## South General Contractors, Inc.

dba Southwestern Roofing 11745 Jones Rd Houston, TX 77070



PO No.

Phone (281) 955-6014

(291) 955-6260 Fax



Date 8/6/2019 Invoice # 95654

Rep

| Bill To  | Ship To  |  |
|--|--|--|
| Chuck Barton<br>10004 Robin St<br>Houston, TX 77068-2728<br>Subdivision: Meadowcrest Sec 2 | Chuck Barton<br>10004 Robin St<br>Houston, TX 77068-2728<br>Subdivision: Meadowcrest Sec 2 |  |

|             |          |   | 10110.       | Кер          |
|-------------|----------|---|--------------|--------------|
|             |          |   | 40007LR      | LR           |
| Item        | Quantity | Description   | Rate         | Amount       |
| (EM)        | 1        | Interior Attic Repairs:   | 0.00         | 0.00         |
| (EM)        | 1        | Use 2" x 6" x 16' Lumber to Brace at Least 7 Rafters that       | 0.00         | 0.00         |
|             |          | Showed Small Gap at Ridge Joint Connection                      |              |              |
| (EM)        | 1        | Split 2" x 6" x 16'. Once Cut, Nail Down next to Existing One   | 0.00         | 0.00         |
|             |          | (Making a Gap at Center Ridge by Pulling Away from it). When    |              |              |
|             |          | Attached to Existing Ones, Added Ones will be Long Enough to    |              |              |
|             |          | Connect and Secure with Ridge Beam. Repeat at Least 5-6         |              |              |
| ( <b></b> ) |          | Times.  |              |              |
| (EM)        | 1        | Install 2" x 4" Perlines in Every Other One for Support         | 0.00         | 0.00         |
| (EM)        | 1        | On Perlins will find a Solid Base Board to Prevent any Damage   | 0.00         | 0.00         |
| (EM)        | 1        | Interior Attic Repairs Cost                                     | 560.00       | 560.00       |
| 625         | 1        | Roof Repair (per Inspection Report):                            | 0.00         | 0.00         |
| (EM)        | 1        | Install 1 1/2" x 1 1/2" Metal Flashing Drip Edge at Both Gables | 0.00         | 0.00         |
|             |          | on Two Story Roof   | 0.00         | 0.00         |
| (EM)        | 1        | Trim Roof Shingles Evenly along Perimeter of Upper Roof once    | 0.00         | 0.00         |
|             | 4        | Drip Edge is Installed  | 0.00         | 0.00         |
| (EM)        | 1        | Remove and Dispose Away Non-Fold Laminated Shingles             | 0.00         | 0.00<br>0.00 |
| (EM)        | 1        | Install over Main Ridge   | 0.00         |              |
| (EM)        | 1        | Use Flexible 3-Tab Composition Shingles                         | 0.00<br>0.00 | 0.00<br>0.00 |
| (EM)        | 1        | Seal (2) Upper Vents and Plumbing Pipes                         | 0.00         | 0.00         |
| (EM)<br>625 | 1        | Seal along Edge of Lower Roof<br>Roof Repair Cost               | 525.00       | 525.00       |
| 025         |          | Rooi Repair Cost  | 525.00       | 525.00       |
|             |          |   |              |              |
|             |          |   |              |              |
|             |          |   |              |              |
|             |          |   |              |              |
|             |          |   |              |              |
|             |          |   |              |              |

Thank you for your business.

**Total Due** 

\$1,085.00

## **Payments Applied** -\$1,085.00

Payment Terms and Conditions:

Please make all checks payable to: South General Contractors, Inc. or Southwestern Roofing.

All debit card and credit card transactions must be pre-authorized by your salesman and are subject to a 4% processing fee. Payment is due upon completion of work.

If you have any questions or concerns, please feel free to contact our office at (281) 955-6014.