

TEXAS ASSOCIATION OF REALTORS®

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2018

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

4523 Shetland Ln

CONCERNING THE PR	ROPE	ERT	Y A	Γ			ŀ	lous	ston	, TX 7	7027-5517			
DATE SIGNED BY SEL	LEF	R AN	ID I	SN	TC	A SI	JBSTITUTE FOR A	NY	INSF	PECTIO	ION OF THE PROPERTY AS ONS OR WARRANTIES THE SELLER'S AGENTS, OR ANY	BU	YER	?
Seller X is is not or	ccup	ying	the	Pro	pert	y. If	unoccupied (by Sellemate date) or nev	er), l	now	long si	ince Seller has occupied the P	rope	erty?	?
Section 1. The Proper				ems	s ma	arke	d below: (Mark Yes	(Y)	, No	(N), o		′ .		
Item	Υ	N	U]	Ite	m		Υ	N	U	Item	Υ	N	U
Cable TV Wiring	Y				Lic	uid	Propane Gas:		X		Pump: sump grinder		X	
Carbon Monoxide Det.		X					mmunity (Captive)		X		Rain Gutters	X		
Ceiling Fans	X						Property		X		Range/Stove	V		
Cooktop	X					t Tu			X		Roof/Attic Vents	X		
Dishwasher	X				Int	erco	m System		X		Sauna		X	
Disposal	X						/ave	X			Smoke Detector	X		
Emergency Escape Ladder(s)		X			Οι	itdoc	or Grill		×		Smoke Detector - Hearing Impaired		X	
Exhaust Fans	X				Pa	tio/D	Decking	X			Spa			
Fences					_	_	ng System				Trash Compactor	X		
Fire Detection Equip.					Po		<u> </u>		X		TV Antenna			
French Drain	X				Po	ol E	quipment		X		Washer/Dryer Hookup	X		
Gas Fixtures	X						laint. Accessories		V		Window Screens		X	
Natural Gas Lines	X				Ро	ol H	eater		X		Public Sewer System	X		
							•							
Item				Υ	N	U			Α	dditio	nal Information			
Central A/C				X				nur	nber	of uni	ts:			
Evaporative Coolers					\times		number of units:							
Wall/Window AC Units					X		number of units:							
Attic Fan(s)					\times		if yes, describe:							
Central Heat				X			1 electric 2 gas number of units:							
Other Heat					\times		if yes, describe:							
Oven				X			number of ovens: electric Z gas other:							
Fireplace & Chimney				X		,	wood 5 gas log	gs_	_ mc	ockc	other:			
Carport					\times		The state of the s		che					
Garage			×			X attached not attached								
Garage Door Openers			X			number of units: number of remotes:								
Satellite Dish & Controls	5			X			★ owned ★ lease		_		CONTRACTOR AND THE STATE OF THE			_
Security System				X			X ownedlease							
Solar Panels					X		ownedlease	d fro	om:					
Water Heater				X			electric X gas		ther:		number of units: 2			
Water Softener				X			Xowned lease	d fro	om:					
Other Leased Items(s)					L	L	if yes, describe:			AV	0			
(TAR-1406) 02-01-18			Initia	led b	ру: В	uyer	: , а	nd S	eller	SK	Pa	ge 1	1 of 5	j

and Seller: 🞾 ^ Coldwell Banker United, REALTORS® - Metropolitan, 2 Greenway Plaza Houston TX 77046 Phone: 713-623-8899 Fax: 713-623-0322 Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com Jeff Dunn

Page 1 of 5 4523 Shetland Ln

				4523 Sh	etla	and Ln	ı		
Concerning the Property at		Houston, TX 77027-5517							
Underground Lawn Sprinkler	X auto	automatic manual areas covered: Entire Yard							
Septic / On-Site Sewer Facility		if yes, a	ttach I	nformation A	Abc	ut On-	Site Sewer Facility (TAR-1407))	
Water supply provided by: X city Was the Property built before 197 (If yes, complete, sign, and at Roof Type: Standing Set Is there an overlay roof covering covering)? yes no unknown Are you (Seller) aware of any of are need of repair? yes no	tach TAR-1906 The Metal The Met	o ur conce perty (s	knowr rning le Age: _ shingle	ead-based p	ain	t hazar	rds). (approximate of the condition of t	xima or r	te) roof
									_
Section 2. Are you (Seller) awa		ects or	malfu	nctions in a	ny	of the	following?: (Mark Yes (Y) if	you	are
Item Y	N Item				Υ	N	Item	Y	N
Basement	Floors					\times	Sidewalks		X
Ceilings		Foundation / Slab(s)					Walls / Fences		5
Doors		Interior Walls				>	Windows		$\overline{\mathbf{x}}$
Driveways		Lighting Fixtures					Other Structural Components		\sum
Electrical Systems								\top	
Exterior Walls		Plumbing Systems Roof						+	\vdash
Section 3. Are you (Seller) awayou are not aware.)	are of any of t	he folk	owing	conditions:	: (1\)	lark Y	es (Y) if you are aware and N	10 (1	4) if
		V	N.	Condition				Υ	N
Condition		Y	N			ındatio	n Banaira	+	
Aluminum Wiring			\Diamond	Previous			n Repairs		
Asbestos Components		_	\Diamond						
Diseased Trees: oak wilt	Proporty	_	\Diamond	Previous Other Structural Repairs Radon Gas				+	S
Endangered Species/Habitat on Property			\rightarrow	Settling	45			+	5
Fault Lines				Soil Movement				+	
Hazardous or Toxic Waste		_	\Diamond	Subsurface Structure or Pits			+		
Improper Drainage							+-		
Intermittent or Weather Springs			\rightarrow	Underground Storage Tanks Unplatted Easements				+	
Landfill Lead-Based Paint or Lead-Based Pt. Hazards			\Diamond	Unrecorded Easements			+	X	
							Insulation	+	5
Encroachments onto the Property				Water Pe			insulation	+	
Improvements encroaching on others' property				Wetlands			rtv	+	*
Located in 100-year Floodplain			X	VVellarius	UI	Tope	i ty		>
(If yes, attach TAR-1414) Located in Floodway (If yes, attached)	sh TAP. 1/1/1	_	\Diamond	Wood Ro	t			+	1
Present Flood Ins. Coverage (If yes, attach TAR-1414)	×			est		f termites or other wood		X	

(TAR-1406) 02-01-18

(If yes, attach TAR-1414)

Located in Historic District

Previous Flooding into the Structures

Previous Flooding onto the Property

Initialed by: Buyer: _

Previous Fires and Seller:

Previous treatment for termites or WDI

Previous termite or WDI damage repaired

Page 2 of 5

4523 Shetland Ln

Concerning the Property at _____

4523 Shetland Ln Houston, TX 77027-5517

Historic Pro	operty Designation		Termite or WDI damage needing repair	
	se of Premises for Manufacture	X	Single Blockable Main Drain in Pool/Hot Tub/Spa*	X
If the answ			ttach additional sheets if necessary):	
	*A single blockable main drain may	, cause a s	suction entrapment hazard for an individual.	
which has necessary)	Are you (Seller) aware of any item, ed not been previously disclosed in the	quipment, is notice?	or system in or on the Property that is in need yes no If yes, explain (attach additional	of repair,
Section 5. not aware.	Room additions, structural modification	s, or other	(Mark Yes (Y) if you are aware. Mark No (N)	
X _	Name of association: Atton C Manager's name: Same Fees or assessments are: \$ Any unpaid fees or assessment for	nce fees o aks C 30 the Proper	r assessments. If yes, complete the following: Phone: per year and are: mandatory	
_ X	with others. If yes, complete the following	ng:	s courts, walkways, or other) co-owned in undividenarged? yes no If yes, describe:	
_ X	Any notices of violations of deed restrict Property.	ctions or go	overnmental ordinances affecting the condition or	use of the
_ X	Any lawsuits or other legal proceedings to: divorce, foreclosure, heirship, bankru		indirectly affecting the Property. (Includes, but is taxes.)	not limited
_ X _ X	Any death on the Property except for the to the condition of the Property.	nose death	s caused by: natural causes, suicide, or accident	unrelated
_ X	Any condition on the Property which ma	terially aff	ects the health or safety of an individual.	
	hazards such as asbestos, radon, lead-	based pair er docume	ntation identifying the extent of the remediation (for	
_ X _ X	Any rainwater harvesting system locate water supply as an auxiliary water source		roperty that is larger than 500 gallons and that use	es a public
_ X			ervice area owned by a propane distribution system	
-X	Any portion of the Property that is locate	ed in a gro	undwater conservation district or a subsidence dis	trict.

(TAR-1406) 02-01-18

Initialed by: Buyer: _____, ___ and Seller: 🔀

Page 3 of 5

Section 3 Explanations:

- 3.a. Flooding: NO FLOODING TO STRUCTURES HAS OCCURRED. Street flooding during extremely large rain events (e.g. Hurricane lke 2008, Hurricane Harvey 2017) resulted in some water encroachment (+/- 10') on to front yard grass near street for brief period but drained quickly.
- 3.b. Previous Roof Repairs: (1) The house was built in 2007, and the first large rain event experienced was Hurricane Ike in 2008. During this storm, the skylights in the master bedroom bathroom and in the second master suite bathroom leaked. This was repaired at the time by sealing the areas around the skylights no further leakage has been observed since. No repairs to the standing seam roof have ever been made or needed. (2) During a buyer's home inspection in March 2019, the ceiling of the patio was discovered to have leaked from the 2nd floor sundeck. The cause of the leak was improperly sealed areas in the flashings that allowed rainwater to leak into the area between the deck floor and the sheetrock ceiling. This was repaired in April 2019 and tested. There was no leakage during the recent Tropical Storm Imelda (September 2019).

 3.c. WDI: Annual termite inspection and treatment every year (2007-18). No insects found. Confirmed during buyer's home inspection in March 2019.

Section 4 Explanations:

- 1) The shower control valve in the downstairs study bathroom must be replaced. These repairs are estimated to cost +/- \$2,000, including sheetrock repair and painting.
- 2) The GFCI outlet in the garage by the water softener, which regulates all the exterior outlets on the house, was tripping after heavy rainstorms. An electrician checked out the circuit and determined that small amounts of water leakage into the exterior outlets was causing this issue. He resealed all outlets in August 2019. During the extended rain of Tropical Storm Imelda (September 2019), the GFCI did not trip. However, subsequently during a wind-driven rainstorm, it did trip once.

4523 Shotland I n

Concerning the Property at	Houston, TX 77027-5517
	n (attach additional sheets if necessary):
Section 6. Seller X has has not attached a survey	
Section 7. Within the last 4 years, have you (Seller) regularly provide inspections and who are either licen inspections? X yes _ no If yes, attach copies and comp	received any written inspection reports from persons who sed as inspectors or otherwise permitted by law to perform plete the following:
Inspection Date Type Name of Insp	
3-19-19 Structural Hedderm	
3-19-19 Mechanical Heddern	10 00 10
5.22, 5.28, 7-8-19 Stucco Hedderm	an Engineering 12.8,12
Property. A buyer should obtain inspe	d reports as a reflection of the current condition of the ctions from inspectors chosen by the buyer.
Section 8. Check any tax exemption(s) which you (Se	ller) currently claim for the Property: Disabled
X Homestead Senior Citizen Wildlife Management Agricultural	Disabled Disabled Veteran
Other:	Unknown
	n for damage to the Property with any insurance
insurance claim or a settlement or award in a legal prowhich the claim was made? Yes no If yes, explain damage in 2008 Hurricane The Repair Slight damage to floor in Living Room enough by Seller to warrant repairs	near glass wall was not deemed severe.
Section 11. Does the Property have working smoke of requirements of Chapter 766 of the Health and Safety (Attach additional sheets if necessary): To the best clarm service professionals from ADT	tof my knowledge as informed by
installed in accordance with the requirements of the buil including performance, location, and power source requestfect in your area, you may check unknown above or contact A buyer may require a seller to install smoke detectors for family who will reside in the dwelling is hearing-impaired.	the hearing impaired if: (1) the buyer or a member of the buyer's l; (2) the buyer gives the seller written evidence of the hearing
impairment from a licensed physician; and (3) within 10 do the seller to install smoke detectors for the hearing-impa agree who will bear the cost of installing the smoke detect	ays after the effective date, the buyer makes a written request for ired and specifies the locations for installation. The parties may ors and which brand of smoke detectors to install.
Seller acknowledges that the statements in this notice are the broker(s), has instructed or influenced Seller to provide 10-10-19	e true to the best of Seller's belief and that no person, including e inaccurate information or to omit any material information.
Signature of Seller Dat	e Signature of Seller Date
Printed Name: Stephen R. Locke	Printed Name:
(TAR-1406) 02-01-18 Initialed by: Buyer:	, and Seller: , Page 4 of 5

ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit www.txdps.state.tx.us. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review *Information Regarding Windstorm and Hail Insurance for Certain Properties* (TAR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.


(6)	The foll	lowing	providers	currently	provide	service	to the	Property:
-----	----------	--------	-----------	-----------	---------	---------	--------	-----------

Electric:	Reliant	phone #: _	713-488-3667
Sewer:	City of Houston	phone #:	713-371-1400
Water:	15 / 10	phone #:	
Cable:	Comcast	phone #: _	800-93A-LA89
Trash:	Incl in HOA Fees	phone #:	
Natural Gas:	Centerpoint	phone #:	713-659-2111
Phone Company:	Comcast	phone #:	800-934-6489
Propane:	NA	phone #:	
Internet:	Comcast	phone #:	800 - 934 - 6489
Internet.	Content	priorio	

(7) This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

The undersigned Buyer acknowledges receipt of the foregoing notice.

Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	



SURVEY REVISED: October 29, 2018 to reflect current platting information. (No field work was performed

NOTES:

- Surveyor has not obstracted this property. This survey has been prepared based upon information provided by the title company. No independent investigation of the accuracy of the title company's work has been performed by the surveyor. Zoning ordinances and zoning building settlack thes (if any) are not shown. Surveyor has not reviewed restrictive covenants as set forth under Emoptions
 From Coverage in Schoolde B of the Title Commitment.
- Lot may be subject to certain requirements pertaining to front, side and rear satisack thes and also architectural profusions such as caves, overhangs, ledges, etc., in relation to easements entire building lines and should be writted prior to any planning or construction.
- 3. Pipeline Easement to Humble Pipe Line Company as recorded in Volume 562, page 140, Volume 603, Page 140, and Volume 691, Page 150 of the Deed Records of Harris County Tours, (unable to locate)
- 4. All bearings are based on the South right of way line of Shettand Lone. (N 87° 41' 33° E)

PLAT OF PROPERTY STEPHEN R. LOCKE FOR: 4523 SHETLAND LANE - HOUSTON, TX LGL: LOT 2, BLOCK 1 AFTON OAKS SECTION 1, PARTIAL REPLAT NO. 1 FILM CODE No. 686626 OF THE MAP RECORDS OF MARRIS COUNTY, TEXAS SCALE: REVISED DATE: 6/29/2018 DATE: 6/21/2018 This Property DOES HOT Lie within the designated 100 year Fit 48201C 0885 L PANEL NO: X (UNSHADED) EFF. DATE: ZONE: N/A (100 YR) | N/A (500 YR) BASE FLOOD ELEVATION: LOCATED BY GRAPHIC PLOTTING GRLY AND NOT RESPONSIBLE FOR ACTUAL DETERM

THIS SURVEY WAS PERFORMED IN ACCORDANCE WITH TITLE COMMITMENT PROVIDED BY: ABSTRACT SERVICES OF HOUSTON

CPL 7910-18-3546 (0/21/2018)

EMAIL COPY

NOT TO BE REGORDED FOR ANY PURPOSE

JOB # 686-U59 DRAWN BY: MTM / MFC / DL

This survey is the property of prosoffeld a associates, Inc., is certified for this transaction cally, and is not transferable to additional institutions or carreds