



McCRORY ENGINEERING, INC.

May 29, 1998
Job #12197

Precision Foundation Services, Inc.
8427 Hammerly Blvd.
Houston, Texas 77055

FOUNDATION REPAIR CERTIFICATE OF INSPECTION


**#29 Winter Haven
Bentwater Area
Montgomery, Texas**

CERTIFICATION


I HEREBY CERTIFY that I personally reviewed the foundation repair pier locations shown on the attached drawing, and inspected the bell bottom pier holes at #29 Winter Haven in the Bentwater Area in Montgomery, Texas. All pier holes were judged to be located and prepared according to specifications.

I FURTHER CERTIFY that the findings and conclusions contained in this report have been, to the best of my knowledge, correctly and completely stated without bias, and are based upon my observations and experience. No responsibility is assumed for the events that occur after the inspection and submission of this report and no warranty, either expressed or implied, is made.

CERTIFIED THIS 29TH DAY OF MAY 1998.



E. Don McCrory, Jr.
Registration No. 36647






SINCE 1972

PRECISION FOUNDATION SERVICE, INC.
8427 HAMMERLY BLVD. HOUSTON, TEXAS 77055
(713) 973-0114 FAX: (713) 973-2168

STORIES 1 1.5 2 2.5 3 Other _____
FOUNDATION S/R P/T B&S P&B Other _____
VENEER: B/V W/S Alum. Other _____
LOT TYPE: S/D Ø T/H Other _____

NUMBER OF BREAK OUTS: _____
TYPE: P/G _____ OTHER: _____
DIRT: _____ P/B's _____
LIFT: _____ ADJ's _____

NAME Howard & Barbara Andrew HOME _____ HIS WORK _____
ADDRESS #29 Winter Haven KEY MAP MOUNT. Co. HER WORK _____
CITY MOUNTGOMERY, TX (BENTWATER) # HOLES 18



NOTES: _____

●	Proposed Exterior Pier	—	Slab Crack
●	Proposed Interior Pier	—	Brick Veneer Crack
●	Existing Exterior Pier	—	Separation @ Door/Window
●	Existing Interior Pier	—	URETEK Injections

