

Mr. Robert Hess



Front of house facing west.



Breakers not labeled in service panel.



Brick veneer crack on south side of house.



Two carports in back yard.



Back wall not sealed under south bathroom lavatory.



Water heater in laundry room.



Water heater T&P line reduced in size and uphill.



Furnace in attic.

1806 10th Street - Hempstead 77445