



LOFLIN ENVIRONMENTAL SERVICES, INC.

October 10, 2017

1206 Eversham Way
Kingwood, TX 77339

Attention: Mr. Craig Stevens

Subject: Report of Post Flood Mold Assessment
1206 Eversham Way - Kingwood, TX
Loflin Environmental Services Project No. 100-17-225

Dear Mr. Stevens,

Loflin Environmental Services, Inc. (**LOFLIN**) has completed a limited mold assessment at the above referenced residence. The purpose of this work was to assess mold growth within the ground floor of the house affected by flooding from Hurricane Harvey. This work was performed on October 7, 2017.

The house was visually inspected to identify suspect mold contamination due to flooding. It was reported that approximately 36 inches of water had entered the house. At the time of the assessment, all wall gypsumboard had been removed. All flooring along with wood components including cabinets and shelving had also been removed. Visual inspection revealed no mold growth on exposed wood framing or remaining wallboard.

Moisture readings were taken at exposed wood studs and sill plates. No wood framing with elevated moisture content was identified.

Based on visual inspection and moisture testing, there was no identified mold growth or conditions leading to future mold growth related to the flooding event.

Attached please find the Certificate of Mold Damage Remediation.

Loflin Environmental Services, Inc. appreciates this opportunity to provide these testing services. Should you have any further questions regarding this matter, please do not hesitate to contact us.

Sincerely,
Loflin Environmental Services, Inc.



James Murray, CIH, CSP
MAC0143