4106 Turnberry Circle, Houston TX 77025-1715 Upgrades (page 1 of 2)

| Date | Cost | Provider | Description |
|-------------------|-----------------|--|---|
| January 5, 2016 | \$ 1,403.00 | Wedgeworth Plumbing 832-867-5309 | Replace water heater |
| January 14, 2016 | \$ 3,706.00 | Window World 866-946-3189 | Remove nine windows, replace with double-hung windows, and clean up afterwards. Includes all inclusive transferable lifetime warranty. Three in master bedroom One in master bathroom Three in living room Two in breakfast area |
| | | | Install eleven pairs of window shutters on all large windows on south and west sides of the house. |
| February 18, 2016 | \$ 608.00 | Houston Wholesale Blinds 713-304-2497 | Install six new blinds: one on mud room door, one each on left and right patio doors, one in master bathroom, and two in bedroom that looks out to the back yard |
| June 14, 2016 | \$ 9,100.00 | Fuller-Services, Inc. 281-477-0013 | Mud Room: remove all cabinetry and replace with design supplied by homeowner |
| June 14, 2016 | \$ 5,200.00 | Fuller-Services, Inc. 281-477-0013 | Living Room: reconfigure bookshelves and cabinets on both sides of the fireplace. Replace existing counter tops with granite counter tops. |
| June 14, 2016 | \$ 950.00 | Fuller-Services, Inc. 281-477-0013 | Coat closet in foyer: remove existing and replace with better quality clothes rod and shelf |
| June 14, 2016 | \$ 1,075.00 | Fuller-Services, Inc. 281-477-0013 | Butler Pantry off formal dining room: reconfigure to have solid shelves on all sides |
| June 14, 2016 | \$ 1,750.00 | Fuller-Services, Inc. 281-477-0013 | Bedroom #2 (ensuite) Closet: reconfigure as discussed with upgraded materials |
| June 14, 2016 | \$ 1,750.00 | Fuller-Services, Inc. 281-477-0013 | Bedroom #2 (ensuite) Bath: remove counter top and sink. Install sink, faucet, granite counter tops, and backsplash |
| June 14, 2016 | \$ 1,750.00 | Fuller-Services, Inc. 281-477-0013 | Bedroom #3 Closet: reconfigure as discussed with upgraded materials |
| June 14, 2016 | \$ 1,750.00 | Fuller-Services, Inc. 281-477-0013 | Bedroom #3 Bath: remove counter top and sink. Install sink, faucet, granite counter tops, and backsplash |
| June 14, 2016 | \$ 650.00 | Fuller-Services, Inc. 281-477-0013 | Bedroom #4 Closet: reconfigure as discussed with upgraded materials |
| June 14, 2016 | \$ 2,450.00 | Fuller-Services, Inc. 281-477-0013 | Bedroom #4 Bath: remove counter top and sink. Install sink, faucet, granite counter tops, and backsplash |
| June 14, 2016 | \$ 19,500.00 | Fuller-Services, Inc. 281-477-0013 | Master Closet: reconfigure with design supplied by homeowner. Include small vent to supply heating and air conditioning. |
| June 14, 2016 | \$ 11,500.00 | Fuller-Services, Inc. 281-477-0013 | Master Bathroom: remove all counter tops and cabinets. Remove wallpaper, light fixtures, mirrors, and medicine cabinets. Paint entire master bath. Install new cabinets, sinks, faucets, light fixtures, power outlets, and granite counter tops and backsplashes per design supplied by homeowner. |

4106 Turnberry Circle, Houston TX 77025-1715 Upgrades (page 2 of 2)

| Date | | Cost | Provider | Description |
|-------------------|------|-----------|---------------------------------------|---|
| June 14, 2016 | \$ | 1,250.00 | Fuller-Services, Inc. 281-477-0013 | Living Room Hidden Wiring: Install cable from TV area to HD antenna in the attic. Install new plug behind TV above fireplace, communication tube from right cabinet to TV area. Repair walls when completed. |
| June 14, 2016 | \$ | 450.00 | Fuller-Services, Inc. 281-477-0013 | Paint bathrooms (except Master Bathroom which is covered elsewhere) |
| June 14, 2016 | \$ | 2,125.00 | Fuller-Services, Inc. 281-477-0013 | Remove mirrors in all upstairs bathrooms. Install five larger mirrors: two in master bathroom, and one in the three remaining bathrooms. |
| June 14, 2016 | \$ | 600.00 | Fuller-Services, Inc. 281-477-0013 | Roof: Inspect roof and repair exposed nails as needed. Shingle all vents (approximately 18) as needed. Seal and paint all penetrations, plumbing vents, hawk vents, HVAC and heater vents. |
| December 15, 2016 | \$ | 2,500.00 | Fuller-Services, Inc. 281-477-0013 | Paint all kitchen cabinets. |
| December 15, 2016 | \$ | 650.00 | Fuller-Services, Inc. 281-477-0013 | Remove trash compactor and install new cabinet. |
| December 15, 2016 | \$ | 1,150.00 | Fuller-Services, Inc. 281-477-0013 | Paint over all yellow walls SW7671 including Washer and Dryer area |
| December 15, 2016 | \$ | 650.00 | Fuller-Services, Inc. 281-477-0013 | Paint Hollywood bathrooms SW1015 |
| December 15, 2016 | \$ | 350.00 | Fuller-Services, Inc. 281-477-0013 | Install blocks and panel above all kitchen cabinets to make flat |
| December 15, 2016 | \$ | 350.00 | Fuller-Services, Inc. 281-477-0013 | Touch up several areas of the trim and doors. |
| December 15, 2016 | \$ | 275.00 | Fuller-Services, Inc. 281-477-0013 | Install washer pan |
| December 15, 2016 | \$ | 25.00 | Fuller-Services, Inc. 281-477-0013 | Cover old hinge recesses from mud room door (note: door is stored in garage) |
| December 15, 2016 | \$ | 375.00 | Fuller-Services, Inc. 281-477-0013 | Power wash concrete |
| July 27, 2017 | \$ | 14,600.00 | H-Town Services 832-404-2062 | Replace air conditioners. New units are 16 SEER 3 ton. New drain pan with float switch, new supply plenum, media air filter 16x25x5 with return can. New 'Nest' thermostats. Warranties: 10 years parts and 2 years labor. |
| April 12, 2018 | \$ | 130.00 | H-Town Services 832-404-2062 | Install damper in ductwork to control air flow to ensuite bedroom |
| March 2, 2019 | \$ | 974.24 | Best Buy | New dishwasher: KitchenAid 24" model KDTE334GPS and SKU #6005004. Color: stainless steel. Noise level: 39 decibels (among the quietest in the industry!). Since the power outlet for the garbage disposal is behind the dishwasher, I plugged an extension cord into the outlet and ran it to the garbage disposal unit before the new dishwasher was installed. |
| November 2019 | \$ | 700.00 | A-Bald Garage Door 281-701-0207 | Garage door repair: replace broken overhead spring, adjust new spring and cables, lubricate all wheels and wheel guides. |
| TOTAL | \$ 9 | 90,296.24 | | |