

11.40 08"42"32" THE ARBORS AT GLEANNLOCH AMENDING PLAT NO. 1

75.00 C1

N 49°58'35" W

STATE HARRIS F.C. NO. 617240, H.C.P.R. LENDER CO. DHI TITLE COMPANY 150-120200923-201 19646 CANDLEWOOD OAKS LANE

© COPYRIGHT 2012 WINDROSE LAND SERVICES, INC. ALL RIGHTS RESERVED.

FIELD WORK	07-14-12	DB
DRAFTED BY	07-16-12	CL
CHECKED BY	07-16-12	18
KEY MAP NO.	329C	
	REVISION	
-	-	
-	-	

5758

I do hereby certify for this transaction only, that this survey under my supervision was this day made on the ground and that this plat correctly represents the property legally described hereon (or on attached sheet). That the facts found at the time of this survey show the improvements and that there are no visible encroachments apparent on the ground, except as shown, to the best of my knowledge.

Windrose Land Services, Inc. 3200 Wilcrest Drive, Suite 325 Houston, Texas 77042 Phone (713) 458-2282 Fax (713) 461-1151

Professional Development Consultants Land Surveying, Platting, Project Management, GIS Services