

THIS PROPERTY DOES NOT LIE WITHIN THE 100 YEAR FLOOD PLAIN AS PER FIRM LINC. 48157C 0105 J
MAP REVISION: 01/03/97
ZONE X

BASED ONLY ON VISUAL EXAMINATION OF MAPS. INACCURACIES OF FEMA MAPS PREVENT EXACT DETERMINATION WITHOUT DETAILED FIELD STUDY


A SUBSURFACE INVESTIGATION WAS BEYOND THE SCOPE OF THIS SURVEY


RECORD BEARING: SLIDE NO. 1474/A AND 1474/B

DRAWN BY: AL

BILLIE G. MCDUFFIE PROFESSIONAL LAND S NO. 2090 JOB NO. 09—00536 JANUARY 22, 2009 HEREBY CERTIFY THAT THIS SURVEY MAS MADE IN THE GROUND, THAT THIS PLAT CORRECTLY PRESENTS THE FACTS FOUND AT THE ACTS FOUND AT THE ACTS FOUND, THE FACTS APPARENT ON THE GROUND, CEPT AS SHOWN HEEGON, THIS SURVEY IS RITHED FOR THIS TRANSACTION ONLY AND ISTRACTING PROVIDED IN THE ABOVE FERENCED THE COMMINANT MAS RELIED FOR THE COMMINANT MAS RELIED FOR THE COMMINANT MAS RELIED FOR IN THE FACTOR FACILITY OF THIS SURVEY. SURVEYOR







RECISIONINC

 ∇ URVEYORS

1-800-LANDSURVEY 1-800-526-3787 14925 MEMORIAL DRIVE SUITE B

B100 HOUSTON, TEXAS 77079