

Hurricane Harvey
Attachment for the property located at:
2951 Kings Forest Drive, Houston, TX 77339

1. Prior to August 2017, the seller had knowledge of the property flooding: Yes No
If Yes, when did the property flood previously? _____
-
2. The recent floodwater did or did not enter the improvements.
3. During the week of August 28, 2017, the interior experienced approximately 19 inches of floodwater.
4. The seller was able to enter the property and begin repairs on August 30 2017.
5. The sheetrock and insulation was removed up to approximately 4 feet.
6. All of the lower cabinets were removed: Yes No
7. The following items were also removed: Door Trim Door jambs Window seal/casement
 Electrical outlets Cable/Phone outlets Fireplace insert
Other: _____
8. The following flooring was removed: Carpet Laminate Wood Tile
9. After removal, the following product(s) was applied to the structure:
2 coats Concrobium , 2 coats Shockwave RTU
10. Additional moisture was removed by the following process: dehumidifiers , high velocity fans and completed on: dried until October 31, 2017
11. Prior to replacing the sheetrock what, if any, tests were performed: moisture meter was at acceptable level before new insulation + sheetrock Reports attached? Yes No
12. The exterior HVAC system was replaced or serviced: Yes No, House generator: Yes No
13. The damaged moisture barrier between the exterior siding/brick was removed and replaced Yes No
14. The following pool equipment, pool surfaces, and outdoor kitchen equipment were replaced: N/A

15. The following contractors provided services above:
Receipts/Invoices Attached Yes No Pictures Attached Yes No
- Seller Initials [Signature] Seller's Initials [Signature] Buyer's Initials Buyer's Initials

This information is provided in addition to and in furtherance of Sellers' prior disclosures. These additional disclosures are not intended as a guaranty or additional warranty, and their specificity is not intended to create additional liability on the part of Sellers. Buyers are cautioned to obtain additional inspections to assure themselves that the Property is free from moisture and the damage commonly associated with a flood event.