




INFRARED THERMOGRAPHIC CERTIFICATION

Issued to: Trendmaker Homes
Address: 27610 Riata Hills Ln.
Date: 7/30/2013

An independent, certified and bonded Your Home Check thermographer has scanned the following areas of the home with infrared equipment:

- Interior walls and ceilings have been scanned for water leaks and excessive heat from electrical wiring. No relevant problems were found.
- All electrical devices including outlets, switches, fixtures and main electrical panel, have been scanned. No excessive heat was detected from any electrical devices.
- Insulation within walls, ceilings and attic was found to be present and properly installed.
- All windows and doors were scanned with no excessive thermal leaks found.
- Attic ductwork was scanned for leaks and no sufficient air loss was detected.
- Attic decking was scanned for roof leaks and no leaks were found.
- A/C condensers were scanned for Freon leaks. No leaks were detected (weather permitting).



Infrared picture of your home's interior wall.