From: Sent: To: Loreen Wells Subject: Fwd: Coastal Hankla A/C & Heat - Invoice #LM1020 ----- Forwarded message ------From: Coastal Hankla A/C & Heat <no-reply@pictureperfectpricing.com> Coastal Hankla A/C & Heat × License No. TACLB11627E 8001 Underwood Dr. Missouri City, TX 77459 Phone: 281-980-1616 Email: coastalair.P3@gmail.com URL: www.coastalairandheat.com INVOICE **PAID IN FULL** Date: October 19, 2020 Invoice: Thank you Here is a copy of your invoice. If you have any questions please feel free to contact us.

Thank you for your business!

Coastal Hankla A/C & Heat

Customer Information

Service Address

3515 Summit Lane
Missouri City, TX 77459-4042

## **Invoice Summary**

Amount	Terms	Amount Paid	Amount Owed	Service Agreement Member?	Service Agreement Missed Savings
\$156.00	Due on Receipt	\$156.00	\$0.00	No	\$0.00

## **Invoice Details**

				<b>Price Options</b>	
TaskID	Description	System	Qty	Preferred Customer	Amount
LM1020-1	Heat inspection performed, no carbon monoxide was detected and the system is heating and operating properly at this time.	System 1	1	\$89.00	\$89.00
LM1020-2	Fixed the pitch on the ventilation pipe and cleared all debris from secondary drain pan.	System 1	1	\$67.00	\$67.00
Customer Notes		No Diagnostic Fee Notes : A/c inspection completed. System is cooling and operating properly at this time.		\$0.00	\$0.00
			Total Amount	\$156.00	\$156.00

# **Payment History**

Date	Payment Method	Payment Made By	Comment / Notes	Amount
Oct 19, 2020	Payment - Other		Office to collect credit card	\$156.00
			Total Payment Received	\$156.00

## **Equipment & Diagnostics**

# <u>Diagnostics</u>

LM1044, LM1045, LM1046

#### **Evaporator Coil**

Trane

TXH054A4HPAF

5353JJ77H

#### **Furnace**

Trane

TUD100R9V5K4

5454Y691G


## A/C - Condenser

Trane


4TTX4048B1000AA

5204M6P2F

#### **Affiliations**









#### **Terms and Conditions**

### Customer Signature (Work Authorize)



I have the authority to order the above described work. It is agreed that the seller will retain title to any equipment or material furnished until full and complete payment is made, and if settlement is not made as agreed, the seller shall have the right to remove same and the seller shall be held harmless for damages resulting form the removal thereof. If this invoice is not paid within 30 days, I agree to pay 1 1/2% per month (18% annual rate) or the maximum allowed in the state of residence on the unpaid balance. If this invoice is placed for collection I agree to pay seller's attorney fees and any court costs.

# Customer Signature (Work Completed)



All work has been completed to my satisfaction.

#### LIMITED WARRANTY:

All materials, parts and equipment are warranted by the manufacturers' and suppliers' written warranty only. All labor performed by the above named company is warranted for 6 months or as otherwise indicated in writing. The above named company makes no other warranties, express or implied, and its agents or technicians are not authorized to make any such warranties on behalf of above named company.

Regulated by the Texas Department of Licensing & Regulation P.O. Box 12157
Austin, Texas 78711
1-800-803-9212 / 1-512-463-6599
www.tdlr.texas.gov

License# TACLB011627E



October 12, 2020

Subject Property: 3515 Summit Lane, Sugar Land, TX 77459

Jericho Foundation Repairs was founded upon a belief that honesty, integrity and hard work would help establish and build a good reputation for our company. We are proud to confirm that after over 30 years of doing business in the greater Houston area and Fort Bend County, people call Jericho because they trust us.

Many times we visit homes that do not warrant foundation repair procedures. Such was the case when I visited the subject property. Elevations were taken and very little sloping or movement was noted at the residence.

It is my professional opinion that foundation repair or underpinning is not necessary at this time. This opinion would not be applicable to future changing conditions, as no accurate prediction can be made of future movement. If the evidence and the consequences of foundation movement become significantly more pronounced, repairs may become necessary. It is always helpful to water your foundation, especially during periods of extreme dryness like we are currently experiencing.


This can be accomplished by using soaker hoses placed around the perimeter of the structure, at least 6 inches from the slab. We recommend watering at least 30 minutes per day during dry months. It is most efficient to water either early in the morning or late in the evening as the water tends to evaporate so quickly during the highest temperatures of the day. At this time, please make sure to take into account the water restrictions currently in your area. You may also purchase timers to help make it a little easier on yourself. The hoses and timers may be purchased at Home Depot, Lowes, or your local hardware store.

Should you have any questions, please give me a call.

Sincerely,







KEY MAP 6091

From: HERNDON MUNCEY INC <herndon\_muncey@msn.com>

**Sent:** Friday, September 25, 2020 9:46 AM

To:

**Subject:** [EXTERNAL] 5311N197V

**Attachments:** hr25368.pdf

## Please see the attached.

Geneva Martens Herndon/Muncey, Inc. P O Box 218941 Houston TX 77218 (281) 579-0515 Herndon\_muncey@msn.com



Office (281) 579-0515

Fax (281) 579-1960

September 25, 2020

# **INVOICE NO.:**



RE: 3515 Summit Drive Missouri City TX 77459 5311N197V

## TIN: 76-0462307

1	STATIC TEST	\$175.00
1	HYDROSTATIC TEST	\$125.00
1	ABOVE GRADE PLUMBING INSPECTION	\$150.00
	SUB-TOTAL	\$ 450.00
	SALES TAX	\$ 37.13
	TOTAL DUE	\$ 487.13

MASTER PLUMBER – DENNIS THIBODAUX - MASTER PLUMBING LICENSE # M-16447
REGULATED BY THE TEXAS STATE BOARD OF PLUMBING EXAMINERS
919 EAST 41ST STREET - P. O. BOX 4200
AUSTIN, TEXAS 78765 - 512/458-2145 - FAX 512/450-0637 - 1-800-845-6584

P. O. BOX 218941, HOUSTON, TEXAS 77218-8941 LEAK DETECTION – HYDROSTATIC – FLOW TEST



Office (281) 579-0515

Fax (281) 579-1960

September 25, 2020

OUR JOB #



RE: 3515 Summit Drive Missouri City TX 77459 5311N197V

### **SUMMARY**

The test revealed no under-slab or above-grade plumbing leaks.

The following tests were performed on the plumbing system at the above referenced residence. The scheduled test was on September 24, 2020 and began at 9:00 AM. The structure is approximately (45) forty--five years old. There is one (1) exit from the structure, and a cleanout was available. The AC Condensate Drain is located at the tub in Bath #2 as per our drawing.


## STATIC TEST

A (30) thirty minute test revealed no loss of water. The ABS piping is in fair condition.

### **HYDROSTATIC TEST**

The test revealed no loss of pressure (60 psi) in a (30) thirty minute period. The galvanized piping is routed overhead and is in fair condition.

# HERNDON/MUNCEY, INC.




### **ABOVE GRADE PLUMBING INSPECTION**


The Above Grade Plumbing Inspection revealed **no above grade plumbing leaks.** This report includes only active above grade plumbing leaks and does not include any previous leaks.

• We splashed water at the tub in Bath #2 and observed small amount of water leaking at the spout and at the escutcheon for the valves. These need to be caulked.

Drawings are for bid purposes only and are not intended to be used to locate drain lines in their exact locations.



Drawings are for bid purposes only and are not intended to be used to locate drain lines in their exact locations.







Photograph #2



Photograph #3




Photograph #4



Photograph #5



Photograph #6



Photograph #11 Photograph #12



#### Callen Roofing, Inc.

3515 Summ Ln M ssour C y, TX 77459



EST MATE #2463
EST MATE DATE Oc 15, 2020
SCHEDULED DATE Thu Oc 15, 2020
8:00am

TOTAL \$0.00

**CONTACT US** 

P.O. Box 713 Ka y, TX 77492

(281) 391-8257

ca enroof ng@ca enroof ng.com

#### **ESTIMATE**

Serv ces amoun

#### TD - 609L - ROOF INSPECTION

Af er nspec ng he roof, he roof s n good and serv ceab e cond on. No ssues found and no repars a hs me. Roof should as 5 p us years.

Total \$0.00

- \*Moun ng Sa e e d shes on he roof n no recommended. They w be re ns a ed n he same p ace and adjus men s may be needed by your prov der a he cus omers expense.
- \*Due o excess ve v bra ons, we recommend ha a wa f x ures be removed.
- \*Ca en Roofing, Inc. will no be responsible for air conditioning lines, waler lines, or electrical nesies haid!" below the roof decking.

Add ona charges may be required because of fac orsid scovered during the process of the work or the effects of the work being performed. Such tems not ude without more at a on (1) with fashing insiation, wood replacement and/or pain to ouch up, (2) with vibrations during work, and (3) shee rock repair or replacement.

- \*SEE TERMS AND CONDITIONS BELOW FOR IMPORTANT LEGAL INFORMATION.
- \*If he unders gned fa s o pay Ca en Roof ng, Inc. any amoun s due under h s con rac whn hry (30) days from he dae of compeed, he unders gned agrees o pay a cossof coec on pusa reasonabe a orney's fee shoud he same be paced nhe hand of and a orney, a ong whe egh percen (8%) neres on unpad baance.
- \*IMPORTANT NOTICE: You and your con rac or are respons be for mee ng he erms and cond ons of hs con rac. If you sign hs con rac and you fa o mee he erms and cond ons of hs con rac, you may ose your ega ownership rights in your home. KNOW YOUR RIG TS AND DUTIES UNDER TIELAW.
- \*YOU MAY CANCEL T IS OFFER BEFORE ANY WORK IS STARTED, WIT OUT PENALTY OR OBLIGATION WIT IN T REE (3) BUSINESS DAYS FORM T E ACCEPTANCE DATE.