



THIS PROPERTY DOES NOT LIE WITHIN THE 100 YEAR FLOOD PLAIN PER THE FLOOD INSURANCE RATE MAP COMMUNITY PANEL NUMBER 48010C0225 G REVISED DATE: SEPTEMBER 28, 1990. (ZONE "X")

CABLE T.V. SERVICE AGREEMENT AS RECORDED IN H.C.C.F. NO. R-977030

T.E. & P. AGREEMENT FOR UNDERGROUND ELECTRIC SERVICE AS RECORDED IN H.C.C.F. NO. J-67252.



PLAT of SURVEY
 LOT 49 BLOCK II
 REPLAT
 BARKERS RIDGE SUBDIVISION,
 SECTION TWO
 HARRIS COUNTY, TEXAS
 FILM CODE NO. 347130 H.C.M.R.

PURCHASER: REGINALD B. BEATY
 ADDRESS: 18538 IRON LAKE DRIVE
 PULTE HOME CORP.

Reginald B. Beaty
Deed of Plat

HEREBY CERTIFY THAT THIS SURVEY WAS MADE ON THE GROUND UNDER MY SUPERVISION AND THAT THIS PLAT CORRECTLY REPRESENTS THE FACTS AS FOUND AT THE TIME OF THIS SURVEY.
Harry Taplin, Jr.

TE TAPLIN ENGINEERING, INC.
 ENGINEERS - SURVEYORS
 11331624642 & 50 / 31670100-ANNEYTON, TX 77021
 (713) 196-8496 FAX (713) 496-8498

SCALE: 1" = 20'
 PLAN NO.: 24229