Stockton House Updates (1-7-21)

- 1. Carpet in 3 upstairs bedrooms installed 2015
- 2. Sprinkler System Front 2013
- 3. Sprinkler System Back 2019
- 4. Pool Re-plastered 2019
- 5. Gulf Coast Windows 2019
- Exterior A/C Units Replaced
 Downstairs Exterior Unit (Unit in front and closest to street)
 Replaced July 2015

Upstairs Exterior Unit – Replaced April 2017

- 7. Downstairs furnace system replaced May 2017
- 8. Upstairs Furnace System Replaced December 2015
- 9. New Attic Insulation installed 2019
- 10. New Garage Door Opener March 2019
- 11. Roof Replaced 2006
- 12. Ceiling Fans replaced throughout entire house with the exception of three upstairs bedrooms 2017
- 13. Ceiling fans replaced in three upstairs bedrooms 2020

Stockton Updates (continued)

- 14. New Smoke Detectors/Carbon Monoxide Detectors 2020
- 15. Gameroom Carpet installed 2017
- 16. Replaced patio door 2017
- 17. Replaced big garage door 2017
- 18. Replaced door from garage to laundry room 2017
- 19. Completely remodeled kitchen 2017
- 20. Remodeled half bath 2017
- 21. Replaced exterior door at garage bath 2020
- 22. Complete master bath remodel 2017
- 23. Wood floors 2008
- 24. Carpet in Living Room and Study 2012
- 25. New roof on patio cover 2020
- 26. Ceiling fans at patio cover 2020
- 27. Exterior repainted 2020
- 28. Majority of interior repainted -2020