

- 3) FLOOD ZONE DETERMINED BY GRAPHIC PLOTTING ONLY. WE DO NOT ASSUME RESPONSIBILITY FOR EXACT DETERMINATION.
- 4) SUBJECT TO RESTRICTIVE COVENANTS BY DOCUMENT NOS. 2007-062057, 2007-070513, 2007-070514, 2007-140454, 2009-095224, 2010100251, 2011111921, 2011115012, AND 2011115013, AND IN CAB. Z, SHEETS 2205-2206, M.C.M.R.
- 5) THE SUBJECT PROPERTY LIES WITHIN MONGTGOMERY COUNTY M.U.D. NO. 112.
- 6) THIS SURVEY IS VALID ONLY WITH ORIGINAL SIGNATURE IN BLUE INK.
- 9) FENCE LOCATIONS SHOWN HEREON ARE FROM APPROXIMATE CENTER & ARE SUBJECT TO CHANGE DUE TO ENVIRONMENTAL CONDITIONS, WARPING, LEANING, CHANGES FROM RECONSTRUCTION, ETC. FENCES MAY MEANDER BETWEEN MEASURED LOCATIONS.

CURVE	RADIUS	DELTA	ARC	BEARING	CHORD
C1	150.00'	17*53'57"	46.86'	S 77*26'04" W	46.67'

7) THIS SURVEY IS NOT FOR FUTURE CONSTRUCTION PURPOSES BUYER'S ACKNOWLEDGMENT \_ SUBDIVISION FLOOD NOTE BLOCK SECTION ACCORDING TO THE FEDERAL EMERGENCY MANAGEMENT AGENCY (FEMA) FLOOD INSUBANCE RATE MAP (FIRM) FOR MONTGOMERY COUNTY, TEXAS MAP NO. 483326 0350F, DATED DECEMBER 19, 1996. THE SUBJECT TRACT APPEARS TO LIE WITHIN UNSHADED ZONE "X". THIS DETERMINATION WAS DONE BY GRAPHIC PLOTTING AND IS APPROXIMATE ONLY AND HAS NOT BEEN FIELD VERIFIED. THIS FLOOD STATEMENT DOES NOT IMPET THAT THE PROPERTY OR STRUCTURES THEREON OF THE ACT OF THE PROPERTY OR STRUCTURES THEREON OF THE ACT OF THE PROPERTY OR STRUCTURES THEREON OF THE ACT OF THE PROPERTY OR STRUCTURES THEREON OF THE ACT OF THE PROPERTY OF STRUCTURES THEREON OF THE ACT OF THE PROPERTY OF STRUCTURES THEREON OF THE ACT OF THE PROPERTY OF STRUCTURES THEREON OF THE ACT OF THE PROPERTY OF TH THE MEADOWS AT JACOBS RESERVE RECORDATION COUNTY STATE SURVEY A170 TEXAS CAB. Z. SHEETS 2205-2206 M.C.M.R. MONTGOMERY LENDER CO. TITLE CO. DHI TITLE COMPANY JOB NO. PURCHASER 48924 123 FIELDS VIEW COURT I do hereby certify for this transaction only, that this survey under my supervision was this day made on the ground and that this plot correctly represents the property legally described hereon (or on attached sheet). That the facts found at the survey show the improvements and that there are no visible encreachments apparent on the ground, except as shown, to the best of my knowledge. OF C COPYRIGHT 2013 WINDROSE LAND GLEN H FREEL SERVICES, INC. ALL RIGHTS RESERVED 5758 ESSIO FIELD WORK 04-01-13 SURVE DRAFTED BY EC CHECKED BY 04-02-13 JB Windrose Land Services, Inc. KEY MAP NO. 217 A/B 3200 Wilcrest Drive, Suite 325 Houston, Texas 77042 REVISION Phone (713) 458-2282 Fax (713) 461-1151 Professional Development Consultants

Land Surveying, Platting, Project Management, GIS Services