

UPDATE TO SELLER'S DISCLOSURE NOTICE

USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS®, INC. IS NOT AUTHORIZED. ©Texas Association of REALTORS®, Inc. 2018

UPDATE TO THE SELLER'S DIS 50 N Westwinds Cir	SCLOSURE NOTICE	CONCERNING THE PROPERTY AT	
Seller is aware of the following neare changed to read (cite specific any necessary changes): Section 3	c sections and copy tr	ng the condition of the Property. Sect ne applicable language in the section	ion(s) ^{3, 4 & 13} s verbatim, making
- Previous roof Repairs. Roof	was replaced in May	7 of 2019	
Section 4			
- Hot Tub Motor two not worki working. Hot Tub was not plan	ng and potentially ned to convey with h	leaking. Motor one, filters and h nouse.	eater are
— Sprinkler System. Repaired valve	leaking zone in fal	l of 2020. Drip on supply side of	the master
Section 13.			
- Explanation. Insurance claim	m in 2019 for hail o	damage when roof was replaced in	2019.
including the broker(s), has insti	ructed or influenced so have relied on this	ompleted by Seller as of the date seller to provide inaccurate information as true and correct and	tion or to omit any
Seller acknowledges that the statements to the best of Seller's belief.	in this form are true	Buyer acknowledges receipt of this form	
Docusigned by: Thomas Kadach	2/17/2021		
Signature of Seller	Date	Signature of Buyer	Date
Printed Name: Thomas Radach		Printed Name:	
— DocuSigned by: Iran Kadadh	2/17/2021		
Signature of Seller	Date	Signature of Buyer	Date
Printed Name: Jean Radach		Printed Name:	

(TXR 1418) 02-01-18 Page 1 of 1