



# TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

11/15/17

14 N Hutcheson St Houston, TX 77003



We love your home.

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT Page 2 of 4												
	14 N Hutche	son St		Houston		77003						
			<u> </u>	City	-	Zip Code						
A. B. C. D. E. F. G.	Inspected Address  City  Zip Code  SCOPE OF INSPECTION  This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.  This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.  Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage.											
Н.	covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.  There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and											
J.	renewal options.  There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.											
1A.	US Inspect  Name of Inspection Comp	nany	1B	607354 SPCS Business Lice	ense Numher							
1C.	2203 Jonathan Court		Euless	TX	76040	800.872.3810						
	Address of Inspection Co	mpany	City	State	Zip	Telephone No.						
1D.	Gabe Fitzpatrick Name of Inspector			1E. Certified Applicator Technician								
_	· · · · · · · · · · · · · · · · · · ·											
2.	File # APRO242536 / Job # ITA310		3. 1	I/14/2017 Inspection Date								
	Graebel Relocation Services World Name of Person Purchasi	wide Seller	Agent Buyer	. —	Other Relocation con	npany						
4B.	Unknown Owner/Seller											
Owner/Seller  4C.REPORT FORWARDED TO: Title Company or Mortgagee Purchaser of Service Seller Agent Buyer (Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy)												
The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Department of Agriculture Structural Pest Control Service. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected.  5. House and garage.												
List	structure(s) inspected that may inclu	de residence, detached garages	and other structures on t	he property. (Refer to Part	A, Scope of Inspection)							
(Ref 6B.1 Attic Dec	k Grade Too High	Yes" specify in 7B. include but are not limited to the Insulated area of attic Sub Floors Heavy Foliage	Plumb Slab J Eaves		Crawl Space Weepholes	abutting structure						
7A.0	Conditions conducive to wood destro	oying insect infestation:	Yes	No 🔳								
7B.0 Deb	fer to Part J, Scope of Inspection) If "\ Conducive Conditions include but are pris under or around structure (K) inter box abutting structure (O) ifficient ventilation (T)		too high (L) Wood	ooards left in place (l) I Rot (M) Ien Fence in Contact with tl	Excessive Mo Heavy Foliag he Structure ( R)	` `						
=												
8A.9 8B.0 8C.6 8D.0 8E.0	spection Reveals Visible Evidence in Subterranean Termites Drywood Termites Formosan Termites Carpenter Ants Other Wood Destroying Insects Specify: None Explanation of signs of previous treatine		Active Infe	No Yes	No N	Previous Treatment  Yes No						
8G.\	Visible evidence of: N/A  Here is visible evidence of active or properties.		observed in the following		lank and all identified info	ested areas of the property						
	pected must be noted in the second be			ast so noted in the inst b	and an identified fille	and or the property						
SPC	CS/T-4	(Rev. 09/01/07)	(866)	918-4481	Buyer's Initia	als						
	www.usinspect.com/re	location • 800.872.3810	• Inspection. Inte	grity. Buyers Initia	alsbs							

	TEXAS OFFICIAL WOOD I	DESTROYING I	NSECT REPOR	т		Pa	ge 3 of 4			
9.Will be o	tions conducive to insect infestation reported in 7A & 7B: or has been mechanically corrected by inspecting company: ecify corrections:				Yes	No				
9A.Correct a 9B.A preve Specif	tive treatment recommended for active infestation or evidence of previous inf is identified in Section 8. (Refer to Part G, H, and I, Scope of Inspection) entive treatment and/or correction of conducive conditions as identified in 7A fy reason:  to Scope of Inspection Part J	·			Yes Yes	No No				
If treating  If treating  10B. N/A	company has treated or is treating the structure for the following wood destroy for subterranean termites, the treatment was:  for drywood termites or related insects, the treatment was:  Full  Coate of Treatment by Inspecting Company  any has a contract or warranty in effect for control of the following wood dest	Spot Limi N/A Common Name	ted	Bait	N/A Name of Pestici	Other de, Bait or O	ther Method			
Yes No List Insects: N/A  If "Yes", copy(ies) of warranty and treatment diagram must be attached.										
Evidence o	Diagram of Str ctor must draw a diagram including approximate perimeter measurements and of Infestation, A-Active; P-Previous; D-Drywood Termites; S-Subterranean Ter Ants; Other(s) – Specify		previous infestati							
	27'									
Common Wall	Oovered 24'									
	27'  Comments Drawing not to scale, measurements are approximate.									
	Inspector		rest in the propert ection Was Poster Electric Breaker E Water Heater Clo Bath Trap Access Beneath the Kitcl Date Posted 11	d At or Near dox uset nen Sink		I nor the co	mpany for			
I understar			ns made. I have als			e of Inspecti	ion."			
	(Rev. 09/01/07)  www.usinspect.com/relocation • 800.872,3810 • Inspection	on Integrity	Buyers Init	ials	os kB	(T)				

### TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Page 4 of 4

## **CONSUMER INFORMATION SHEET**

The structural pest control industry is regulated by the Texas Department of Agriculture (TDA), Structural Pest Control Service (SPCS), PO Box 12847, Austin, TX 78711-2847. TDA licenses the businesses, certified applicators and technicians who perform structural pest control work. Certified applicators and technicians must pass a written examination in order to receive their licenses.

Pesticides must be registered with the United States Environmental Protection Agency (EPA) and TDA before they may be used in Texas. EPA registration is not a finding of product safety. Pesticides are designed to kill or control pests. Your risk of harm depends upon the degree of your exposure and your individual susceptibility.

Specific health and safety information varies between pesticides and types of exposures and is available on the label information or MSDS sheet, which can be supplied to you upon request from the licensed applicator. Take precautions when a treatment has been performed to avoid exposure to vulnerable individuals. Pesticides may be harmful if swallowed, inhaled, or absorbed through the skin. Avoid breathing dust or spray mist and any unnecessary contact with treated surfaces. If you desire specific information on precautions, refer to the pesticide label. The law requires that the application procedures specified on the label be followed.

If you have questions about the application, contact the business or person making the application. If you suspect a violation of the law regarding structural pest control, contact the SPCS. In case of a health emergency, seek immediate medical attention.

Pest Control signs must be posted prior to treatment in many instances. The signs should be posted in an area of common access at least 48 hours prior to treatment. The information sign will allow you to contact someone who can tell you what pesticide is being used.

If you are contracting for pest control services due to a home solicitation, you have the right to cancel the contract within 72 hours. You may exercise this right by notifying the pest control company that you do not wish to receive their service.

For general information on pesticides, contact the National Pesticide Information Center 1-800-858-7378

For information concerning structural pest control laws, contact the Structural Pest Control Service at 866-918-4481.

For information concerning the formulation and registration of pesticides, contact the TDA pesticide registration at (512) 463 -7476 or 800-835-5832.

For non-emergency health information relating to pesticides, contact Texas Department of State Health Services (512) 458 -7111.

# **REDUCED IMPACT SERVICE**

In order to minimize the reliance on pesticides and reduce pest populations, a Reduced Impact Pest Control operator may recommend that you consider the sanitation or physical alteration of your work place or residence. It is your responsibility to follow those recommendations. Your pest control operator may or may not offer these services upon request. A proper inspection will provide the information necessary for you to choose the method of pest control which best suits your situation. Many pest problems can be solved without using pesticides.

This Reduced Impact Service will include an inspection report and treatment recommendations. You should review these and keep a copy for your records. Your cooperation in following the recommendations made by your service provider is essential to a reduced impact service program.

Pesticides may be used in a responsible and professional manner in a reduced impact pest control service. If you do not want a specific pesticide used or any pesticides used at all, you must note this in writing on the contract prior to the initiation of the service. If any specific pesticide or class of pesticides are not excluded, it may be used by the provider.

# REQUIRED BY THE TDA STRUCTURAL PEST CONTROL SERVICE

Revised 09/01/07

LB E

TW DS