

Photo Report by Roof Repair Squad

Created by Tono Bogran

Sep 1, 2020 | 16 Photos



**Roof Repair Squad**

# Roof Inspection Report for:


KARIM BEYDOUN  
14 N Hutcheson St.,  
Houston, TX 77003





Front view

Project: Karim Beydoun Date: August 31st, 2020, 9:33 a.m.



Top view

Project: Karim Beydoun Date: August 31st, 2020, 10:04 a.m.



Leaking square vents

Project: Karim Beydoun Date: August 31st, 2020, 9:54 a.m.



**BLOWN SHINGLE**

Project: Karim Beydoun Date: August 31st, 2020, 10:01 a.m.



Project: Karim Beydoun Date: August 31st, 2020, 10:01 a.m.



Project: Karim Beydoun Date: August 31st, 2020, 9:56 a.m.




Project: Karim Beydoun Date: August 31st, 2020, 10:04 a.m.



Project: Karim Beydoun Date: August 31st, 2020, 10:02 a.m.



Project: Karim Beydoun Date: August 31st, 2020, 10:03 a.m.



High attic temperature suggests poor ventilation.

Project: Karim Beydoun Date: August 31st, 2020, 9:30 a.m.



Project: Karim Beydoun Date: August 31st, 2020, 9:29 a.m.



Project: Karim Beydoun Date: August 31st, 2020, 9:28 a.m.



Water intrusion point through an HVAC pipe.

Project: Karim Beydoun Date: August 31st, 2020, 9:27 a.m.



Water marks due to leak on ceiling.

Project: Karim Beydoun Date: August 31st, 2020, 9:24 a.m.





Project: Karim Beydoun Date: August 31st, 2020, 9:23 a.m.



Project: Karim Beydoun Date: August 31st, 2020, 9:24 a.m.