## List of improvements

House -

Front entry expanded and double doors added
Entry Tile
Office/guest room remodel
Exterior paint on entire home
Upgraded interior lighting fixtures at dining, breakfast and front entry

## Land -

Drainage from house and field to pond and from pond to southeast property
Bridge over drainage ditch at southeast corner of the pond
Add approximately 200 tons of road base and crushed concrete for parking to venue/barn

Venue/barn -

20' addition to the rear of the structure
Added select fill and concrete slab to the entire structure
Glass storefront and doors added to the entryway
New electrical service complete with all lighting fixtures, chandeliers, and trim
3 New restrooms added
Working kitchen sink and service area
Bar and storage area
Added sewage storage tanks
Installed Hvac system
Constructed pergola and rear barn deck
Insulated walls
Covered over walls and ceiling with OSB for durability

Interior and exterior paint to entire structure