

1823 LAKE WINDS DRIVE – UPDATES

- POOL PUMP AND FILTER REPLACED - 2020
- LAWN SPRINKLER CONTROLLER REPLACED - 2021
- PAINTING OF MASTER, MASTER BATH, KITCHEN AND SECOND BATH - 2020
- CANNED LIGHTS AND PENDANT LIGHTS INSTALLED IN KITCHEN - 2020
- EXTERIOR PAINTING - 2020
- EXTERIOR DRIVEWAY, SIDEWALK AND BUILDING POWER WASHED – 2020
- GRANITE COUNTERTOPS INSTALLED IN KITCHEN. FAUCET REPLACED – 2015
- QUARTZ COUNTERTOPS INSTALLED IN BATHROOMS AND FAUCETS AND SINKS REPLACED – 2020
- TILES INSTALLED IN MIDDLE BATHROOM – 2008
- GARAGE DOOR OPENER REPLACED – 2021
- ALUMINUM BLINDS INSTALLED IN KITCHEN – 2021
- CEILING FANS INSTALLED IN BEDROOMS AND LIVING ROOM AND PIANO ROOM – 2010
- AC UNIT WAS REPLACED – 2018
- WATER HEATER REPLACED -2017
- POLARIS POOL CLEANER PURCHASED – 2020
- RING DOOR BELL INSTALLED FRONT AND BACK - 2020
- NEST THERMOSTAT INSTALLED – 2020
- CONCRETE PAD EXTENDING DRIVEWAY TO THE SIDE ALLOWING A CAR TO PARK ON THE SIDE WITHOUT BLOCKING CARS IN GARAGE - 2008

NOTE:

THE HOUSE HAS NEVER FLOODED OR HAD ANY SERIOUS DAMAGE FROM HURRICANES OR STORMS.

WE DID NOT HAVE ANY BROKEN PIPES DURING THE FREEZE OF 2020