

McMillan - BPG Inspection Report 08-05-21 TREC # 22455

Actions Page 6-8

1. Removed mulch at those areas
2. Roof was inspected
3. Painted exposed flashings
4. Minor cracks repaired
5. Repainted home
6. N/A
7. N/A
8. N/A
9. N/A
10. Replaced door leading into garage
11. Window screens stored in attic
12. N/A
13. Replaced
14. Repaired
15. Repaired
16. Installed
17. Installed
18. Serviced
19. N/A - original overflow accepted
20. Repaired
21. Repaired
22. N/A
23. -26 N/A
27. Repaired