

1617 Hawthorne Updates/Repairs

- New Vent Grills
- Bathroom mold clean out and treatment
- Bedroom mold clean out and treatment
- New Kitchen plumbing
- HVAC coils cleaning
- Air duct cleaning
- Outake/intake cleaning
- Bedroom wall texture/paint repair
- New Front door install
- Bathroom remodel
- Front awning paint
- Powerwash Ext guest house
- New Window back room
- New Chimney Cap
- New HVAC pipe and thermostat
- Paint back exterior
- Brick step repair
- Interior paint main house

Total Cost Estimate of Updates/Repairs

\$18,500