
General Info

The owner of this property passed away unexpectedly in May, 2021. He purchased it in June 2016, lived alone, and was infrequently visited by family & friends. Accordingly, little was known about the condition of the property. The info provided herein was gathered from personal documents, etc. and is provided in good faith to interested potential buyers.

Summary

- Property Survey -Attached
- HCAD Ownership history
- Foundation 2004 Allied Foundation *Documents attached.*
 - o [17] driven piles around perimeter, [2] under interior load-bearing walls.
 - o 2010- Allied returned and adjusted 11 of the piers under warranty.
 - Lifetime transferrable warranty. Warranty passes with property, no requirement to formally transfer it.
 - o [Info provided by Allied's business office @ 281-479-5832.]
- Air Conditioner 2010 New RUUD R410a Complete System
 - Heat Exchanger [coil] warranty 20 years.-<u>Documents attached.</u>
- Roof 2007 replaced w/ 30 yr shingles- <u>Documents attached.</u>
- <u>Chimney Cap</u> 2009 Replaced- <u>Documents attached</u>.
- Floors updated w/ Vinyl WoodPlank [except bathrooms]
 - 2020-Stairs & Upstairs
 - o 2021- First floor & kitchen
- New Paint- Walls & Trim [except kitchen & baths]-2021
- New Garage Door & Opener -2021
 - Neighborhood Garage Door Service of Houston 713-364-0913
 - o Installed May 14, 2021 10 Year Warranty
- Chimneys Inspected & Swept 2021
- New Door Handle locksets -Kwikset SmartKey™ enables easy DIY re-keying
- Electrical Updates- 2021
 - LED light upgrades
 - Kitchen fluorescent tubes replaced with LED tubes
 - Front porch light -LED with switchable color temp
 - Downstairs track lights Dimmable LEDs
 - Bathrooms LED bulbs
 - Ceiling fan lights Dimmable LED candelabra bulbs in bedroom
 - Note: Wall switches must be in "ON' position, both pull chains "on, and then remotes used to control fan & lights
- Property Updates [by HoA] See attached HoA letter
 - Wall repair planned 2021 [caused by tree on city property]
 - o Sidewalk revision to accommodate tree- planned early 2022
 - HoA Policy can be provided on request. Note dues =\$75/month

WORK ON REPAIRS TO THE COMPLEX BRICK WALL ON FOWLER ST AND SIDEWALK WILL BEGIN AS SOON AS THE SELECTED CONTRACTOR[S] ARE AVAILABLE.



DRAFTING SURVEY 1, INC.

P.O. BOX 2543 + ALVIN. TX 77512
(281) 393-1382 + FGX (281) 393-1383

25077 8-541-05 65.6 49538 SATE 8-17-05

NOTES

ALL EMPORTS AND THE ACT, CORD, OR A COMMENT
THE SERVICE OF THE SET THEORETICS HOLD, IT IS NOT
THANKING TO ACCOUNT, SETTIMENS ON EXCENDED CHARGE,
ALLOCOT THAN AND ALL ECCOUNTY AND ALLOCATIONS AND ALLOCATIONS

FIELD NOTES Of A Survey Of

All that certain tract or parcel of land containing 1610.63 square feet out of Lot 6, Block 29, A. Brunners Addition, as recorded in Volume 42, Page 26, Harris County Deed Records, Houston, Harris County, Texas, said tract being more particularly described by metes and bounds as follows:

COMMENCING at the intersection of the Easterly right-of-way line of Fowler Street (50.00 feet wide) and the Northerly right-of-way line of Floyd Street (50.00 feet wide), said point being the Southwest corner of said Lot 6, Block 29, A. Brunner's Addition;

THENCE North, along the Easterly right-of-way line of said Fowler Street, being the Westerly line of said Lot 6, a distance of 53.92 feet to an "X" in concrete found marking the Southwest corner and the POINT OF BEGINNING of the herein described tract;

THENCE North, along the Westerly line of the tract herein described, being the Easterly right-of-way line of said Fowler Street, a distance of 46.08 feet to a ½ inch iron rod found for corner;

THENCE East, along the Northerly line of the tract herein described, a distance of 30.12 feet to an "X" in concrete found for corner;

THENCE South, along the Easterly line of the tract herein described, a distance of 55.96 feet to a P. K. Nail found for corner;

THENCE West, along the Southerly line of the tract herein described, a distance of 22.54 feet to P. K. Nail found for corner;

THENCE North, a distance of 9.88 feet to a P. K. Nail found for corner;

THENCE West, a distance of 7.58 feet to the POINT OF BEGINNING of the herein described tract of land.


11.T. Wit


Property Ownership History [per HCAD]

Anthon	y Do	yle	[Estate of]	06/14/2016
--------	------	-----	-------------	------------

Kenneth Kishida & Thuy Vu 08/31/2005

Leslie Niccum 01/02/1998





FOUNDATION REPAIR


REASONS FOR SETTLEMENT:

Seasonal drying to drought like conditions cause the soil to shrink. Excessive rain causes it to swell just like a sponge. The shifting and moving of the ground below, stresses the foundation and eventually cracks the slab.


THE SOLUTION:

Allied Foundation has two (2) outstanding piers to stabilize your foundation.

- 1. Driven Concrete Pier: Solid concrete piers are driven to a point of refusal. Hydraulic jacks are then placed on concrete pads to level the foundation. The lift is secured with concrete blocks and shims.
- 2. Pile Guard Pier: This is a driven concrete pier plus. Pile guards are couplings that encase each concrete cylinder so that a positive alignment is assured.







Pile Guard Pier



Before



After

House Pro, Inc.

Heating Ventilation Air Conditioning Specialty Solutions For Today's Quality Custom Home Builder

7 May 2010

House Pro, Inc. Proposal Created For

Homeowner: Ken Kishida Address: 704 Fowler

Address: 704 Fowler City/St./Zip: Houston, TX 77007 Email: ken.kishida@gmail.com

Address: City/St./Zip:

Scope of Work

Install Ruud Value Series Air Conditioning System

Condensor:

13AJM42A01

Condenser Install Package: new slab, filter drier, suction line insulation

Air Handler: RHSL-HM3617JA

Air Handler Install Package: primary drain lines, secondary drain pan, float switch, furnace stands,

Thermostat: Relocate thermostat to upstairs

Warranties**

Compressor: 10 years Condenser Coil: 10 years Evaporator Coil: 10 years Heat Exchanger: 20 years

Parts: 10 years Labor: 1 years

Total Installation Price: \$6,061 Ruud Instant Rebates: \$500 House Pro System Discount: \$500 Total Investment: \$5,061

Terms: C.O.D.

^{**} Requires online registration

	House Pro Inc.						nvoice
	6115 Skyline D Houston, TX 7	7057			[Date	Invoice #
	nousion, 127	7037				5/12/2010	1001-1224
DIII T.				1	Ship To		
Bill To Ken Kish 204 Fow Houston,	hida			710	Ken Kishida 204 Fowler Houston, TX 77007		
P.O. Number	Terms	Rep	Ship	Via	F.O.B.		Project
810100	Due on rece	ipt MK	5/12/2010	Hand delivere	ed	810100	
Quantity	Item Code	De		ption	Pri	ce Each	Amount 5,061.0

RJM Roofing LLC 11518 BISCAYNE WAY HOUSTON TX, 77076 Ph 713-691-6838 Fax 713-692-5427 Page No.___1__ of ___2__Pages Proposal No. 2171 DATE 04/28/07

PROPOSAL SUBMITTED TO:

WORK PERFORMED AT:

Thuy M. 710 Fowler St. Houston Tx, 77007 Ph 832-594-5244 SAME

We hereby propose to furnish the material and performed the labor necessary for the completion of the composition roof as follows:

Remove one layer of composition shingles.

Replace rotted damage decking at a cost of \$ 1.25 per square foot.

Install one layer of 15 Lb. felt.

Install 1.5X 1.5 galv. metal edge to the perimeter of the roof.

Install new roof with 30 years class A composition shingles, hand nailed with 1.25" galv.nails, four nails per shingle.

Install one 24"X 36" sky light doble dome.I

Install 7X8 tin shingle and counter flash chimney.

Replace lead pipe vents and roof jacks as needed.

Remove all debris incidental to our work from the premises.

Roll yard and drive way with a magnetic roller after work is completed.

All material is guaranteed to be as specified, and the above work to be performed in accordance with the drawings and specifications submitted for above work and completed in a substantial workmanlike manner for the sum of : TWO THOUSAND THREE HUNDRED FIFTY FIVE DOLLARS (2,355.00)

With payments to be as follows.

50% BEFORE START THE WORK AND 50% AFTER WORK IS COMPLETED.

Any atteration or deviation from above specifications involvin extra costs will be executed only upon written order, and will become an extra charge over the above estimate.

LIMITED WARRANTY

RJM ROOFING LLC. Warrants its workmanship for a period of ___5__ years and expressly irmits such warranty, express or implied to provide labor and supervision as is required to correct any defects of its work caused by its workmanship.

Page 2___
Proposal No.

 I will not be responsible for damages to the building or contents due to acts of God such as earthquakes, fire, windstorm, hailstorm, tornado, or other unusual phenomena or other occurances or forces beyond our control.

Prices subject to change as material cost escalate without notice to us. Once contract is signed by customer the price will be binding unless customer delays our starting the job.

Prices quoted in the proposal do not include rotten lumber replacement unless is spicified.

No painting or gutter work is included, any extra work performed, other then specified will be an extra charge.

It is impossible to determine extent of rotten decking, except by inspection after removal of old roofing to expose decking, also we connot be responsible for internal structural strength so if you have any doubt about the strength of your roof substructure, rafters, beams etc. it will be your responsibility to either notify us or to have weakened conditions repaired before we start our work. Also if you have any exposed decking inside your house (catherdral ceilings)..

you should be sure that we know, so that proper nail length can be used.

4. It is understood and agreed upon that the contract price for the work including alternates is DUE and PAYABLE IN FULL, in Houston, Harris County, Texas, upon completion of the work.

All unpaid amounts shall bear interest at the maximum lawful rate from the due date until paid in full. Should it become necessary to employ an attorney to collect or take legal action, for any amounts that may become due hereunder, then the attorney fees and court cost will be added.

This contract is enforceable in Harris county, Texas, an shall be construed in accordance with the laws of the state of Texas, regardless of the location of the work performed hereunder.

Zaymand Medina.
be withdawn by us if not accepted within60days.
E OF PROPOSAL
ations and conditions are satisfactory and are hereby accepted ne work as specified. Payment will be made as outlined above.
Signature Mush

STREET: 7/2 (Equipolicative Allegable)	ZIP:	7) D D	-)	CHIMNEY SWEEP & AIR DU	
ORDER DATE:					_	-	870
PHONE: Zal- Sis-	265					NEXT INSPECTION SCHE	NIED
ALT. PHONE:						IN: OF:	,
5+MAL:						THE NATIONAL FIRE PROTECTION ASS	OC. CODE STATES:
Type of Fireplace:		٤١	≿I	ų	19	THE FIREPLACE AND CHINNEY SHOUL YEARLY FOR ANY STRUCTURY	D BE INSPECTED
			ğ	3	8	CHIMNEY CLEANING .	4 " may = 19 The"
Woodstove: ⊠Insert □Free Standing		MISFACTOR	ATISFACTOR	5	¥	ADDITIONAL	
□Direct Connect	_	剈	剈		ECO		
CONDITION REPORT		og	劉		2	INSTALLATIONS /REPAIRS:	
CHIMNEY 3	B			_	_		
1. Height		Т	Т		Г		
2. Chimney Cap/Shroud	鼯	7	7		Т	SM . MED LG XLG MAG	
3. Crown/Chase Cover	財	7	7		Н	TOP SEALING DAMPER	
4. Spark Arrestor	曽	7	1	ï	Г		
6. Brickwork/Mortar/Stucco		7	7	А.			
6. Flue Liner	田	7	7	::::	_	WATER REPELLENT	
7. Moisture Resistance	8		1			SPARK ARRESTOR @	
FIREPLACE	嵩	_			_		
8. Smoke Chamber	-0-	T	Т				
9. Damper	#	\top	5/1				10
10. Firebox		A		-		OTHER	
11. Ash Doors	4	4	4			1 S 1 1/2/3"	
12. Firebeck/Reflector	-32	T	T			SWEEP'S REPORT & NOTES	** 33 c
13. Firewell		\Box	T		12	JACET SBEFORT & HOTES	Try 7 3 14
14. Gas Logs		\Box	I		- 7	"March	TOTAL SIVE
ROOF		9	ट्र	i	\hat{x}^{i}	or of it.	
15. Flashing		83	ι. I			<u> </u>	DEPORT
16. Tiles / Shingles	Ç.	\perp	T				MANCE
WOODSTOVE		\perp	A				BILLING
17. Stove Pipe Condition			1				PND
18. Stove Condition						l D	>ECK#
19. Installation/Clearance		\perp	\perp	1			MBA I MC I DIBC I AMEX
-		\perp	1	⅃		L	NOBILE CC PIAT

Brick wall repair

Subject: Brick wall repair

From: Jim Taylor Date: 9/28/21, 10:18 PM To: jmwted@comcast.net

Hello fellow HOA members.

We have picked a company to repair the brick wall in the front of the south courtyard. We are working to schedule the repair. The repair should should only take a few days to complete.

The next project is to replace the sidewalks that have been damaged by the tree roots. We are a little short of the funds but hope to be able to start this project the first part of 2022

Thanks Jim Taylor 700 Fowler Place HOA President