

The pool valves, control panel and spa heater were replaced this year after the freeze.

Both fireplaces refurbished in 2020 and 2021.

Water heater replaced last year.

Sprinkler system control panel replaced November 2021.

Mister installed under the pergola.

Past landscape lighting in back yard wiring present to be refurbished if desired.