

THIS PROPERTY DOES NOT LIE WITHIN THE 100 YEAR FLOOD PLAIN AS PER FIRM PANEL NO. 485488 0025 D MAP REVISION: 09/22/1999 ZONE X BASED ONLY ON VISUAL EXAMINATION OF MAPS. INACCURACIES OF FEMA MAPS PREVENT EXACT DETERMINATION WITHOUT DETAILED FIELD STUDY

A SUBSURFACE INVESTIGATION
WAS BEYOND THE SCOPE OF THIS SURVEY

D.C.L. = DIRECTIONAL CONTROL LINE
RECORD BEARING: PLAT RECORD 2007-A, MAP # 55 & 56 G.C.M.R.

DRAWN BY: BR

CERTIFIED TO: MOODY NATIONAL BANK

CERTIFIED TO: MOODY NATIONAL BANK
I HEREBY CERTIFY THAT THIS SURVEY WAS MADE
ON THE GROUND, THAT THIS PLAT CORRECTLY
REPRESENTS THE FACTS FOUND AT THE
TIME OF SURVEY AND THAT THERE ARE NO
ENCROACHMENTS APPARENT ON THE GROUND,
EXCEPT AS SHOWN HEREON. THIS SURVEY IS
CERTIFIED FOR THIS TRANSACTION ONLY AND
ABSTRACTING PROVIDED IN THE ABOVE
REFERENCED TITLE COMMITMENT WAS RELIED
UPON IN PREPARATION OF THIS SURVEY.


GEORGE GALE PROFESSIONAL LAND SURVEYOR NO. 4678 JOB NO. 10-11783 DECEMBER 03, 2010







TAMMY MOSS 409-986-1211



SUSAN MAGERS 281-280-8383





1-800-LANDSURVEY www.precisionsurveyors.com

281-496-1586 FAX 281-496-1867 14925 MEMORIAL DRIVE SUITE B100 HOUSTON, TEXAS 77079

210-829-4941 FAX 210-829-1555 1777 NE LOOP 410 SUITE 600 SAN ANTONIO, TEXAS 78217