
TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

705 Fowler St	Houston	77007
Inspected Address	City	Zip Code
	SCOPE OF INSPECTION	

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). **Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.**
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
- F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.
- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). The warranty should specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- I. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

705 Fowler St	Houstor	1	77007	
Inspected Address	City		Zip Code	
1A. Life After Bugs LLC	1B.	0691524		
Name of Inspection Company		SPCS Business License	e Number	
1C. 2006 Thompsons Rd. #205	Richmond	Тх	77469 832-643-9724	
Address of Inspection Company	City	State	Zip Telephone No.	
1D. Christian Martinez Name of Inspector (Please Print)		1E. Certified Applicator Technician	[] (check one) [X]	
	1F	05/25/2021		
	Inspection Date			
2. Brennan Jantzen Name of Person Purchasing Inspection		Seller [] Agent [] Buyer [X] N	Aanagement Co. [] Other [] <u>N/A</u>	
3. Owner of Record				
Owner/Seller 4.REPORT FORWARDED TO: Title Company or Mortgagee [] Purce (Under the Structural Pest Control regulations only the purch		Seller [] Agent [X] uired to receive a copy)	Buyer []	
The structure(s) listed below were inspected in accordance with the offic This report is made subject to the conditions listed under the Scope of In	ial inspection procedure spection. A diagram mus	s adopted by the Texas Department of Ag at be attached including all structures insp	griculture Structural Pest Control Service. Dected.	
5A. Residence		·		
List structure(s) inspected that may include residence, detached garage	s and other structures or	n the property. (Refer to Part A, Scope of I	nspection)	
5B. Type of Construction:				
Foundation: Slab [X] Pier & Beam [] Pier Type: Siding: Wood [] Fiber Cement Board [X] Brick [] Stone Roof: Composition [] Wood Shingle [] Metal [] Tile [X	[] Stucco [X] Other	ent [] Other [] <u>N/A</u> [] <u>N/A</u> Masor	Crawlspace [] nite [] Vinyl Siding [] Metal []	
6A.This company has treated or is treating the structure for the following	, , , ,			
If treating for subterranean termites, the treatment was: If treating for drywood termites or related insects, the treatment was:	Partial [] Full []	Spot [] Bait Limited []	[] Other []	
6B. N/A		N/A	N/A	
Date of Treatment by Inspecting Company	Common Name		f Pesticide, Bait or Other Method	
This company has a contract or warranty in effect for control of the follow Yes [] No [X] List Insects:	, s	ects:		
If "Yes", copy(ies) of warranty and treatment diagram mu				
Neither I nor the company for which I am acting have had, presently ha			his property. I do further state that neither I nor the	
company for which I am acting is associated in any way with any party to Signatures:	this real estate transaction	on.		
7A. Inspector (Technician or Certified Applicator Name and License Number	ar)			
Others Present:	-1)			
7B. N/A	tion (Licon co Number (c)			
Apprentices, Technicians, or Certified Applicators Name(s) and Registra	tion/License Number(s)			
Notice of Inspection Was Posted At or Near:				
Water Heater Closet []	ate Posted: 05	/25/2021		
Beneath the Kitchen Sink [X]				
9A.Were any areas of the property obstructed or inaccessible? (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 9B.	Yes [X] No []		
9B.The obstructed or inaccessible areas include but are not limited to the Attic [] Insulated area of attic [X	e following:] Plumbing Area:	s [X] Planter box abutting s	tructure []	
Deck [] Sub Floors [] Soil Grade Too High [] Heavy Foilage []	Slab Joints	[X] Crawl Space [] Weepholes		
Limited Exterior Accessibility [] High Water []		[]	[]	
Other [] Specify: <u>Furniture/Storag</u> 10A.Conditions conducive to wood destroying insect infestation:	ye Yes [X] No []		
(Refer to Part J, Scope of Inspection) If "Yes" specify in 10B.				
10B. Conducive Conditions include but are not limited to: Wood to Ground	Contact (G)	[] Formboards left in place (I) []	Excessive Moisture (J) []	
Heavy Foliage (N) [] Planter box abut	r soil line too high (L) ting structure (O)	[] Wood Rot (M) [] [] Wooden Fence in Contact with the	Wood Pile in Contact with Structure (Q) [] e Structure (R) []	
Insufficient ventilation (T) [] Corner Other (C) [] pops []	Specify:			
	- I 7 -			
SPCS/T-5 (Rev. 09/1/2020)			Page 2 of 4	



05 Fowler St	Housto	n	77007
Inspected Address	City		Zip Code
	Statement	ofPurchaser	
lave received the original or a legible copy of the nderstand that my inspector may provide add ⁱ	is form. I have read and understand any reco tional information as an addendum to this rep	mmendations made. I have also rea ort.	ad and understand the "Scope of Inspection." I
additional information is attached, list number			
gnature of Purchaser of Property or their Desig		Date	
	Puwor's Initials		
] Customer or Designee Not present	Buyer's Initials		