


CURVE	RADIUS	ARC LENGTH	CHORD LENGTH	CHORD BEARING	DELTA ANGLE
C1	330.00'	60.00'	59.92'	S 73°46'18" W	10°25'03"

LINE	BEARING	DISTANCE
L1	N 02°00'08" E	43.47'

LEGEND

These standard symbols will be found in the drawing.

- BOUNDARY LINE
- EASEMENT LINE
- BUILDING SETBACK LINE
- WOOD FENCE
- CHAINLINK FENCE
- OVERHEAD ELECTRIC
- SET 1/2" IRON ROD WITH CAP
- PROPERTY CORNER
- FOUND IRON ROD
- FENCE POST
- WATER METER
- GAS METER
- ELECTRIC METER
- POWER POLE
- GUY ANCHOR
- CONTROL MONUMENT



NOTE:
THIS SURVEY MEETS THE CURRENT STANDARDS OF THE TEXAS SOCIETY OF PROFESSIONAL SURVEYORS STANDARDS AND SPECIFICATION FOR A CATEGORY 1A, CONDITION II SURVEY.


THIS SURVEY IS BASED ON A TITLE COMMITMENT REPORT ISSUED BY FIRST AMERICAN TITLE GUARANTY COMPANY GF NO. 2366257-H0166 ISSUED ON 11/26/2018.

THE ORIGINAL PLAT RECORD IS ILLEGIBLE. THIS REPRESENTATION IS SURVEYOR'S BEST INTERPRETATION OF RECORD INFORMATION.

FLOOD INFORMATION
FIRM: 48201C PANEL: 1005 L
REV. DATE: 06/18/2007
ZONE: "X"

FLOOD INFORMATION PROVIDED HEREON IS BASED ON SCALING THE LOCATION OF THE SUBJECT TRACT ON THE FLOOD INSURANCE RATE MAPS, THE INFORMATION SHOULD BE USED TO DETERMINE FLOOD INSURANCE RATES ONLY AND IS NOT INTENDED TO IDENTIFY SPECIFIC FLOODING CONDITIONS. WE ARE NOT RESPONSIBLE FOR THE F.I.R.M.'S ACCURACY.

GRAPHIC SCALE



I, RODRIC R REESE, a Registered Professional Land Surveyor in the State of Texas, do hereby certify to FIRST AMERICAN TITLE INSURANCE COMPANY and NATION RELIABLE LENDING, LLC that the above map is true and correct according to an actual field survey, made by me or under my supervision, of the property shown hereon or described by field notes accompanying this drawing. I further certify that all easements and rights-of-way of which I have been advised are shown hereon and that, except as shown, there are no apparent visible encroachments, no apparent visible overlapping of improvements and no apparent discrepancies or conflicts in the boundary lines, as of the date of the field survey. Lot(s) 28, Block 5, WINDSOR VILLAGE, SECTION 1 recorded in Volume 50, Page(s) 48, of the Map/Deed and Plat Records of HARRIS County, Texas, located in the JOHN W. STAMPS SURVEY. Borrower: SANDY NAJERA. Address: 5822 HEATHERBLOOM DRIVE, HOUSTON, TX 77085 GF No. 2366257-H0166

LAND TITLE SURVEY

JOB NO.:	1812012856	NO.	REVISION	DATE
DATE:	12/06/18			
DRAWN BY:	IK			
APPROVED BY:	RRR			

SUBJECT TO RESTRICTIVE COVENANTS AND/OR EASEMENTS RECORDED IN: VOLUME 50, PAGE 48, MAP AND/OR PLAT RECORDS, HARRIS COUNTY, TEXAS CLERK'S FILE NOS. J773760, K180157, S303222, S329678, S418533, T301606, T360148, U633348, Y356078, Y653696, 2017-102719, OFFICIAL RECORDS, HARRIS COUNTY, TEXAS

PROPERTY PHOTOGRAPH:



Rodric R. Reese
FIRM REGISTRATION NO. 10190700
THIS SURVEY IS CONTRACTED TO RODRIC R REESE, RPLS
PHONE NUMBER 713-647-1315
RODRIC R REESE, R.P.L.S.
Registered Professional Land Surveyor
Registration No. 5883
COPYRIGHT ALL RIGHTS RESERVED TO OVERLAND CONSORTIUM INC.

Overland Consortium Inc. Surveyors
Te: 281 940 8869 Fax: 281 207 6476
1528 W. CONTOUR DR., SUITE 204, SAN ANTONIO, TX 78212