

## Home Repairs - 2810 Grants Lake Boulevard #1006

New black dishwasher purchased and installed
New black and stainless counter top microwave oven
New facet installed in the kitchen
New smoke/carbon dioxide detectors installed downstairs and upstairs
AC/Heater was inspected and working correctly. The inspection was performed by the people that inspect it twice a year. A new AC filter was also installed.
Mold was removed from the brick wall in the patio area two months ago
Ceiling was replaced in the storage room
Rotted wood was replaced surrounding the rear french doors
Paint was touched up around the house to repair holes made by picture hanging
All carpets and downstairs tile floors were professional cleaned and deodorized. (Stanley Steemer)
Two leaking toilets were repaired
Leaking faucet was repaired in the upstairs hall bath
Stopper in upstairs master bath sink was repaired
All kitchen cabinet doors were adjusted to align correctly
Kitchen drawer was repairs to open correctly