
Property Inspection Report



Quality Home Inspections

10907 Keese St.

Inspection Prepared For: Juan Rios
Agent: Ruth Longoria - Ruth Longoria Realtors

Date of Inspection: 9/1/2022

Year Built: Size:

Weather:

PROPERTY INSPECTION REPORT FORM

Juan Rios Name of Client 10907 Keese St., Houston, TX 77089	9/1/2022 Date of Inspection
Address of Inspected Property	
donald stahl	
Name of Inspector	TREC License #
Name of Sponsor (if applicable)	TREC License #

PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. It is important that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

RESPONSIBILTY OF THE INSPECTOR

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minimum requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or component **OR** constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

- identify all potential hazards;
- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another;
- provide follow-up services to verify that proper repairs have been made; or
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233).

RESPONSIBILTY OF THE CLIENT

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

Please Note: Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

REPORT LIMITATIONS

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above).

ONLY those items specifically noted as being inspected on the report were inspected.

This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

NOTICE CONCERNING HAZARDOUS CONDITIONS, DEFICIENCIES, AND CONTRACTUAL AGREEMENTS

Conditions may be present in your home that did not violate building codes or common practices in effect when the home was constructed but are considered hazardous by today's standards. Such conditions that were part of the home prior to the adoption of any current codes prohibiting them may not be required to be updated to meet current code requirements. However, if it can be reasonably determined that they are present at the time of the inspection, the potential for injury or property loss from these conditions is significant enough to require inspectors to report them as Deficient (D). Examples of such hazardous conditions include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices and arc-fault (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- · lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

Please Note: items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions. The decision to correct a hazard or any deficiency identified in an inspection report is left up to the parties to the contract for the sale or purchase of the home.

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

D=Deficient

10907 Keese St., Houston, TX

I. STRUCTURAL SYSTEMS

D

NI NP

Type of Foundation(s):

Slab Foundation

Comments:

Concrete slab only

X B. Grading and Drainage

Comments:

Out structures and sheds are excluded from this report

X C. Roof Covering Materials

Type(s) of Roof Covering:

Ásphált shingles noted.

Viewed From:

Roof has many soft areas or weak areas.

Comments:

- · Deteriorated shingles at ridge cap
- · Roof is weathered
- Recommend roofing contractor to evaluate
- Mismatched shingles
- Shingles curling
- Mismatched shingles
- · Roof is weathered
- Deteriorated shingles at ridge cap
- Recommend roofing contractor to evaluate



Mismatched shingles

Deteriorated shingles at ridge cap

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

NI NP D



wave in the roof

D. Roof Structure and Attics

Viewed From:

· attic area

Approximate Average Depth of Insulation:
• Insulation is 10 inches deep

Comments:

- Recommend review by a qualified professional for repair or replacement, as necessary, prior to close.
- roof sheating shows damage
- · Recommend review by a qualified professional for repair or replacement, as necessary, prior to close.
- roof sheating shows damage



roof sheating shows damage

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

NI NP D



roof sheating shows damage

X	E. Walls (Interior and Exterior)
	Wall Materials: • Exterior walls are made of brick • Exterior walls are made of wood • Interior walls are made of Drywall Comments: • New paint in areas • Blistered • New paint in areas • Blistered
X	F. Ceilings and Floors
	Ceiling and Floor Materials: • Ceiling is made of drywall Comments:
X	G. Doors (Interior and Exterior)
	Comments: • All doors are functional
X	H. Windows
	Window Types: • Windows are made of alluminum Comments: • All windows are functional

Quality Home Insp	pections		10907 Keese St., Houston,
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	I. Stairways (Interior ar	nd Exterior)	
	Comments: • None		
	J. Fireplaces and Chim	nneys	
	Locations: Types: Comments:		
X	K. Porches, Balconies,	Decks, and Carports	
	Comments: • porch is functional		
	L. Other		

Materials: Comments:



down spout missing

C. Other

Copper wiring

Comments:

Comments:

• 100 Amp service panel



electric service line to close to the ground

Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
NI NP D			
	III. HEATING, VENTILA	TION AND AIR CONDI	TIONING SYSTEMS
	A. Heating Equipment		
	Type of Systems: Gas fired forced hot Energy Sources: The furnace is gas p Comments: Enclosure is function The heater is an old The heater is an old	owered al unit	
	B. Cooling Equipment		
	Type of Systems: • Electric Comments:		
	C. Duct Systems, Cha	ses, and Vents	
	functional.	ered in insulation, which	are old and out of date, but are old and out of date, but
	D. Other		
	Comments:		

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

IV. PLUMBING SYSTEMS

X A. Plumbing Supply, Distribution System and Fixtures

Location of Water Meter:

• left side of driveway by curb

Location of Main Water Supply Valve:

• left side of house

Comments:

- No hot water pressure in the kitchen
- Recommend plumber to evaluate all areas
- back flow preventers were missing
- Recommend plumber to evaluate all areas
- No hot water pressure in the kitchen
- · back flow preventers were missing



back flow preventers were missing

back flow preventers were missing

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

NI NP D



No hot water pressure in the kitchen

Type of Drain Piping Material:
• Galvanized steel

Observations:

X	′						Χ	C.	. Water Heating Equipmen
---	---	--	--	--	--	--	---	----	--------------------------

Energy Source:

- · Water heater is gas powered
- Water heater is located in the laundry room

Capacity:
• Unit is 40 gallons

Comments:

- Unit is old, recommend replacement
- Unit is old, recommend replacement

NP=Not Present D=Deficient I=Inspected NI=Not Inspected

NI NP D





rust on top of unit

Unit is old, recommend replacement

	D. Hydro-Massage Therapy Equipment
	Comments:
	E. Gas Distribution Systems and Gas Appliances
	Location of Gas Meter: Type of Gas Distribution Piping Material: Comments:
	F. Other
	Materials: Comments:
	V. APPLIANCES
X	A. Dishwashers
	Comments: • Operated.
X	B. Food Waste Disposers
	Comments: • Operated - appeared functional at time of inspection.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D)			
$x \square \square$	C. Range Hood and E	xhaust Systems		
	Comments: • Unit operated norma	ally		
$X \square \square X$	D. Ranges, Cooktops,	and Ovens		
	Comments:			

- Oven: gas burners
- The burners: not all flames came on
- oven did not heat up properly
- The burners: not all flames came on
- oven did not heat up properly



The burners: not all flames came on

The burners: not all flames came on



oven did not heat up properly

l=Inspected	NI=Not Inspected NP=Not Present D=Deficient
I NI NP I	D
	E. Microwave Ovens
	Comments:
x	F. Mechanical Exhaust Vents and Bathroom Heaters
	Comments: • The bath fan was operated and no issues were found.
	G. Garage Door Operators
	Door Type: Comments:
x 🗌 🗎	H. Dryer Exhaust Systems
	Comments:
	I. Other
	Comments:

Report Summary

STRUCTURAL SYSTEMS				
Page 3 Item: C	Roof Covering Materials	 Mismatched shingles Roof is weathered Deteriorated shingles at ridge cap Recommend roofing contractor to evaluate 		
Page 4 Item: D	Roof Structure and Attics	 Recommend review by a qualified professional for repair or replacement, as necessary, prior to close. roof sheating shows damage 		
Page 5 Item: E Walls (Interior and Exterior)		New paint in areasBlistered		
HEATING, VENTI	LATION AND AIR C	ONDITIONING SYSTEMS		
Page 8 Item: A	Heating Equipment	The heater is an old unit		
Page 8 Item: C	Duct Systems, Chases, and Vents	• ducts are metal covered in insulation, which are old and out of date, but functional.		
PLUMBING SYSTEMS				
Page 9 Item: A	Plumbing Supply, Distribution System and Fixtures	 Recommend plumber to evaluate all areas No hot water pressure in the kitchen back flow preventers were missing 		
Page 10 Item: C	Water Heating Equipment	Unit is old, recommend replacement		
APPLIANCES				
Page 12 Item: D	Ranges, Cooktops, and Ovens	The burners: not all flames came onoven did not heat up properly		