

## Interior

- Replaced flooring downstairs with wood like tile
- All carpet upstairs was recently replaced
- □ Added crown molding downstairs
- Added custom wood trim to archways
- Wood window valances in the main living area
- Replaced both 40-gallon hot water heaters
- □ HVAC/Heater replaced
- Added a marble backsplash to the kitchen
- Updated stainless steel appliances

## Exterior

- Pool motor was replaced with a variable speed motor
- Outlet plugs around the exterior of the home
- □ Added covered patio in the back
- Fence replaced within using stainless steel nails and a rot board at the bottom

- Quartz composite countertops installed
- Replaced kitchen sink
- □ Lighting above kitchen cabinets
- Added marble backsplash in laundry room
- □ Replaced garbage disposal
- Replaced lighting fixtures throughout the home
- □ Recess lighting upstairs/downstairs
- All faucets have been replaced
- Chair high toilets

- □ Sprinkler system
- 2 Meters: One for the home and one for the pool and the sprinkler system
- Replaced all the windows
- □ Storm doors front/back