TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT Page 1 of 2 1436 VASSAK 1 to visson 77066 SCOPE OF INSPECTION This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc.. is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that agency at factors and devices. A. B. C If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is D present. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified E. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS. F. G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renowal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options. H. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure. (2) there is visible evidence of a previous infestation with no evidence of a prior treatment. evidence of a prior freatment. If treatment is recommer ded based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture. J. 733387 BULLO POSTICENTRUC Name of Inspection Company SPCS Business License Number #63 RICHIMONO 1472407 9720 11, MILLEM 281-246-2157 Address of Inspection Company City Zip THEIS STALLET 1E. Certified Applicator 🖫 (check one) Name of Inspector (Please Print) Technician NA 3-22-18 Case Number (VA/FHA/Other) Inspection Date ANUGRESUN Seller J Agent J Buyer A Management Co. A Other A Name of Person Purchasing Inspection ~ W Owner/Seller 4C.REPORT FORWARDED TO: Title Company or Mortgagee J Purchaser of Service Seller J Ages (Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy) Agent 🗓 Buver 🗆 The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Department of Agriculture Structural Pest Control Service. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected. 120 612200 1700030 List structure(s) inspected that may include residence, detached garages and other structures on the property. (Refer to Part A. Scope of Inspection) 6A.Were any areas of the property obstructed or inaccessible? (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 6B. No J 6B.The obstructed or inaccessible areas include but are not limited to the following: Insulated area of attic 15 Sub Floors 1 Attic J Plumbing Areas Planter box abutting structure Deck Soil Grade Too High Deck Slab Joints Heavy Foliage Weepholes Other → Specify: 7A.Conditions conducive to wood destroying insect infestation: (Refer to Part J, Scope of Inspection) If "Yes" specify in 7B. 7B.Conducive Conditions include but are not limited to: Wood to Ground Contact (G) Footing too low or soil line too high (L) Wood Pile in Contact with Structure (Q) Formboards left in place (i) 🔳 3 Debris under or around structure (K) Wood Rot (M) Wooden Fence in Contact with the Structure (R) Planter box abutting structure (O) Heavy Foliage (N) Insufficient ventilation (T) Other (C) ⇒ Specify: _ 8.Inspection Reveals Visible Evidence in or on the structure: Active Infestation Previous Infestation Previous Treatment 8A.Subterranean Termites No 3 Yes J Yes J Yes J Yes J No J Yes 1 Yes 1 Yes 1 الد No الد No 8B. Drywood Termites 8C.Formosan Termites 8D.Carpenter Ants No No Yes No Ja No 42 8E.Other Wood Destroying Insects Yes Specify: 8F.Explanation of signs of previous treatment (including pesticides, baits, existing treatment stickers or other methods) identified:

If there is visible evidence of active or previous infestation, it must be noted. The type of insect(s) must be listed in the first blank and all identified infested areas of the property inspected must be noted in the second blank. (Refer to Part D. E & F, Scope of Inspection)

has been observed in the following areas:_

8G. Visible evidence of:

| TEXAS OFFICIAL WOOD DESTR | OYING INSECT REPORT Page 2 of 2 |
|--|--|
| The conditions conducive to insect infestation reported in 7A & 7B: 9.Will be or has been mechanically corrected by inspecting company: If "Yes," specify corrections: | Yes ii No ii |
| 9A.Corrective treatment recommended for active infestation or evidence of previous infestation or as identified in Section 8. (Refer to Part G, H, and I, Scope of Inspection): 9B.A preventive treatment and/or correction of conducive conditions as identified in 7A & 7B is respectly reason: Refer to Scope of Inspection Part J | ecommended as follows: Yes No 2 PCE, L-1A16It SOIL LC-LLY, M-LUCO ROT |
| 10A.This company has treated or is treating the structure for the following wood destroying insect if treating for subterranean termites, the treatment was: Partial U Spot If treating for drywood termites or related insects, the treatment was: Full U Limited | ⊔ Bait '⊔ Other □ |
| 10B Date of Treatment by Inspecting Company Common Nam This company has a contract or warranty in effect for control of the following wood destroying ins | e of Insect Name of Pesticide, Bait or Other Method |
| Yes J No J List Insects: If "Yes", copy(ies) of warranty and treatment diagram must be attached. | |
| Diagram of Structure(s) Inspected The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes: E-Evidence of Infestation, A-Active; P-Previous; D-Drywood Termites; S-Subterranean Termites; F-Formosan Termites; C-Conducive Conditions; B-Wood Boring Beetles; H-Carpenter Ants; Other(s) — Specify | |
| | |
| | |
| | |
| | |
| 104 | |
| The state of the s | |
| | |
| D 60 5 5 | * |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | 37 m 05 10 1 |
| | 2 65 83 |
| | |
| Additional Comments | |
| | |
| N. M | |
| Neither I nor the company for which I am acting have had, presently have, or contemplate having thich I am acting is associated in any way with any party to this transaction. | g any interest in the property. I do further state that neither I nor the company for |
| IIA | tice of Inspection Was Posted At or Near: Electric Breaker Box |
| Inspector | |
| Approved: 11B 12B. Da Certified Applicator and Certified Applicator License Number | Water Heater Closet Bath Trap Access Beneath the Kitchen Sink Be Posted Date Date |
| Statement of Purchaser | |
| I have received the original or a legible copy of this form. I have read and understand any recommendations made. I have also read and understand the "Scope of Inspection." I understand that my inspector may provide additional information as an addendum to this report. If additional information is attached, list number of pages: | |
| Signature of Purchaser of Property or their Designee: | e: |
| SPCS/T-4 (Rev. 09/01/07) | |