

8616 Daffodil St Houston TX 77063 (Office) (713) 723-4215 (Fax) (713) 723-3334

E-Mail office@foxinspectiongroup.com

Company TPCL # 0575464 Certified Applicator TPCL # 0704820 Technician TPCL # 0587102, 0745495, 0764144, 0772213, 0772220, 0772221, 0772384

Report Number: 200507TTTJMc-21515 Pebble Pine Court

Repor	t Prepared for Jason Baldwin
•	Thursday, May 7, 2020
Conta	
Ooma	ot II.
Insped	ction Address: 21515 Pebble Pine Court
'	Cypress, TX 77433
	<u>9441000; 17.11400</u>
Prope	rty was <u>Occupied</u>
	present during inspection: No
	anty Offered: Yes
vvaria	inty Official. —Tes
Insne	ctor: John McElroy
	ctor Licence No.: TPCL: 0587102
mspec	Stor Licence No <u>IPCL: 038/102</u>
Te	xas Termite Terminators Additional Statements Included in the Scope of Inspection Agreement that are not
10.	Promulgated by the Texas Department of Agriculture
A.	This inspection is only good for the date and time of the inspection. Texas Termite Terminators, its Inspectors,
	employees and agents will not guarantee or warrant the absence of any wood destroying insect. Due to the
	characteristics and behavior of various wood destroying insects, the insects may not be visible or detectable on the date
	and time of the inspection. Even with the best inspection, termites can remain hidden and unnoticed for a long period of time. Swarming of wood destroying insects can occur in a short amount of time and may by the first signs of the presence
	of wood destroying insects that were not detectable at the time of the original inspection. If swarming occurs after the
	date and time of the original inspection and active wood destroying insects were not detectable at the time of the original
	inspection. Texas Termite Terminators, its Inspectors, employees and agents cannot be liable for the non-detectable
	infestation and will not assume any liability for corrective actions needed and will not assume liability for non-detectable /
	hidden wood damage.
B.	Texas Termite Terminators Standard Operational Inspection Procedures: The Inspector will perform a visual inspection of
	the visible and accessible foundation perimeter beam (slab-on-grade foundation), visual inspection of the visible and
	accessible exterior perimeter beam and accessible interior perimeter beam and piers (pier-&-beam foundation), probe visible and accessible exterior wood for active or signs of previous activity of a wood destroying insects, visual inspection
	of the structures accessible interior walls, ceiling, baseboards and cabinetry and visual inspection of the accessible areas
	of the attic.
	The inspector will not deface the structure, cut holes, remove panels, pull back carpet, lift floor treatments, cut holes in
	the floors, wall or ceilings, move boxes, furniture, personal items or effects. The inspector will then complete this WDIR
•	using the SPCB required standards for completing this form. These standards can be provided to you upon request.
C.	Additional Information from Texas Termite Terminators. AREAS OF POTENTIAL NON-VISIBLE WOOD
	<b>DESTROYING INSECT ACTIVITY AREAS ARE LISTED BUT NOT LIMITED TO THE FOLLOWING:</b> In the wall voids at the bathroom bathtraps and shower stalls/enclosures, plumbing penetrations within the construction wall voids, below
	high soil lines, behind heavy foliage, non-visible slab joints, non-visible slab cracks, under and/or behind decks and/or
	raised patios, behind cosmetic repairs of the foundation beam, within sill plates and between sub-floors and any other
	and that the legerates made as increasible in certific CD of this report Toyon Townite Towningtons and its legerates.

employees and agents will not assume any liability for active infestation of a wood destroying insect that is not visible

The Inspector will do his/her best to access and to inspect all accessible and visible areas and/or components of the structure. This inspection is only good for the date and time of this inspection and Texas Termite Terminators, its Inspectors, employees and agents will not assume any liability for non-accessible areas and non-visible wood destroying insects. If for any reason you are unhappy with the performance of the Inspector, his/her findings or unwilling to accept

the scope of this inspection. Texas Termite Terminators will be more than happy to refund to you the cost of this inspection within 90 day's from the date of the original inspection. The refund is contingent on you surrendering all copies of this inspection report back to Texas Termite Terminators and you releasing Texas Termite Terminators, its employee and its agents from all future liabilities to the inspected property. This refund cannot be made if the report has already

and/or accessible to the Inspector at the time of the original inspection.

been used to close on a real estate transaction.

D.

## TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT Page 1 of 2 21515 Pebble Pine Court <u>Cypress</u> 77433 Zip Code Inspected Address **SCOPE OF INSPECTION** This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate В removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company C. cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment, has rendered the pest(s) inactive. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present. D. E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not eng qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qua THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS. neers or builders performed by a qualified expert. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such G information to any person other than the contracting party. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options. Η. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. J. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture 1B. **TPCL #0575464** 1A. Texas Termite Terminators SPCS Business License Number 1C. 8616 Daffodil St **Houston** 77063 (713) 723-4215 TX Address of Inspection Company 1D. John McElroy TPCL: 0587102 Certified Applicator (check one) 1E. Name of Inspector (Please Print) Techniciar 3. Thursday, May 7, 2020 N/A Case Number (VA/FHA/Other) Inspection Date 4A. Jason Baldwin Seller ☐ Agent ☐ Buyer ☑ Management Co. ☐ Other ☐ Name of Person Purchasing Inspection N/A 4B. Owner/Seller 4C. REPORT FORWARDED TO: Title Company or Mortgagee Purchaser of Service ✓ Seller □ Agent $\square$ Buver 🗹 (Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy) The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Structural Pest Control Service. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected One story, Single family residence List structure(s) inspected that may include residence, detached garages and other structures on the property. (Refer to Part A, Scope of Inspection) 6A. Were any areas of the property obstructed or inaccessible? (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 6B. No □ Yes 🗹 6B. The obstructed or inaccessible areas include but are not limited to the following: Insulated area of attic $\square$ Plumbing Areas $\checkmark$ Planter box abutting structure П Deck Sub Floors Slab Joints Crawl Space Soil Grade Too High П $\square$ $\overline{\mathsf{A}}$ Heavy Foliag $\square$ Specify: Bath traps, Behind debris piled next to the structure, Behind personal effects/furniture, Othe Blocked/Stored areas, Construction voids, Foundation corner pops, Cracks in the slab, Under floor coverings, Behind storage in garage, Raised concrete, Brick and/or Stone at patio / porche(s), Foundation plumbing penetrations, 7A. Conditions conducive to wood destroying insect infestation? (Refer to Part J, Scope of Inspection) If "Yes" specify in 7B. Yes $\square$ No ☑ 7B. Conducive Conditions include but are not limited to: Wood to Ground Contact (G) Formboards left in place (I) $\ \square$ Excessive Moisture (J) П П Debris under or around structure (K) Footing too low or soil line too high (L) Wood Rot (M) П Heavy Foliage (N) Wood Pile in Contact with Structure (Q) □ Wooden Fence in Contact with the Structure (R) Planter box abutting structure (O) Insufficient ventilation (T) 8. Inspection Reveals Visible Evidence in or on the structure: Active Infestation Previous Infestation **Previous Treatment** Yes 🗆 Yes No 🗹 8A. Subterranean Termites Yes 🗆 No 🗹 No 🗹 Yes 🗆 Yes No 🗹 No ☑ Yes No ☑ 8B. Drywood Termites Yes 🗆 Yes 🗆 Yes No ☑ 8C. Formosan Termites No 🗹 No 🗹 Yes 🗆 No ☑ Yes 🗆 No 🗹 Yes 🗆 No ☑ 8D. Carpenter Ants 8E. Other Wood Destroying Insects Yes 🗆 Yes 🗆 Yes No No ☑ No Specify: N/A 8F. Explanation of signs of previous treatment (including pesticides, baits, existing treatment stickers or other methods) identified: None visible at the time of inspection 8G. Visible evidence of: None visible at the time of inspection has been observed in the following areas: N/A If there is visible evidence of active or previous infestation, it must be noted. The type of insect(s) must be listed on the first blank and all identified infested areas of the property inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspection)

TEXAS OFFICIAL WOOD DESTROYING INSECT REP	ORI	Page 2 of 2
The conditions conducive to insect infestation reported in 7A & 7B:  1. Will be or has been mechanically corrected by inspecting company:	Yes 🗆	No 🗹
f "Yes", specify corrections: <a href="M/A">M.A</a> A. Corrective treatment recommended for active infestation or evidence of previous infestation with no prior treatment as identified in Section 8. (Refer to Part G, H and I, Scope of Inspection)  B. A preventive treatment and/or correction of conducive conditions as identified in 7A & 7B is recommended as follows:  Specify reason: <a href="M/A">M/A</a>	Yes ☐ Yes ☐	No ☑ No ☑
Refer to Scope of Inspection Part J  OA. This company has treated or is treating the structure for the following wood destroying insects: N/A		
treating for subterranean termites, the treatment was:  Partial  Spot  Limited  Bail  treating for drywood termites or related insets, the treatment was:  N/A  N/A  N/A		Other
his company has a contract or warranty in effect for control of the following wood destroying insects:  Yes □ No □ List Insects: <b>N/A</b>		
If "Yes", copy(ies) of warranty and treatment diagram must be attached.  Diagram of Structure(s) Inspected		
he inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infest vidence of infestation; A-Active; P-Previous; D-Drywood Termites; S-Subterranean Termites; F-Formosan Termites; C-Carpenter Ants; Other(s) - Specify	ation and type of i Conducive Condition	nsect by using the following codes ons; B-Wood Boring Beetles; H-
8'		
20'20'		
34'		
	50'	
	Ĩ	
20'20'	+	
**		
18'		
	<del>\</del>	
dditional Comments		
either I nor the company for which I am acting have had, presently have, or contemplate having any interest in the prope nich I am acting is associated in any way with any party to the transaction.	erty. I do further si	ate that neither I nor the compan
gnatures: Notice of Inspection Was Posted	_	
TPCL: 0587102 12A. Electric Breaker Box Water Heater Closet		
Inspector Bath Trap Access pproved: Beneath the Kitchen	□ Sink ☑	
1B. Progre <u>TPCL# 0704820</u> 12B. Date Posted <u>Ma</u>	ny 7, 2020 Date	
Certified Applicator and Certified Applicator License Number  Statement of Purchaser  ave received the original or a legible copy of this form. I have read and understand any recommendations made. I have not not that my inspector may provide additional information as an addendum to this report.		nderstand the "Scope of Inspection
gnature of Purchaser of Property or their Designee  Date		



8616 Daffodil St. Houston TX 77063

TDA TPCL 0575464

Office: (713) 723-4215

Fax: (713) 723-3334

office@houstontexastermite

## **Eastern Subterranean 90-Day Free Protection**

(Convertible to Lifetime)

TEXAS TERMITE TERMINATOR PROTECTION PLAN

Client

Jason Baldwin

Address

21515 Pebble Pine Court

City, State, Zip Cypress, TX 77433

Effective Date May 7, 2020

(Effective date is date of initial inspection and the 90T<sup>3</sup>P<sup>2</sup> must be processed in accordance with the terms on the reverse side.)

## **Eastern Subterranean Termite Infestation**

Texas Termite Terminators or it's designee has inspected the building noted above for the purpose of determining visible evidence of Wood Destroying Insects, as defined by the Texas Department of Agriculture. Texas Termite Terminators or it's designee has provided a written report of its findings to the client. That report and the Limited Warranty are subject to the terms and condition of the Inspection Agreement, as well as the Scope and Limitations of the Limited Warranty. The parties agree that the liability of Texas Termite Terminators is as follows:

If Eastern Subterranean Termites are visually observed while this 90 day FREE Protection (Convertable to a Lifetime Renewable Termite Treatment Protection) is in good standing, Texas Termite Terminators will have the infestation treated as is determined by the terms of this agreement. Any areas having "Conducive Conditions" as noted in the written report are exempt from this coverage unless remedied and reinspected by Texas Termite Terminators (a re-inspection fee may apply).

GENERAL TERMS, SCOPE, AND LIMITATIONS ARE SET FORTH ON PAGE TWO OF THIS CERTIFICATE

