

## Roto-Rooter Services Company Remittance Address: 5672 Collections Center Drive Chicago, IL 60693

JIMMY MALITZ MPL # 18592 ALL CALLS ANSWERED & DISPATCHED FROM 1003 OAK CREEK DRIVE

INVOICE DATE	P.O. NUMBER
4/20/18	011279
INVOICE NUMBER	SERVICE DATE

â	Ħ	1	ě	_	۰
п	ы	ı.	u	u	ä

#### Service Address:

DREW BRAMLETT 1710 WESTMERE CT HOUSTON, TX 770774943

DREW BRAMLETT 1710 WESTMERE CT HOUSTON, TX 770774943

JOB CODE	DESCRIPTION OF SERVICE PERFORMED	GUARANTEE
0407	Repair by the open-cut hand-dig process designated underground pipeline with new pipe and fittings from 2 predetermined points. All work is done in accordance with local plumbing code and OSHA regulations.	FIVE YEARS

LABOR \$ 1,214.13
PARTS \$ 110.32
OTHER \$ 7,014.55
PRODUCTS \$ 61.00

Call 713-934-8208 or email MONICA.GONZALES@RRSC.COM

## **Need Service?**

Call 1-800-GET-ROTO (438-7686) 24 Hours a Day, 365 Days a Year

INVOICE AMOUNT \$ 8,400.00

NO OVERTIME CHARGES FOR NIGHTS, WEEKENDS OR HOLIDAYS!

TERMS: Net 10 days

TOTAL DUE \$ 8,400.00

Thank you for choosing Roto-Rooter!

### Bill to:

DREW BRAMLETT 1710 WESTMERE CT HOUSTON, TX 770774943

### Service Address:

Method of Payment:

Check #\_

DREW BRAMLETT 1710 WESTMERE CT HOUSTON, TX 770774943

INVOICE NUMBER	TOTAL DUE
04520171232	\$8,400.00

#### Remit to:

Roto-Rooter Services Company 5672 Collections Center Drive Chicago, IL 60693



Master Card VISA	☐ Discover ☐ Am Ex
Card #	
Evoiration Date	

Authorized Signature

(Please return stub with payment)









## SAVE THIS INVOICE FOR TOUR GUARANTEE SEE BINDING TERMS ON REVERSE

Roto-Rooter Services Company
Remit to: 5672 Collections Center Drive, Chicago IL 60693-0056
For Service Please Call 1-800-GET-ROTO (438-7686)
General (281) 509-9713 • FAX (281) 280-0413

DATE OF SERVICE	HOUSTON
SERVICE TECHNICIAN'S NAME	2590#
45- 20/71	237

-800-GET	RATA	3403	General North Sam Ho	ouston P	kwy. We	• FAX (281 est, Ste. 40 MPL #1859	0, Houst		7086	45-	201712	232	
	8 7686) <sub>nor</sub>	Tex	as State Board Box 420	of Plum	bing Ex		929 East		, PO	SEWER & DRA	NN PLUMBIN	IG F	PUMPING
CONTRACTOR NAME	ran	ett	q ayumi lenos	toq (in) 3	HOH 3.1	RIENOS	CUSTOME	R NO.	e we	EV1	CUSTOMER CLASS		MMERCIAL
BILLING ADDRESS	COMMON CHILL	سرور	CE CI	DECINE PS MO	Val. Ch	PLASERS	BL WA	APT. NUI	MBER	CLEVITO	FEDERAL I.D.		A STOREGISTORY
CITY	History A. 18	NG D		TE/PROVIN	CE :	ZIP/POSTAL	77	CUSTOME	R PHON	ENO.	P.O. NUMBER		And in concession with the same
SERVICE ADDRESS (IF I	DIFFERENT THA	N BILLING	3 ADDRESS)	11	DESCRIPTION OF STREET	. (0		CITY	ATT.	<del>ly Lobe</del>	STATE/PROV	NCE ZIP	/POSTAL
WORK ORDER AL including the limits of stuck in a pipe, I ma (SIGNATURE)	on Roto-Roote y be respons	er's responder to	onsibility specifie ne cost of removi	d in those	terms. I quipment	acknowledg , including a (PRINT	je that und ny require NAME) \(\lambda\)	der parag ed excava	raph 2( tion.	b) of those ter	ms, if Roto-Roote	er equipme	ent gets
REPAIR CODE	is	ND DESC						-			<ul> <li>and the approxements</li> </ul>		
	Revo	Luc	e Kile	Various and	ad	wegl	er l	من	20		~>00v~	-	\$ AMOUNT
If we receive, if	FO	سدعسه	- Serve	1	س	1 3 Sm	200	V h	on	A	and the street	d	13011
adi ob ratho no	allos rop	Ewcay)	cognition of	M38831110	nobnu	AT THE PARTY OF	Tentaka:	asyon.	-(Line)	4	digamb, data	DE(N)	12161.
p. oc. impropor.	chang parto	24701 A	late to number	RITE SECTE	ideng b	tot apply t	1.00. 35.01	nermh).	inem	ked noa pu	1107 TO 1203 100	RF 20 10	ohege strovi
SOUTHWAY SUB-	S OF IDARIE	politican Clubbi	BORGER BANKS	Sancane:	AND MEN	EDWIN OF BOL	relity size	MULUI EQ	(190 H)	LENGTH W	o do sen hotele	HILLS IN S	ACTURATED O
ADJUSTMENTS/	CHANGES I	N WOR	K TO BE PERF	ORMED	(Use add	ditional invo	ice if nee	ded to d	escribe	e changes)	cannoning to	OUTIN HIL	ED EDIRON
Occurred Circumstance	CONTRACTOR	e mere	farente ettert a	Ansvar	SUBCLINE.	MARK CONTIN	AND STREET	BA BU	Notes III	III BUOKA	remarano ( 22	CHOLDSAN	COL TRE-UNI
RESIDENTIAL GU	ARANTEE	COMM	MERCIAL GUARA	ANTEE			PAYMEN	ντ					1 120
LABOR	M. W. G. STATE D. W. C.	em en	LABOR	OO days	OUBSIDE	Maria Peri	DODS/VEG	NOT LION	HD1440E	margar.	LABOR \$	13.9	161
Main/Branch Lines Toilet Auger	6 months 7 days		n/Branch Lines tt Auger	30 days 24 hours		лен 🔲 с	CHECK NO	NSSON	100	TERMAN E	PHILL SP TE	THE L	an lanasa
Plumbing Repair	6 months	-	nbing Repair	90 days		REDIT CARD	2 22	T 10 DA		NAGES.	LABORTAX\$_	1 11	(09a) I
Plumbing Replacen		=-	nbing Replacement			DAYS = LAT					PARTS \$ _	Trees Const	
Extended Guarante		cvent	om I neinse	an sie		ated bank fees	-	N TO	in is res	polisible	DISCOUNT \$ _	<u>55</u>	61. 5
REASON FOR NO GUAR	ANTEE	30110	ISOTON DV O	guida	W.5W.(5	ib silw	000018879	1 30	ar wid	in toy it	PRODUCTS \$ _		
COMPLETION I ac	knowledge co	omoletic	on of the above o	described	work wi	hich has be	en done t	o my cor	nolete	satisfaction	ALTO DO CONT.	un illi	to Log IX II
SIGNATURE)	Ad	39	A	55V0 TU	II presu		arronga mu ue m		10: 11 110:58	zena of o	TAX\$_		1
(PRINT NAME)	AND	250	Beau	LET	ofte mi	nobi ava	s clds	ettin) o		CERT HIS DOR	TOTAL \$_	3 /0	
SUGGE	STIONS FOR	REPAIR .	/ REPLACEMENT			FROM	O/S OR TI	RUCK	1		PARTS US/	AGE	
ITEM	LOCATI	ON	ESTIMATED COST	YOU SA		VENDOR	PART #	OTY	T/ OS	DESC	CRIPTION	TOTAL	SELL
MATER HEATER					Children and								

TOTAL TO A STATE OF THE PARTY O										
ITEM	LOCATION	COST	YOU SAVE TODAY							
WATER HEATER	ha has y loor	dynation avii	unvilla n							
DISPOSER		verifien.	b to nigi							
SINK										
TOILET			NIEDWC							
BATHTUB	ING A IIIL	The opening of	ave 8m h							
SHOWER										
FAUCET		- 9 0	F- 0							
DRAIN A										
OTHER		AND REAL RESIDENCE								

Screnje

	U/S UR IF	10011	V	171110 001	PANTS USAGE		
VENDOR	PART #	OTY USED	T/ OS	DESCRIPTION	TOTAL COST	SELL PRICE	
are had	1037700	tniiraa	DROF	ional or a'n More were	ES 70 75	are at an	
183117.0	moight	Lurolo.	7735	deals without regard to	est miller	myolgens	
1							
CAR S	AT BUSE S	V BYALD			11		
#3 110 T	- K00	Marria	11,4%	Bun a damen.			
		130	44 ( 8)	ili anti all'internati	T)		
n.							
2000		ii tali		racinitadisa.			
	C THE U	1.6.2.2.1	Li Li e	TOTALS			

(CLERK'S SIGNATURE)

OFFICE COPY

45-317028

INV-BR-TC1-3(8/17)

4,



# **EXCAVATION PROPOSAL**

Date 4-11-18
Ticket No. 45-2017-1232

**Roto-Rooter Services Company** For Service Please Call 1-800-GET-ROTO (438-7686)

General (281) 509-9713 • Fax (281) 260-0413 3403 North Sam Houston Pkwy. West, Ste. 400, Houston TX 77086

Jimmy Malitz, MPL #18592

Texas State Board of Plumbing Examiners, 929 East 41st St., PO Box 4200 Austin TX 78765 · (800) 845-6584

		Submitted To		Performed At
Nan	0.0.0		Name	III letroneste int inchio isso
	TI A TOTAL T	nere et	Street	OW THE PURPOSE SHEET PROPERTY
City	1100000	ZIP	City	710
Stat		ZIP / T		ZIP
-	ephone Number		Telephone Number	
			SINK and well . A	
	Marin Marin Control Volta EVEN AV SON OF THE	A Commission Affects of the Commission Affec	E SOR COMMITTED AND COMMITTED	\$ 8400.
1.	Roto-Rooter will perform the Customer will make payment		and supply all required materials for the	sum of \$
	A STATE OF THE PARTY OF THE PAR		upon execution of this Agreement.	
	L Mg Manual warmer surfaces	Sall and the sale of the sale	THE PROPERTY OF THE PROPERTY O	
	% 0	f the cost (\$)	upon the start of the work.	
	<ul> <li>Balance of the cost u</li> </ul>	pon completion of the job	SHIM NEED IN LINES I BEN FO	
2.	The approximate starting di Neither date is guaranteed	ate is	, and the approximate substantial com problems could cause delays. A definite of	pletion date isof the essent
3.	Roto-Rooter guarantees the practice and in a good, wo	nat all materials will be as orkmanlike manner.	specified above and that all work will be	completed according to standard
4.	is not responsible for the r driveways, or the repair of level and mound it to allow	removal of trees, sprinkle streets, sidewalks and the w for settlement, and (c) (	rights of way. Unless specifically stated r systems, underground and above grou e like, (b) Roto-Rooter will back fill and g Customer is responsible for all landscap oter is not responsible for damage resul	nd fencing, rocks, sidewalks or grade the excavated area to grous ing repairs or replacements
5.	the restriction. After we ha to be done, or a complete for the additional work ma	we uncovered that area, we sewer line replacement is yet be significantly higher the significant signific	ne, we will give you a price to repair the seve will attempt to inspect the rest of the ses required, we will propose a price to propose and the original proposal. If you decide not and back fill any excavation.	sewer line. If additional work need perly complete the work. The price
6.			ed or customer requests additional or dit a new written work description before Ro	
7.	THE TERMS AND COND	ITIONS ON THE REVERS	SE SIDE OF THIS PROPOSAL WILL BE	BINDING ON THE PARTIES.
8.	This proposal may be with		not accepted within days. This prons will be valid unless in writing and sign	pposal constitutes the entire ed by both parties.
Des	81 . A T CN 199	Z Fee Manuagen	HER THE SHAPER AND WILLIAM	
HOC	spectfully submitted:		and the state of the state of the best of the state of th	mare (III) wall (III)
1162	Jan Malita		JIMMY MALITZ	- 4-11-18
L	chnicia Signature	•	Printed Name/Technician Number	Date
L	Annicial Oignature			
L	Similar digitation	T. C. III AND THE STATE OF THE	TANCE OF PROPOSAL	±4000000000000000000000000000000000000
Tecl	uthorize the services indicate	d and agree to pay the a	PTANCE OF PROPOSAL mounts specified. I have read and agree	to the terms, including the limits
Tecl	uthorize the services indicate	d and agree to pay the a led in those terms. I acknow	mounts specified. I have read and agree ledge that under paragraph 2(b) of those term	to the terms, including the limits on the terms, including the limits on the terms, if Roto-Rooter equipment gets studies.
Tecl	uthorize the services indicate	d and agree to pay the a led in those terms. I acknow	mounts specified. I have read and agree	to the terms, including the limits on the terms, including the limits on the state of the terms, if Roto-Rooter equipment gets studied to the terms, including the limits of the terms.

**OFFICE COPY** 



# **VIDEO INSPECTION OF** SEWER LINE AND RECOMMENDED SERVICE OR REPAIR

Date

4-11-18

Ticket No. 45-2017-1232

**Roto-Rooter Services Company** For Service Please Call 1-800-GET-ROTO (438-7686)

General (281) 509-9713 • Fax (281) 260-0413 3403 North Sam Houston Pkwy. West, Ste. 400, Houston TX 77086 Jimmy Malitz, MPL #18592

Texas State Board of Plumbing Examiners, 929 East 41st St., PO Box 4200

	Customer	ven Branlett	Address	1710 Westn	verc	CT					
	Roto-Rooter box that app	has attempted to inspect your sewer line willies):	ith a video camera, and	you acknowledge the follow	ing (please i	nitial the					
Initials (One	X	We were unable to inspect the line by camera beca	use of obstructions, sewage	or water in the line.							
	X AMB	We were able to inspect the line by camera, and we	showed you a video feed ev	videncing the problem(s) noted below	ow.						
		Complete Collapse - The pipe has collapsed and ca		415							
		Broken, Cracked or Corroded - The pipe has deterior									
	A	Bellied Pipe - A section of pipe has sunk due to gro paper and waste.	und or soil conditions, creation	ng a valley or dip in the pipe that re	stricts flow and	collects					
		Leaking Joints - The seals between pipes have brothe pipe.	ken, disconnected or corrode	ed, allowing waste water to escape	into the areas s	urrounding					
		Blockages - Grease buildup or a foreign object is re	estricting or prohibiting prope	r flow and/or performance of the lin	e.						
		Punctured Pipe - A foreign object has perforated the									
	Comments	Root Infiltration - Tree or shrub roots have invaded	the sewer line.								
	Comments:			<u> </u>							
		SOLUTION									
nitials ly)		Cable or Jet Sewer Line - Roto-Rooter will clean the line either with a mechanical blade and cable or a high-pressure water jet. PLEASE NOTE: This is a temporary solution and will not address the underlying problem with the pipe. There is high likelihood that the line will back up again in the future. When that will happen cannot be determined at this time.									
Customer Initials (One Only)		Spot Repair - Roto-Rooter will repair or replace a set the line. If we discover problems in other parts of the estimate for any additional required work.	ection of the sewer line. We we line during this work, we wi	will jet clean (when appropriate) and Il notify you, and at your request, pa	1 video the rema ovide a propos	ainder of al and cost					
Ö	Comments:	Full Line Replacement - Roto-Rooter will replace the	e sewer line between two (2)	agreed-upon points using one of the	ne following me	thods:					
			-								
			METHOD								
	A	Open Trench - The existing line will be excavated, regrade to allow for settling.	emoved and replaced with no	ew pipe and clean-out. The trench	will be backfilled	d above					
		Pipe Lining (if permitted by local authority) - A new plot this method.	pipe sleeve will be installed in	nside the problem line. Minimal ex	cavation may be	required					
		Pipe Bursting (if permitted by local authority) - A new this method.	w pipe will be pulled through	the existing pipe. Some excavation	may be necess	sary for					
	Comments:	Leronte Kite	la, wester	live ad toil	et						
	1	and levelors sink	Ò	0 .		- Sales					
	Technician Signa	ature Pr	rinted Name/Technician Numb	Sovoye	4-11-	-18					
		ssed all solution options with Roto-Roote			Date ddressing th	is					
	problem.	0.11	10 -	4							
	M		16	71		1-18					
	Customer Signal	ture Y	inted Name		Date						