


NORTH

SCALE: 1" = 30'

OLD TIMBER LANE
(50' R.O.W.)



LEGEND

--//-- WOOD FENCE

NOTES:

- 1) THIS SURVEY HAS BEEN PREPARED FROM INFORMATION CONTAINED IN THE TITLE COMMITMENT REFERENCED IN GF NO. 150-120201674-201, EFFECTIVE 04-29-12.
2) ALL BEARINGS ARE BASED ON THE RECORDED PLAT UNLESS OTHERWISE NOTED.
3) FLOOD ZONE DETERMINED BY GRAPHIC PLOTTING ONLY. WE DO NOT ASSUME RESPONSIBILITY FOR EXACT DETERMINATION.
4) SUBJECT TO RESTRICTIVE COVENANTS BY FILM CODE NO. 617240, H.C.M.R. AND H.C.C.F. NOS. R810998, U506056, Y977999, 20060212987, 20100173339, 20110282019, 20110282020, 20110488707, 20110488709, 20110510428, 20110546445, AND 20110546449.
5) THIS SURVEY IS NOT FOR FUTURE CONSTRUCTION PURPOSES.
6) OVERHEAD/UNDERGROUND ELECTRIC SERVICE AGREEMENT BY H.C.C.F. NO. 20060064061.
7) PROVISIONS FOR PARTY WALLS BY H.C.C.F. NO. 20060212987.
8) THIS SURVEY IS VALID ONLY WITH ORIGINAL SIGNATURE IN BLUE INK.
9) SITE LIES WITHIN THE BOUNDARIES OF HARRIS CO., M.U.D. NO. 383.
10) ENGINEERING, ARCHITECTURAL AND JURISDICTIONAL REQUIREMENTS AND GUIDELINES WERE NOT INVESTIGATED, RESEARCHED, OR EXAMINED FOR THIS SITE.
11) FENCE LOCATIONS SHOWN HEREON ARE FROM APPROXIMATE CENTER & ARE SUBJECT TO CHANGE DUE TO ENVIRONMENTAL CONDITIONS, WARPING, LEANING, CHANGES FROM RECONSTRUCTION, ETC. FENCES MAY MEANDER BETWEEN MEASURED LOCATIONS.

Table with 3 columns: LINE, BEARING, DISTANCE. Contains lines L1, L2, L3, L4 with bearings and distances.

BUYER'S ACKNOWLEDGMENT

George R. Simons

Manda B. Simons

Table with columns: LOT, BLOCK, SECTION, SUBDIVISION, FLOOD NOTE, RECORDATION, COUNTY, STATE, SURVEY, LENDER CO., TITLE CO., PURCHASER, ADDRESS, JOB NO.

© COPYRIGHT 2012 WINDROSE LAND SERVICES, INC. ALL RIGHTS RESERVED.

Table with columns: FIELD WORK, DRAFTED BY, CHECKED BY, KEY MAP NO., REVISION.




I do hereby certify for this transaction only, that this survey under my supervision was this day made on the ground and that this plat correctly represents the property legally described hereon (or on attached sheet). That the facts found at the time of this survey show the improvements and that there are no visible encroachments apparent on the ground, except as shown, to the best of my knowledge.

Signature of surveyor


Windrose Land Services, Inc.
3200 Wilcrest Drive, Suite 325
Houston, Texas 77042
Phone (713) 458-2282 Fax (713) 461-1151

Professional Development Consultants
Land Surveying, Platting, Project Management, GIS Services



NORTH
SCALE: 1" = 30'

OLD TIMBER LANE
(50' R.O.W.)



NOTES:

- 1) THIS SURVEY HAS BEEN PREPARED FROM INFORMATION CONTAINED IN THE TITLE COMMITMENT REFERENCED IN GF NO. 150-120201674-201, EFFECTIVE 04-29-12.
- 2) ALL BEARINGS ARE BASED ON THE RECORDED PLAT UNLESS OTHERWISE NOTED.
- 3) FLOOD ZONE DETERMINED BY GRAPHIC PLOTTING ONLY. WE DO NOT ASSUME RESPONSIBILITY FOR EXACT DETERMINATION.
- 4) SUBJECT TO RESTRICTIVE COVENANTS BY FILM CODE NO. 617240, H.C.M.R. AND H.C.C.F. NOS. R810998, U506056, Y977999, 20060212987, 20100173339, 20110282019, 20110282020, 20110488707, 20110488709, 20110510428, 20110546445, AND 20110546449.
- 5) THIS SURVEY IS NOT FOR FUTURE CONSTRUCTION PURPOSES.
- 6) OVERHEAD/UNDERGROUND ELECTRIC SERVICE AGREEMENT BY H.C.C.F. NO. 20060064061.
- 7) PROVISIONS FOR PARTY WALLS BY H.C.C.F. NO. 20060212987.
- 8) THIS SURVEY IS VALID ONLY WITH ORIGINAL SIGNATURE IN BLUE INK.
- 9) SITE LIES WITHIN THE BOUNDARIES OF HARRIS CO. M.U.D. NO. 383.

LEGEND

—//— WOOD FENCE

LINE	BEARING	DISTANCE
L1	N 58°51'45" E	35.33'
L2	S 31°15'34" E	109.92'
L3	S 58°44'26" W	35.33'
L4	N 31°15'34" W	110.00'

- 10) ENGINEERING, ARCHITECTURAL AND JURISDICTIONAL REQUIREMENTS AND GUIDELINES WERE NOT INVESTIGATED, RESEARCHED, OR EXAMINED FOR THIS SITE.
- 11) FENCE LOCATIONS SHOWN HEREON ARE FROM APPROXIMATE CENTER & ARE SUBJECT TO CHANGE DUE TO ENVIRONMENTAL CONDITIONS, WARPING, LEANING, CHANGES FROM RECONSTRUCTION, ETC. FENCES MAY MEANDER BETWEEN MEASURED LOCATIONS.

BUYER'S ACKNOWLEDGMENT

Burgard Simons

Wanda B. Simons

LOT 9	BLOCK 2	SECTION 1	SUBDIVISION ARBORS OF GLEANNLOCH AMENDING PLAT NO. 1
RECORDATION FILM CODE NO. 617240, H.C.M.R.	COUNTY HARRIS	STATE TEXAS	SURVEY A-168
LENDER CO. -	TITLE CO. DHI TITLE COMPANY		
PURCHASER -	ADDRESS 9723 OLD TIMBER LANE		JOB NO. 48376

FLOOD NOTE
ACCORDING TO THE FEDERAL EMERGENCY MANAGEMENT AGENCY (FEMA) FLOOD INSURANCE RATE MAP (FIRM) FOR HARRIS COUNTY, TEXAS. MAP NO. 48201C 0240L, DATED JUNE 18, 2007. THE SUBJECT TRACT APPEARS TO LIE WITHIN UNSHADED ZONE "X". THIS DETERMINATION WAS DONE BY GRAPHIC PLOTTING AND IS APPROXIMATE ONLY AND HAS NOT BEEN FIELD VERIFIED. THIS FLOOD STATEMENT DOES NOT IMPLY THAT THE PROPERTY OR STRUCTURES THEREON WILL BE FREE FROM FLOODING OR FLOOD DAMAGE. ON RARE OCCASIONS FLOODS CAN AND WILL OCCUR AND FLOOD HEIGHTS MAY BE INCREASED BY MAN-MADE OR NATURAL CAUSES. THIS FLOOD STATEMENT SHALL NOT CREATE LIABILITY ON THE PART OF WINDROSE LAND SERVICES, INC.


© COPYRIGHT 2012 WINDROSE LAND SERVICES, INC. ALL RIGHTS RESERVED



I do hereby certify for this transaction only, that this survey under my supervision was this day made on the ground and that this plat correctly represents the property legally described hereon (or on attached sheet). That the facts found at the time of this survey show the improvements and that there are no visible encroachments apparent on the ground, except as shown, to the best of my knowledge.

FIELD WORK	10-11-12	DB
DRAFTED BY	10-12-12	DH
CHECKED BY	10-12-12	DG
KEY MAP NO.	329 C	

REVISION	
-	-
-	-



[Signature]

Windrose Land Services, Inc.
3200 Wilcrest Drive, Suite 325
Houston, Texas 77042
Phone (713) 458-2282 Fax (713) 461-1151

Professional Development Consultants
Land Surveying, Platting, Project Management, GIS Services