




PRECISION Surveyors

NORTH RIDGEWAY DRIVE (CAPPED) M 10.24.01 M LOT 3 []₹ POWER ¥SS IRON ROD CABINET A SHEET 117A M.C.M.R. LOT 2 SON 2-STORY WOOD FRAME RESIDENCE 82.9' 0.5 SEPTIC O O O O LOT 30 DAVID COOK ET UX DOC. NO. 2015062445 CONC FENCE. IRON ROD >\s\s\ 194.09 LOT 31 CONC. 4 50.5 0.2 BARN COVC 2002 1 107 CONC. AREA. POOL 1.8' .S#.TT S 00"52"40" W 142.00 FOUND (C.M.) CHARLES E PARSLEY, JR. DOC. NO. 2005038946 FENCE



0.5803 ACRE BEING ALL OF LOT 31, BLOCK 4 GF NO. 75243-GAT86 GREAT AMERICAN TITLE ADDRESS: 12148 NORTH RIDGEWAY DRIVE WILLIS, TEXAS 77318 BORROWER: BETTY SUROWIEC

ACCORDING TO THE MAP OR PLAT THEREOF RECORDED IN CABINET A, SHEET 11B OF THE MAP RECORDS OF MONTGOMERY COUNTY, TEXAS TOGETHER WITH A TRACT OF LAND LOCALED O.587 ACRE RECORDED IN VOLUME 461, PAGE 1705 OF THE DEED RECORDS OF MONTGOMERY COUNTY, TEXAS (SEE ATTACHED METES AND BOUNDS) LAKEVIEW MANOR, SECTION 1



NOTE: TELEPHONE EASEMENT PER CF NO. 8410208. NOTE: EASEMENT TO GULF STATES UTILITIES CO. PER CF NO. 8805798.

THIS PROPERTY DOES NOT LIE WITHIN THE 100 YEAR FLOOD PLAIN AS PER FIRM PAUEL NO. 48339C 0225 G LAP REVISION: 08/18/2014

BASED ONLY ON VISUAL EXAMINATION OF MAPS. INACCURACIES OF FEMA MAPS PREVENT EXACT DETERMINATION WITHOUT DETAILED FIELD STUDY.

A SUBSURFACE INVESTIGATION
WAS BEYOND THE SCOPE OF THIS SURVEY

D.C.L. = DIRECTIONAL CONTROL LINE
RECORD BEARING: DOC. NO. 2015062445 M.C.D.R.

I HEREBY CERTIFY THAT THIS SURVEY WAS MADE ON THE GROUND, THAT THIS PLAT CORRECTLY REPRESENTS THE FACTS FOUND AT THE TIME OF SURVEY AND THAT THERE ARE NO ENCROCHMENTS APPARENT ON THE GROUND, EXCEPT AS SHOWN HEREON, THIS SURVEY IS CERTIFIED FOR THIS TRANSACTION ONLY AND ABSTRACTING PROVIDED IN THE ABOVE REFERENCED TITLE COMMITMENT WAS RELIED UPON IN PREPARATION OF THIS SURVEY.



1-800-LANDSURVEY
www.precisionsurveyors.com

FAX 281-496-1867 210-8 SUITE 150 HOUSTON, TEXAS 27079 1777 NE FIRM NO. 10063700 210-829-4941 FAX 210-829-1555

281-496-1586 950 THREADNEEDLE 5