TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

1213 55th St	Galveston	77551
Inspected Address	City	Zip Code

SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.

F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.

- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). The warranty should specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by oither mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

1213 55th St	G	alveston			_	7755	51	
Inspected Address		City				Zip	Code	
1A. Ranger Termite Pest Control and	Inspections	1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B1B	7720	SPCS Business Li	cense Numbe	r		
Name of Inspection Compare	пу						740 407 0	200
1C. 24518 Hikers Bend Dr		Katy		tx State	77493		713-467-3 Telephone	lag .
Address of Inspection Com	bany	City		State	Zip		Telephone	NO.
1D. Vernon Gibson			1.E	Certified Applicato	r		(check one)	1
Name of Inspector (Please	Print)			Technician				
		1F. ^{06/1}	7/2023			12		
		Inspecti	on Date		1. 10.721			
2. Adrienne Duran			Seller	Agent D Buyer	Manageme	nt Co. 🔲	Other U.	
Name of Person Purchasing 3. Unknown	g Inspection							
Owner/Seller	Company or Mortgagee Control regulations only the p	Purchaser of Servic ourchaser of the servic	ce 🔳 ce is requir	Seller ed to receive a copy)	Agent 🗌]	Buyer 🛛	
The structure(s) listed below were insp	ected in accordance with the	official inspection pro	cedures a	dopted by the Texas De	partment of A	griculture St	tructural Pest	Control Servic
This report is made subject to the cond	itions listed under the Scope	of Inspection. A diag	ram must l	be attached including al	I structures ins	spected.		
5A. Residence								
List structure(s) inspected that may include	lude residence, detached ga	rages and other struct	ures on the	e property. (Refer to Pa	art A, Scope of	Inspection)	
5B. Type of Construction:	0							
Foundation: Slab D Pier & Beam	Pier Type: Cement Board Brick Stone	Basement	Other:					
	Shingle Metal Tile C							
6A. This company has treated or is trea	ting the structure for the follo	wing wood destroying	insects: N	lone		Other		
If treating for subterranean termites, the If treating for drywood termites or relate	e treatment was:	Partial	Spot Limite	L Bait		Other		
					Nono			
6B. None Date of Treatment by Inspe		None	man Nam	e of Insect	None	of Pesticide	, Bait or Other	Method
					- Calific C			
This company has a contract or warrar		following wood destro cts: <u>None</u>	ying insect	s:				
Yes 🔲 No If "Yes", copy(ies) of war	List Inse ranty and treatment diagra	m must be attached.						
Neither I nor the company for which I a				v interest in the purcha	se or sale of th	is property.	I do further s	tate that neith
I nor the company for which I am actin	g is associated in any way w	ith any party to this re	al estate tra	ansaction.				
Signatures: 7A. 0839394	ma							
Inspector (Technician or Certified A	pplicator Name and License	Number)						
Others Present:	\cdot		.)					
7B. 0827752 Apprentices, Technicians, or Certifie	d Applicators Name(s) and F	Registration/License N	umber(s)					
	\bigcirc							
Notice of Inspection Was Posted At or		Date Posted:		06/17/2023				
	□ 8B. □	Date Posted.						
Beneath the Kitchen Sink								
9A.Were any areas of the property obs (Refer to Part B & C, Scope of Inspect	structed or inaccessible? ion) If "Yes" specify in 9B.	Yes	•	No	Г			
9B.The obstructed or inaccessible are	as include but are not limited	to the following:			r hov abutt	otnicture	-	
Attic Deck	Insulated area of att Sub Floors	ic 🔲 Plumbi	ng Areas pints	Crawl	r box abutting Space			
Soil Grade Too High	Heavy Foliage	Eaves		Weep	noles			
Other 10A.Conditions conducive to wood de (Refer to Part J, Scope of Inspection)	Specify: <u>·</u> stroying insect infestation: If "Yes" specify in 10B.	Yes		No				
10B.Conducive Conditions include but								
	Wood to Ground			Formboards left in place Wood Rot (M)		xcessive Me eavy Foliag		
Debris under or around structure (K) Planter box abutting structure (O)		r soil line too high (L) ntact with Structure (Q		Wooden Fence in Conta				ŏ
Insufficient ventilation (T)	Other (C)	Specify:						
a (1)								
	• • • • • • • • • • • • • • • • • • •	a d Da avilata d has tha	Toyes De	partment of Agricultur	·A			
	Licensed a PO Box 12847, Aus	ing Regulated by the stin, Texas 78711-28	47 Phone	partment of Agricultur 866-918-4481, Fax 888	-232-2567			
SPCS/T-5 (Rev. 9/1/2020)	e est tradens of	88 (E)					Page	2 of 4
,,								

1213 55th St	Galveston	77551
Inspected Address 11. Inspection Reveals Visible Evidence in or on the structure: 11A.Subterranean Termites 11B.Drywood Termites 11C Formosan Termites 11D.Carpenter Ants 11E.Other Wood Destroying Insects Specify: 11F.Explanation of signs of previous treatment (including pestic	Yes No No Yes Yes Yes No Yes Yes Yes Yes No Yes Yes Yes Yes No Yes Yes Yes	No Image: Constraint of the state of the st
None		
11G.Visible evidence of: Carpenter beetle holes	has been observed in the following areas:	
If there is visible evidence of active or previous infestation, it mu inspected must be noted in the second blank. (Refer to Part D, 12A. Corrective treatment recommended for active infestation Scope of Inspection) 12B. A preventive treatment and/or correction of conducive con Specify reason: <u>None</u> Refer to Scope of Inspection Part J	E & F, Scope of Inspection) or evidence of previous infestation with no prior treatment as Yes ■ No □	identified in Section 11. (Refer to Part G, H, and
	Diagram of Structure(s) Inspected	
The inspector must draw a diagram including approximate perin Evidence of Infestation, A-Active; P-Previous; D-Drywood Term Carpenter Ants; Other(s) – Specify	neter measurements and indicate active or previous infestation	and type of insect by using the following codes: E- ucive Conditions; B-Wood Boring Beetles; H-
	a axpenter	ettes
Additional Comments		
<u> </u>	9.04	
		Page 3 of 4

213 55th St	Galveston		77551
Inspected Address	City		Zip Code
	Statemer	nt of Purchaser	
have received the original or a legible copy of this			I have also read and understand the "Scope of Inspection."
f additional information is attached, list number of r	nages:	this report.	
Signature of Purchaser of Property or their Designe	90	Date	-
Customer or Designee Not Present	Buyer's Initials	-	