

ENTERGY — 2 1/2 FEET ON EACH SIDE OF UNDERGROUND ELECTRIC SERVICE LINES AS NOW OR HEREAFTER UPON LOTS IN THE SUBDIVISION

PER M.C.C.F. NO. 2004095998.

4) CONTROLLING MONUMENTS FOR THIS SURVEY ARE A 5/8" IRON ROD FOUND MARKING THE SOUTHWEST CORNER OF SUBJECT TRACT, THROUGH A 5/8" IRON ROD FOUND MARKING THE NORTHWEST CORNER OF THE SUBJECT TRACT. SURVEY PREPARED FOR: MARK SANDERS

BEARING STRUCTURE BASED ON RECORDED PLAT OF SUNRISE RANCH, SECTION FOUR.

ACCORDING TO A GRAPHIC INTERPRETATION OF THE FLIR.M., THIS PROPERTY DOES NOT LIE WITHIN THE 100 YEAR FLOOD PLAIN, AND IT APPEARS THE ENTIRE TRACT LIES IN ZONE "X" ON FLIR.M. NO. 48339C0195F, DATED 12-19-96.

THE SURVEYOR HAS MADE NO REPRESENTATIONS AS TO WHETHER OR NOT THE SUBJECT PROPERTY WILL FLOOD AND RECOMMENDS THAT THE LOCAL FLOOD PLAIN ADMINISTRATOR BE CONTACTED PROPERTY OF THIS FLOOD INFORMATION FOR PROPERTY PURCHASE OR CONSTRUCTION.