

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2022
Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure

CONCERNING THE PROPERTY AT 1122 West Belgravia Drive, Pearland, TX 77584			_						
			_						
THIS NOTICE IS A DISCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PR AS OF THE DATE SIGNED BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTI WARRANTIES THE BUYER MAY WISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER'S AGENTS, OR ANY OTHER AGENT.	ONS	SC	R						
Seller ☐ is ☐ is not occupying the Property. If unoccupied (by Seller), how long since Seller has the Property? ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	occi ipiec	upie 1 th	ed ne						
Section 1. The Property has the items marked below: (Mark Yes (Y), No (N), or Unknown (U).) This notice does not establish the items to be conveyed. The contract will determine which items will & will not	con	vey.							
Item Y N U Item Y N U Item	Y	N	U						
Cable TV Wiring ☑ ☑ □ Liquid Propane Gas: □ ☑ □ Pump: □ sump □ grinder		W							
Carbon Monoxide Det. -LP Community (Captive) Rain Gutters	V								
Ceiling Fans □ □ □ □ -LP on Property □ □ □ □ Range/Stove	V								
Cooktop	V								
Dishwasher ☐ ☐ ☐ Intercom System ☐ ☐ ☐ Sauna									
Disposal ☑ □ □ Microwave ☑ □ □ Smoke Detector			V						
Emergency Escape Outdoor Grill Smoke Detector – Hearing Ladder(s)		□							
Exhaust Fans									
Fences									
Fire Detection Equip.									
French Drain									
Gas Fixtures 🔟 🗆 Pool Maint. Accessories 🗆 🗖 🗅 Window Screens									
Natural Gas Lines 🔟 🗆 🗆 Pool Heater 🗆 🗂 🗖 Public Sewer System	V								
Mana V NI II Additional Information			_						
Item Y N U Additional Information									
Supply Su	□ ☑ electric ☑ gas number of units: ?								
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	number of units:								
Oven									
Fireplace & Chimney		_							
Carport									
Garage									
Garage Door Openers									
Satellite Dish & Controls									
Security System									
Solar Panels □ □ □ □ owned □ leased from									
Water Heater □ □ □ electric □ gas □ other: number of units:									
Water Softener □ ២ □ owned □ leased from									
Water Softener □ ២ □ owned □ leased from Other Leased Item(s) □ □ if yes, describe:									

Underground Lawn Sprinkler	uton	natic	☐ mar	nual	areas covered:		
Septic / On-Site Sewer Facility	s, a	ttach	Informa	tion A	About On-Site Sewer Facility (TXR	-14	07)
Water supply provided by: ☐ city ☐ well ☐ M	1UD	Ос	o-op 🗖	lunkr	nown 🗖 other:		
Was the Property built before 1978? ☐ yes ☐							
(If yes, complete, sign, and attach TXR-1906							
Roof Type:		Age:	12	yea	(approxi	ma	te)
Is there an overlay roof covering on the Property	y (sh	ingle	s or roo	f'cove	ering placed over existing shingles	or	roof
covering)? ☐ yes ☐ no ☐ unknown							
Are you (Seller) aware of any of the items liste	d in	this	Section	1 tha	at are not in working condition, that	at h	ave
defects, or are need of repair? ☐ yes ☐ no If	yes	, desc	cribe (at	tach	additional sheets if necessary):		
Section 2. Are you (Seller) aware of any def			nalfunc	tions	s in any of the following?(Mark)	Yes	(Y)
if you are aware and No (N) if you are not awa	are.)					
Item Y N Item			Υ	N	Item	Υ	N
Basement				2	Sidewalks		
Ceilings	/ Sla	b(s)		TP/	Walls / Fences	V	
Doors Interior Walls		<i>D</i> (0)		Œ	Windows		
Driveways □ Lighting Fixt					Other Structural Components		
Electrical Systems Plumbing Systems			-		Other otractaral compensition	_	
Exterior Walls	JULI	113	ᆖ			=	=
						_	_
If the answer to any of the items in Section 2 is	yes,	expla	in (atta	ch ad	lditional sheets if necessary):		
Cracks in concrete in dr	ive	May	1. 510	eb_	repaired by Atlas		
Fence Will need replaced	ne	nt/	in a	yes	air or two		
				V			
Section 3. Are you (Seller) aware of any of	the	follo	wing c	ondi	tions? (Mark Yes (Y) if you are	aw	/are
and No (N) if you are not aware.)							
Condition	Υ	N	Cond	ition		Υ	N
Aluminum Wiring	-	N P	Rado				N
		_	Settlir		5		
Asbestos Components Diseased Trees: ak wilt			Soil M		mont	금	E CENT
Endangered Species/Habitat on Property		U U			e Structure or Pits	금	E C
	_						
Fault Lines Hazardous or Toxic Waste	무	Ø			nd Storage Tanks	<u>-</u>	
		EZ.			Easements		
Improper Drainage					d Easements	-	<u>U</u>
Intermittent or Weather Springs		Ľ			aldehyde Insulation	<u>-</u>	<u>u</u>
Landfill	무	B			nage Not Due to a Flood Event		<u>u</u>
Lead-Based Paint or Lead-Based Pt. Hazards		E C			on Property		
Encroachments onto the Property			Wood				œ
Improvements encroaching on others' property		U			station of termites or other wood		ď
	_				insects (WDI)		
Located in Historic District		Y			eatment for termites or WDI		
Historic Property Designation		U			ermite or WDI damage repaired		
Previous Foundation Repairs			Previo				P
Previous Roof Repairs					WDI damage needing repair		U
Previous Other Structural Repairs			_		ockable Main Drain in Pool/Hot		B
		ď	Tub/S	pa*		_	_
Previous Use of Premises for Manufacture							
of Methamphetamine				na			
				eller:	Be Page	- 0 -	of 6

Concerning the Property at $\underline{1122}$ West Belgravia Drive, Pearland, TX 77584

Initialed by: Buyer: and Seller: Page 2 of 6

Со	ncernii	ng the Property a	at 1122 West Belgrav	ia Driv	e, Pearla	nd, TX 77	584			
If t	he ar	nswer to any o	of the items in Sec	ction 3	B is yes,	explain	(attach ac	lditional	sheets if	necessary):
_	*A sii	ngle blockable m	ain drain may cause	a sucti	on entrap	ment haz	ard for an inc	dividual.		
of	ction repa	4. Are you (Seller) aware of not been previous	any i ously	tem, eq	uipmen sed in t	t, or syste his notice	em in o	yes ⊡ ′n	Property that is in need o If yes, explain (attach
_										
			Seller) aware of tly as applicable						ark Yes (Y) if you are aware and
<u>Y</u>	N	Present floo	d insurance cove	rage						
	•		oding due to a fa		or brea	ach of a	reservoir	or a co	ntrolled o	or emergency release of
	ľ	Previous flo	oding due to a na	tural f	lood ev	ent.				
	D'	Previous wa	ter penetration in	to a s	tructure	on the	Property d	ue to a i	natural flo	ood.
	ľ	Located □ v AO, AH, VE		n a 10	0-year	floodpla	in (Specia	Flood	Hazard A	rea-Zone A, V, A99, AE,
	ľ	Located □ v	vholly 🛭 partly in	a 500	0-year fl	oodplair	n (Moderat	te Flood	Hazard /	Area-Zone X (shaded)).
	P	Located 🛭 v	vholly 🛭 partly in	a floo	odway.					
	P	Located □ v	vholly 🛭 partly in	a floo	od pool.					
	4	Located □ v	vholly 🏻 partly in	a res	ervoir.					
If t	he an	swer to any o	f the above is yes	в, ехр	lain (att	ach add	itional she	ets as n	ecessary):
_										
		-		matte	rs, Buye	er may c	onsult Info	rmation	About Flo	ood Hazards (TXR 1414).
	"100 which	h is designated a	means any area of la	E, AO	, AH, VE	, or AR o	n the map; (B) has a	one perce	as a special flood hazard area, ent annual chance of flooding, ol, or reservoir.
	area,	which is design	means any area of la ated on the map as o be a moderate risk o	Zone 2	X (shaded	identified d); and (B	on the flood has a two	d insurand o-tenths of	ce rate ma f one perce	p as a moderate flood hazard ent annual chance of flooding,
			ne area adjacent to a nundation under the n							vel of the reservoir and that is
	"Floo unde	d insurance rate r the National Flo	map" means the mo ood Insurance Act of	ost rece 1968 (4	ent flood 12 U.S.C.	hazard m Section 4	ap published 001 et seq.).	d by the F	ederal Em	ergency Management Agency
	a rive	er or other water		ent land	d areas th	at must b	e reserved fo	or the disc	charge of a	which includes the channel of base flood, also referred to as height.
	"Rese water	ervoir" means a r or delay the run	water impoundment μ off of water in a desig	oroject gnated	operated surface a	by the Ui rea of lan	nited States . d.	Army Cor	ps of Engir	neers that is intended to retain
(TX	R-140	6) 07-08-22	Initialed by: E	Buyer:			and Seller:		, BC	Page 3 of 6

and Seller:

Initialed by: Buyer:

(TXR-1406) 07-08-22

Page 4 of 6

Concerning the Prop	erty at 1122 West Belg	ravia Drive, Pearlar	id, TX 77584		
persons who re	gularly provide	inspections and	d who are		spection reports from spectors or otherwise applete the following:
Inspection Date	Туре	Name of Insp	ector		No. of Pages
Section 10. Che	A buyer should ck any tax exemp l nagement	obtain inspection otion(s) which yo ☐ Senior Citize	ns from inspe ou (Seller) o n	ectors chosen by the bug currently claim for the Disabled	
with any insurar Section 12. Have	nce provider? □ e you (Seller) e	yes 🗹 no ver received pr	oceeds for	a claim for damage	mage, to the Property to the Property (for
detector require		r 766 of the Hea	Ith and Safe		dance with the smoke n □ no ⊡∕yes. If no
installed in acco	ordance with the requinance, location, and p	uirements of the build nower source require	lding code in a ments. If you a	o-family dwellings to have we effect in the area in which t do not know the building code n official for more information.	the dwelling is located, e requirements in effect
family who will impairment from seller to install s	reside in the dwelling a licensed physician; smoke detectors for th	g is hearing-impaire and (3) within 10 day ne hearing-impaired a	d; (2) the buye s after the effe and specifies to	npaired if: (1) the buyer or a er gives the seller written e ective date, the buyer makes a he locations for installation. f smoke detectors to install.	vidence of the hearing a written request for the
	ker(s), has instru				lief and that no person, rmation or to omit any
Car boos a	Croswell	06/ 200	3		
Signature of Selle		Date	Signa	ature of Seller	Date
Printed Name: Bar	rbara Croswell		Printe	ed Name: Thomas Croswell	1
(TXR-1406) 07-08-22	! Initialed b	oy: Buyer:	and S	Seller:	Page 5 of 6

ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit www.txdps.state.tx.us. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review Information Regarding Windstorm and Hail Insurance for Certain Properties (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those

items independently measured to verify any reported in	nformation.
6) The following providers currently provide service to the	
Electric: Reliant Energy (elec)	phone #: 713-207-7777 or 377-734-72
Sewer: Pear land Water Dept	phone #: Pearland City Hall (water dept)
Water: Pearland Water Dept	phone #: 281-652-1600
Cable:	phone #:
Trash: included in Pearland Water Dapt.	7 phone #:
Natural Gas: Center Point (945)	phone #: 7/3 - 659 - 2/1/
Phone Company:	phone #:
Propane:	phone #:
Internet:	phone #:
(7) This Seller's Disclosure Notice was completed by Sellethis notice as true and correct and have no reason ENCOURAGED TO HAVE AN INSPECTOR OF YOU! The undersigned Buyer acknowledges receipt of the foreg	to believe it to be false or inaccurate. YOU ARE R CHOICE INSPECT THE PROPERTY.
	O'construct of Davis
Signature of Buyer Date	Signature of Buyer Date
Printed Name:	Printed Name:
TXR-1406) 07-08-22	and Seller: Page 6 of 6
Houston Top Realty - 8511 South Sam Houston Parkway East 8511 South Sam Houston Parkway East 100 Houston	.TX 77075 Sam Ferreri

House in Southdown Subdivision

1122 West Belgravia Drive Pearland, TX. 77584

- 1. Roof 100% windstorm
- 2. All new windows 100% windstorm.
- 3. New front and back doors windstorm 100%.
- 4. New wind storm door locks.
- 5. New interior doors, all interior doors replaced.
- 6. New and door knobs on all doors.
- 7. New fire rated door from the kitchen to the garage.
- 8. New floor coverings in all of the house.
- 9. New banister stair hand rail.
- 10. New cabinets, dove tail, all wood and no partial wood or carboard.
- 11. New granite counter tops.
- 12. New kitchen appliances expect for the stove.
- 13. New sink in kitchen
- 14. New water heater.
- 15. New fireplace box and chimney inspected.
- 16. New half bath door everything replaced.
- 17. New sink and faucet in kitchen.
- 18. New medicine cabinets, sink faucets, shower in bathrooms upstairs.
- 19. New light fixtures inside except for one over table and one in hallway.
- 20. Replaced air conditioner
- 21. Replaced heater
- 22. House slab was completely repaired 100% by Atlas. Was inspected last year by Atlas, accepted. Has a life time warranty, transferable to new home owner.
- 23. Leaf guards on gutters.
- 24. Repairs and inspection by master plumber and electrician.

Home owner

Thomas Croswell

Lakeland Community Association, Inc. P. O. Box 3217 Pearland, TX 77588 (281) 947-8675



Statement

Statement Date: 11/2/2021

Statement

Thomas Croswell 6702 Grapevine Bend Manvel, TX 77578

Angoret Due (C. Second Strong Second Second

01/01/2022 Annual Assessment 2022 \$450.00

	CENTER'S	AND STEP OF SELECTION		grienis (* 1846)	Establinative	TERES IN
\$0.00	\$0.00	\$0.00	* \$ ⁴	\$450,00	97th 19	\$450.00

In order to avoid late fees, payment must be received by our office on or before January 31, 2022. If you have previously filed for bankruptcy, please only pay post-petition amounts. If you are currently on a payment plan for the 2021 assessment, please only pay the 2022 assessment amount. If your account has previously been turned over to the Attorney's office for collection, the statement amount is not the full amount due. Please contact your attorney's office for the full amount owing on your account. Partial payments will not be accepted and will be returned without a signed payment plan agreement. All Check and money orders need to be made out to your association. Payments made payable to LPI will not be accepted and will be returned. Cash is NOT accepted. For more payment information, please visit www.lpipropertymanagement.com and choose "Ways to Pay". To request a payment plan, please visit www.lpipropertymanagement.com and choose "Payment Plan Request" under HOA services. The LPI App is available for download via the App Store or the Google Play Store. If you are serving on active military duty, please refer to the Civil Relief Act (50 U.SC. app. Section 501 et seq.) to learn what your rights are.

Please detach and return this portion with payment. Do not staple or fold.



February 24, 2022

Atlas Foundation Repair made a visit to your home and has determined that there are no adjustments needed at this time. (Readings are within 1" tolerance in 30'). This home was evaluated with a Ziplevel for foundation movement, finding the foundation to be structurally stable.

If you have any further questions or concerns, please feel free to contact our office at (713) 641-4844.

Sincerely,

Rainbow Martinez

CABLE LOCK" LIFETIME FOUNDATION WARRANTY

Certificate # 30000214

his certifies that the homeowners at 1122 W. Belgrave


Pearland, TX 77584

have used the Cable Lock system of foundation repair.

areas previously underpinned without cost to the owner our company or another designated Cable Lock contractor will re-raise all If any adjustments are required during the life of this home due to settling,

applies only to Cable Lock installations this home, provided no major structural changes have been made, and This warranty is completely transferable to any and all future owners of

Atlas Foundation Rep



COMPANY OFFICER SIGNATURE April 22, 2004



April 1, 2004

Atlas Foundation Repair 2835 Fay Houston, Texas 77023

Subject: Review of Foundation Repairs at 1122 W. Belgrave, Pearland, Texas 77584

BEC Engineering, Inc. (BEC) has reviewed the subject foundation repairs that were made to the above referenced residence in March 2004. Atlas Foundation Repair presented the repaired portion of the foundation using 24 segmental pre-cast Cable Lock TM concrete piles beneath the above referenced location for BEC's review. The pile locations and spacing were found to be in general compliance with industry standards, and generally in accordance with Atlas Foundation Repair's proposal.

In BEC's opinion, the piling depths in conjunction with the pile driving force as reported are adequate for this type of structure and for the area where the work is being performed. Based on the information provided the areas where the new pilings were installed under the foundation are now more level then previously recorded prior to the re-leveling work. The repair work performed to the subject location is believed to have been acceptably completed in accordance with good industry practice for foundation pile installation work. The repairs as performed on the subject location should stabilize the foundation movement observed prior to the foundation repair work. A foundation maintenance program is recommended which can be found at www.foundationperformance.org.

The future performance of the foundation system on the subject location should be as intended, provided proper soil moisture is maintained and there is not a loss in the load bearing capacity of the soil beneath the foundation. Soils should be graded such that there is positive drainage away from the foundation to prevent water from ponding around the foundation slab.

BEC appreciates being of service. If you have any questions or require additional information please contact the undersigned.

Regards,

Karl Breckon, P.E. BEC Engineering, Inc.