## **TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT**

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

23219 Sawleaf Circle	Katy	77494
Inspected Address	City	Zip Code


## SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.

## F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.

- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). The warranty should specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure,
   (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

23219 Sawleaf Circle	Ka	ty			_	77494	
Inspected Address		City				Zip Code	e
1A. Anytime Pest Elimination/Pro	oducts	1B.07	763090				
Name of Inspection Compan	У			SPCS Business Lice	ense Number		
1C. 1700 North Main Street		Bayte	own	ТХ	77520	832	-514-2400
Address of Inspection Comp	any	City		State	Zip	Tele	phone No.
1D. Greg Schoch			1.E	Certified Applicator		(che	ck one)
Name of Inspector (Please F	Print)			Technician			
		1F. <u>08</u>	8/21/2023				
Coatt Adama/Darfarmanaa Inana	tiono	Inspe	ction Date				Inonactor
2. <u>Scott Adams/Performance Inspec</u> Name of Person Purchasing			Seller	Agent 🗌 Buyer 🗌	Managemen	t Co. 🗌 Other	
3. <u>N/A</u>							
Owner/Seller 4.REPORT FORWARDED TO: Title (Under the Structural Pest C	Company or Mortgagee			Seller to receive a copy)	Agent 🗌	Buye	er 🗌
The structure(s) listed below were inspe This report is made subject to the condit							I Pest Control Service.
5A. <u>House with attached garage.</u> List structure(s) inspected that may inclu							
List structure(s) inspected that may inclu	ide residence, detached garag	ges and other stru	ctures on the p	roperty. (Refer to Part	t A, Scope of I	nspection)	
5B. Type of Construction: Foundation: Slab		Basement	Other: N/A				
Siding: Wood Fiber Cement Bo	oard ■ Brick■ Stone □ Stu ningle □ Metal □ Tile □ Oth	Icco 🗌 Other:NA					
	-		na incento N/A				
6A.This company has treated or is treati If treating for subterranean termites, the If treating for drywood termites or related	treatment was:	Partial	Spot Limited	Bait		Other	
6B.		N/A			N/A		
Date of Treatment by Inspec	ting Company	Co	ommon Name c	f Insect	Name of	Pesticide, Bait o	r Other Method
This company has a contract or warranty		-	oying insects:				
Yes No	List Insects anty and treatment diagram		4				
Neither I nor the company for which I an I nor the company for which I am acting	is associated in any way with				e or sale of this	s property. Tao fi	urther state that heithei
Signatures: Greg Schs							
Inspector (Technician or Certified App	licator Name and License Nu	mber)					
Others Present: 7B. <u>N/A</u>							
Apprentices, Technicians, or Certified	Applicators Name(s) and Reg	istration/License I	Number(s)				
Notice of Inspection Was Posted At or N	lear:						
8A. Electric Breaker Box		Date Posted:		08/21/2023			
Water Heater Closet Beneath the Kitchen Sink	]						
9A.Were any areas of the property obstr (Refer to Part B & C, Scope of Inspectio		Yes	•	No			
9B.The obstructed or inaccessible areas	include but are not limited to	the following:					
Attic  Deck	Insulated area of attic Sub Floors	<ul> <li>Plumb</li> <li>Slab J</li> </ul>	oing Areas Ioints	□ Planter b □ Crawl Sp	box abutting st	ructure	
Soil Grade Too High	Heavy Foliage	Eaves		Weepho			
Other 10A.Conditions conducive to wood destr	Specify: <u>N/A</u>	Yes		No			
(Refer to Part J, Scope of Inspection) If		103					
10B.Conducive Conditions include but a					. – –	· • • • • •	
	Wood to Ground Co Footing too low or se	oil line too high (L)	Wo	mboards left in place ( od Rot (M)	🗌 Hea	essive Moisture avy Foliage (N)	
<b>U</b> ( )	Wood Pile in Contac	ct with Structure (C Specify: <u>N/A</u>	Q) 🗌 Wo	oden Fence in Contact	t with the Strue	cture (R)	
Insufficient ventilation (T)	Other (C)	opeony: <u>1977</u>					
	Licensed and PO Box 12847, Austin			tment of Agriculture -918-4481, Fax 888-2	32-2567		
SPCS/T-5 (Rev. 9/1/2020)	,			,			Page 2 of 4
. ,							0



SPCS/T-5 (Rev. 9/1/2020)

23219 Sawleaf Circle	Katy		77494
Inspected Address	City		Zip Code
	Stateme	nt of Purchaser	
have received the original or a legible copy of thi understand that my inspector may provide addition	s form. I have read and understand	any recommendations mad	e. I have also read and understand the "Scope of Inspection.
f additional information is attached, list number of	pages:		
Signature of Purchaser of Property or their Desigr	nee	Date	
Customer or Designee Not Present	Buyer's Initials		