From: <sharon.henderson@griptx.com> sharon.henderson@griptx.com

Subject: 800 Northcrest, Livingston, TX 77351 Inspection Results

Date: Sep 18, 2018, 3:41:05 PM

To: <mcculley@livingston.net> mcculley@livingston.net

Cc: Kelli Garcia kelli.garcia@griptx.com

We inspected the MH property at <u>800 Northcrest</u>, <u>Livingston</u>, <u>TX 77351</u> on September 18, 2018 and it does need a retrofit in order to meet either the 1996 HUD Guidelines for FHA and VA loans or Texas Department of Housing and Community Affairs ("TDHCA") guidelines for conventional loans.

- 1. The transverse anchors are not corrosion resistant as required by FHA/HUD and Texas TDHCA.
- 2. There are no longitudinal anchors at all... longitudinal anchors are required by FHA/HUD and Texas TDHCA guidelines.
- 3. The cinderblock piers are mounted directly on the soil... this is allowed on existing homes.
- 4. The axles MUST BE removed as required by FHA/HUD and Texas TDHCA.
- 5. The tongues have been removed as required by FHA/HUD and Texas TDHCA.
- 6. The drainage is adequate as required by FHA/HUD and Texas TDHCA.
- 7. The skirting needs the following in order to meet current FHA/HUD and Texas TDHCA guidelines:
 - a. Skirting bracing along the perimeter of the home using treated wood or metal studs and secured by rebar in the ground
 - b. Seller may do this... If the above skirting work is done before the retrofit, the seller will avoid a \$ 175.00 reinspection fee.
- 8. The modifications to the home do not meet current FHA/HUD guidelines... they do affect the structural integrity of the home
 - a. The front porch roof needs four(4) 4 X 4 support posts to remove porch roof load away from the MH.
 - b. The rear porch roof needs four(4) 4 X 4 support posts to remove porch roof load away from the MH.
 - c. The seller may do this prior to closing.

Our bid of \$3,804.10 for the scope of work below can, if or when you are ready, be sent by separate email in Bid Contract Form, with a place for signature by the responsible party(ies).

1	Foundation Retrofit with Engineer Certification Report	\$2,388.41
2	Skirting Bracing **	\$466.42
3	Porch Roof Support Posts (8) **	\$449.27
4	Detatch Axles **	\$500.00
-		Ψυ

** SELLER MAY DO THIS

Payment for the retrofit work is due at closing or 30 days after completion, whichever is soonest.

PROJECT INFORMATION

Re:

800 Northcrest, Livingston, TX 77351

28' X 68' Manufactured House

HUD Label Nos NTA0485245 and NTA0485246

SCOPE OF WORK: Foundation Retrofit, Skirting Bracing, Front/Rear Porch Roof Support Posts(8), Axle Detachment and Engineers Report

Sharon Henderson
Administrative Manager
GulfTex Retrofit Installation Professionals, LLC
485 Becky Lane
Waxahachie, TX 75165
Installer License MHDINS 00004551
Sharon.henderson@griptx.com
Cell 817-627-7139 (call or text)
Fax 866-863-5069