
2920 Cain Road College Station, TX 77845 Office: (979)690-2020 www.anchorfoundationrepair.net



Date: 17 MAR 15

Anchor Structural Services, LLC. ("Contractor"), and MRS BUCK \$ 5,250 % after piers are po	("Owner") agree that the sum of				
\$ 5,250 %, to be paid as follows: 50 % after piers are po	oured, balance upon completion.				
Contractor will furnish labor, equipment, and materials to perform the following descr	ibed work to the hereinafter described building or structure				
located at: 1207 Westover ;Sto					
Phone: 218-1861; Email:					
1. The work shall consist of the installation of EXTERIOR PIERS and INTERIOR PIERS with 8" diameter shafts drilled to 8' to 12' (water table, rocks, and/or man placed objects permitting.) The bottom of the shaft will have a 20" diameter bell footing, unless rock is encountered.					
2. Contractor assumes no responsibility for any under slab plumbing. It may currently process. Any repairs, if required, are the sole responsibility of the owner. Contractor repairs to plumbing.					
3. Contractor will not make repairs to foundation watering systems after leveling. If damaged, Contractor will make every reasonable effort to repair lawn irrigation systems that are properly installed.					
4. Contractor will carry all insurance required by the State of Texas.					
5. When inside piers are required, contractor will patch floors with concrete to floor level. Carpet will NOT be stretched.					
6. When surfaces such as concrete porches, patios, or drives are broken in order to install piers, Contractor will patch surfaces. However, the patches will NOT match the color or texture of the original surface. Special surfaces such as Flagstone, Spanish Tile, Brick or other such materials will be restored at an additional cost as specified below.					
7. In foundation leveling, conditions might appear when work is begun that were not visible at time of estimate; such as, insufficient reinforcing steel in concrete slab, and/or other structural deficiency. In such cases the guarantee becomes invalid.  8. SPECIAL PROVISIONS: No Subcontractors. Repairs To Rear Portion of Home only					
8. SPECIAL PROVISIONS: No Subcontractors. Repairs To Kear PORTION OF 170ME ONLY					
9. LIFETIME SERVICE AGREEMENT: If any raising is necessary due to settling during the first five years from date of job completion, Contractor will re-raise the settled area WITHOUT COST TO THE OWNER. Servicing for additional years, if required, will be done at the rate of \$					
THIS AGREEMENT IS TRANSFERABLE TO NEW OWNERS. NOTIFICATION MUST BE TENDERED IN WRITING WITHIN 90 DAYS OF OWNERSHIP.					
It is understood and agreed that in order to perform the above described work, it is possible that sheetrock, wallpaper, or other rigid material may crack. Therefore, the above figure does not include any redecorating, repairing, electrical work or the replacement of any material not called for in this Agreement. Contractor, upon request from the Owner, will transplant plants and shrubs obstructing operations, and replace same upon completion of repairs. Survival of plants and shrubs CANNOT be guaranteed.					
It is understood and agreed that Contractor will furnish all the labor, equipment, and material and will perform all necessary work in connection with this job, in a good workmanlike manner. Job site will be clean of all excess dirt and material.					
The Owner may order extra work to be done not contemplated by the contract. In which event, a separate Agreement for such work shall be entered between the Owner and the Contractor. No oral representation made by anyone can change or modify this Agreement. The Agreement, in order to be binding by both parties, must be signed and returned to this office within					
Man Gil Buch	Ley Trans				
Owner	Anchor Structural Services, LLC				





## PIER FOUNDATION DETAILS

## 2920 Cain Road College Station, TX 77845 979.690.2020

www. An chor Foundation Repair. net



Name MRS Buck

Address 1207 Westover C.S.

Tel\_\_\_\_\_

Email\_

		0 0	0
	9		
	++++++++++++++++++++++++++++++++++++		
			* * * * * * * * * * * * * * * * * * *
			5 5 6 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
		1 1	
Interior			
IIILETION			
Interior			
19)			
Exterior			
Direction of Slope			
Direction of Slone			