LIFETIME SERVICE WARRANTY

Certificate # 2012-0697

This certifies that the structure at

21315 Meadow Hill Drive Spring, Texas 77388

Has had Foundation Plus HD Pilings installed on: 05/28/2024

exceed one year after completion of the installation. ATLAS FOUNDATION REPAIR will adjust the ATLAS FOUNDATION REPAIR will adjust those pilings installed due to settling for a period not to

After one year, ATLAS FOUNDATION REPAIR will adjust the pilings located in the settled areas at the cost of \$75.00 per piling plus or minus the U.S. Consumer Price Index (CPI) calculated from the structural changes have been made.

pilings located in the settled areas previously installed without cost to the owner, provided no major

date of installation.

which ATLAS actually performed work. This warranty is transferable to subsequent owners. This warranty does not extend to any portion of the structure not directly located within the area of influence

Atlas Foundation Repair

07/18/2012

Date

LIFETIME SERVICE WARRANTY

Certificate # 2012-0697

This certifies that the structure at

21315 Meadow Hill Drive Spring, Texas 77388

Has had Foundation Plus HD Pilings installed on: 05/28/2024

structural changes have been made. pilings located in the settled areas previously installed without cost to the owner, provided no major exceed one year after completion of the installation. ATLAS FOUNDATION REPAIR will adjust the ATLAS FOUNDATION REPAIR will adjust those pilings installed due to settling for a period not to

After one year, ATLAS FOUNDATION REPAIR will adjust the pilings located in the settled areas at the cost of \$75.00 per piling plus or minus the U.S. Consumer Price Index (CPI) calculated from the date of installation.

This warranty does not extend to any portion of the structure not directly located within the area of influence which ATLAS actually performed work. This warranty is transferable to subsequent owners.

Atlas Foundation Repair 07/18/2012

Date

This warranty is subject to terms and conditions on the backside of this warranty.

LIFETIME SERVICE WARRANTY

Certificate # 2012-0697

This certifies that the structure at

21315 Meadow Hill Drive Spring, Texas 77388

Has had Foundation Plus HD Pilings installed on: 05/28/2024

ATLAS FOUNDATION REPAIR will adjust those pilings installed due to settling for a period not to exceed one year after completion of the installation. ATLAS FOUNDATION REPAIR will adjust the pilings located in the settled areas previously installed without cost to the owner, provided no major structural changes have been made. After one year, ATLAS FOUNDATION REPAIR will adjust the pilings located in the settled areas at the cost of \$75.00 per piling plus or minus the U.S. Consumer Price Index (CPI) calculated from the date of installation.

This warranty does not extend to any portion of the structure not directly located within the area of influence which ATLAS actually performed work. This warranty is transferable to subsequent owners.

07/18/2012

Atlas Foundation Repair

Date

This warranty is subject to terms and conditions on the backside of this warranty.



| FOUNDATION REPAIR™ Ph 713-641-4844 • www.atlasfoundation.net STRUCTURE DESCRIPTION: Siding: Front Back Sides Stories: 1 11/2 2 Other Foundation: Slab PT B&B P/B Beam Depth: Lot Type | DATE: 6-27-17 KEY MAP #: NAME: 6 p npa Coffey ADDRESS: 21315 Meadow Hilld CITY: 504 ng ZIP: 77388 PH: 8323603-7765 PH: OTHER: |
|--|--|
| no problem, the lerance | |
| | |

0.3 0.2 0.1 20.77 +0.9 +1.0 0.90 +0.9 20.90 +0.5 ф ф

| TOTAL | NUMBER | OF DII | INICC. |
|-------|-----------|--------|--------|
| IOIAL | INCINIDEL | OFFIL | LINUS. |

| EXTERIOR | |
|----------|--|
| INTERIOR | |

| LEGEND: | | | |
|--------------------------|------|------------------|---|
| EXTERIOR PILINGS | 0 | FENCES | _ |
| INTERIOR PILINGS | | DECKS | _ |
| EXISTING PILINGS | | PEA GRAVEL | _ |
| EXISTING BELL BOTTOM PIE | RS 🔘 | 1 INCH = 10 FFFT | |