

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2022

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which

exceed the minimum disc	closu	ires i	requ	ired	by ti	ne C	ode.							_
											inti Dr			
CONCERNING THE PR					Richmond, TX 77406									
AS OF THE DATE WARRANTIES THE B SELLER'S AGENTS, O	SIG UYE R AN	NEC R M IY O) B' IAY THE	Y S WIS	ELL SH GEN	ER TO IT.	AND IS NOT A	N S	UBS A V	STITU VARR	CONDITION OF THE PRO TE FOR ANY INSPECTIO ANTY OF ANY KIND BY S	NS SELI	LER	Κ,
Property											ow long since Seller has date) or never occupi	ed	piec the	t e
Section 1. The Proper	not e	as ti stabli	ish th	ems ne ite	ma ms t	rkec o be	conveyed. The contra	ct wi	l det	ermine	which items will & will not convey			
Item	Y	N	U		Ite	n		Υ	N	U	Item	Y	N	U
Cable TV Wiring	/				Na	tural	Gas Lines	/			Pump:sump / grinder	~		
Carbon Monoxide Det.		/			Fue	el Ga	as Piping:			/	Rain Gutters	/		
Ceiling Fans	/						ron Pipe			/	Range/Stove		/	
Cooktop	~					ppe				/	Roof/Attic Vents	/		
Dishwasher					-Corrugated Stainless Steel Tubing		ated Stainless			/	Sauna		/	
Disposal			Ì	Hot Tub				/		Smoke Detector	/			
Emergency Escape Ladder(s)		/			Inte	erco	m System		/		Smoke Detector - Hearing Impaired		/	
Exhaust Fans	/				Mic	crow	ave	/			Spa		/	
Fences	/				40.49494		or Grill	/			Trash Compactor		/	
Fire Detection Equip.	-	/			-	0.5545.004.054	ecking	/			TV Antenna		/	
French Drain				Plumbing System			/			Washer/Dryer Hookup	/	-		
Gas Fixtures					Po		9 -)		1		Window Screens	V		
Liquid Propane Gas:	+	/		1	Pool Equipment				/		Public Sewer System	V	1	
-LP Community (Captive)		/					aint. Accessories		/		÷			
-LP on Property		/			Po	ol H	eater		/					
Item				Υ	N	U					onal Information			
Central A/C				V				nur	nbe	r of un	its: _3	_		
Evaporative Coolers					V,		number of units:							
Wall/Window AC Units					√,		number of units:							
Attic Fan(s)					V		if yes, describe:							
Central Heat				V			electric/gas	nui	nbe	r of un	its: 3			
Other Heat					\		if yes, describe:							
Oven				/			number of ovens:	1		✓ ele	ctric gas other:			
Fireplace & Chimney				/			✓ wood ✓ gas logsmockother:							
Carport attached not attached														
Garage				V			attached √no		ache	ed				
Garage Door Openers				/			number of units:	-			number of remotes: 2			
Satellite Dish & Contro	ls				V		ownedlease	ed fr	om:					
Security System				1			✓ ownedlease	ed fr	om:				_	_
(TXR-1406) 07-10-23			Initia	aled	by: E	Buyer	:177	and S	Selle	r: (K	W, 4	age	1 of	7

Fax: 8175779003

3618 Vacanti Dr Richmond, TX 77406

									4		
Solar Panels		,	V	ow	ned	leased fro	m: _				
Water Heater		/		_ ele	ctric 🏏	gas ot	her:		number of units: 2	•	
Water Softener		\checkmark		✓ owl	ned	leased fro	m: _				
Other Leased Items(s)			✓ if	f yes,	descri	be:					_
Underground Lawn Sprinkler		/	/	∠ aut	omatic	manua	ıl ar	eas co	vered		
Septic / On-Site Sewer Facili	ty		✓ it	f yes,	attach	Informatio	n Al	oout Or	n-Site Sewer Facility (TXR-140	7)	
Water supply provided by: Was the Property built before (If yes, complete, sign, a Roof Type:	e 1978? nd attach	n TX	res <u>//</u> no _ (R-1906 co	uni oncer	known ning le Aae:	ad-based	oain Ve	t hazar		kima or r	te)
outdoor grill t	r? / yes	e o	no If yes,	desci	ribe (at	tach additi	er	sheets ac	of the following? (Mark	Yes	(Y)
Item	YN		Item				Υ	N	Item	Y	N
Basement			Floors				/		Sidewalks		/
THE CONTRACT OF THE CONTRACT O			undation / Slab(s)						_	/	
Doors	/		Interior V	Valls				1	Windows		1
Driveways	✓		Lighting	Fixtur	es			/	Other Structural Components		/
Electrical Systems	V		Plumbing	g Syst	ems			1			
Exterior Walls	✓		Roof								
	ettline vertine er) awa	Į i	in vari	- let ous	5 po	tsinh	ous	arage ie di	sif necessary): Some small ue to natural settli (Mark Yes (Y) if you are	0	
Condition				Y	N	Conditio	n			Y	N
Aluminum Wiring						Radon G	as				V
Asbestos Components					/	Settling					/
Diseased Trees: oak wilt					/	Soil Mov	eme	ent			/
Endangered Species/Habita	t on Prop	erty	/		V	Subsurfa	ice S	Structur	re or Pits		1
Fault Lines					1	Undergro	ounc	Storag	ge Tanks		1
Hazardous or Toxic Waste					1	Unplatte					/
Improper Drainage					/	Unrecord	ded	Easem	ents		1
Intermittent or Weather Sprir	nas				1	Urea-fori	malo	dehyde	Insulation		V
Landfill	.5-								Due to a Flood Event		V
Lead-Based Paint or Lead-B	ased Pt.	Ha	zards		/	Wetlands					/
Encroachments onto the Pro	COLUMN TO THE REAL PROPERTY AND ADDRESS OF THE PARTY AND ADDRESS OF THE	1 10			1	Wood Ro					/
Improvements encroaching		s' pr	operty		/			ation of	termites or other wood		1
		16.			V	destroyir					~
Located in Historic District					1				for termites or WDI		/
Historic Property Designation	n				1				WDI damage repaired		V
Previous Foundation Repairs					1	Previous			-		/

Page 2 of 7
Kandace Kesler

3618 Vacanti Dr Richmond, TX 77406

Previous R	oof Repairs	/	Termite or WDI damage needing repair	
Previous O	ther Structural Repairs	/	Single Blockable Main Drain in Pool/Hot Tub/Spa*	-
Previous U of Metham	se of Premises for Manufacture phetamine	V		
If the answ	er to any of the items in Section 3 is your repairs on room	ves, explair	(attach additional sheets if necessary):	
Section 4.	e blockable main drain may cause a sucti	tem, equi	ent hazard for an individual. oment, or system in or on the Property that is in this notice?yes _v_no lf yes, explair	in need
	sheets if necessary):			
Section 5. check who	Are you (Seller) aware of any only or partly as applicable. Mark No	of the foll o (N) if you	owing conditions?* (Mark Yes (Y) if you are av are not aware.)	ware and
	Present flood insurance coverage.			
		e or brea	ch of a reservoir or a controlled or emergency re	elease of
	Previous flooding due to a natural fl	ood event.		
$\overline{}$	Previous water penetration into a st	ructure on	he Property due to a natural flood.	
- \frac{1}{2}	Located wholly partly in a AO, AH, VE, or AR).	100-year	loodplain (Special Flood Hazard Area-Zone A, V,	A99, AE,
- -	Located wholly partly in a 5	00-year floo	odplain (Moderate Flood Hazard Area-Zone X (shaded	i)).
	Located wholly partly in a flo	oodway.		
	Located wholly partly in a flo	ood pool.		
	Located wholly partly in a re	eservoir.		
If the answ	ver to any of the above is yes, explain	(attach ad	ditional sheets as necessary):	

For purposes of this notice:

"100-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a special flood hazard area, which is designated as Zone A, V, A99, AE, AO, AH, VE, or AR on the map; (B) has a one percent annual chance of flooding, which is considered to be a high risk of flooding; and (C) may include a regulatory floodway, flood pool, or reservoir.

"500-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a moderate flood hazard area, which is designated on the map as Zone X (shaded); and (B) has a two-tenths of one percent annual chance of flooding, which is considered to be a moderate risk of flooding.

"Flood pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that is subject to controlled inundation under the management of the United States Army Corps of Engineers.

(TXR-1406) 07-10-23

Initialed by: Buyer:

and Seller

Fax: 8175779003

Page 3 of 7

3618 Vacanti Dr Richmond, TX 77406

Concerning	the	Proper	tv at
COLICCITIII	LIIO	1000	.,

"Flood insurance rate map" means the most recent flood hazard map published by the Federal Emergency Management Agency under the National Flood Insurance Act of 1968 (42 U.S.C. Section 4001 et seq.).

"Floodway" means an area that is identified on the flood insurance rate map as a regulatory floodway, which includes the channel of a river or other watercourse and the adjacent land areas that must be reserved for the discharge of a base flood, also referred to as a 100-year flood, without cumulatively increasing the water surface elevation more than a designated height.

"Reservoir" means a water impoundment project operated by the United States Army Corps of Engineers that is intended to retain water or delay the runoff of water in a designated surface area of land.

Section 6. provider, i	Have you (Seller) ever filed a claim for flood damage to the Property with any insurance ncluding the National Flood Insurance Program (NFIP)?* yes _v no If yes, explain (attach heets as necessary):
Even whrisk, and structure	in high risk flood zones with mortgages from federally regulated or insured lenders are required to have flood insurance, nen not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderated low risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the exp(s).
Administra	Have you (Seller) ever received assistance from FEMA or the U.S. Small Business ition (SBA) for flood damage to the Property?yes v_no If yes, explain (attach additional ecessary):
Section 8.	Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) not aware.)
Y N	Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time.
✓_	Homeowners' associations or maintenance fees or assessments. If yes, complete the following: Name of association: Montage Community Services Manager's name: Phone: 281 - 232 - 7659 Fees or assessments are: \$
	Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following: Any optional user fees for common facilities charged?yes no If yes, describe:
	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.
	Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited to: divorce, foreclosure, heirship, bankruptcy, and taxes.)
	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.
$ \checkmark$	Any condition on the Property which materially affects the health or safety of an individual.
	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold. If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).
	Any rainwater harvesting system located on the Property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.
(TXR-1406)	
W. 113221 P	2333 F. Voo Bd. Sto 215 C. Hondon TV 77057 Phone: 8175010622 Fax: 8175779003 Kandace Kesler

World Wide Realty, 2323 S. Voss Rd. Ste.315-C Houston TX 77057 Rhonda Liotta

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Fax: 8175779003

Kandace Kesler

Concerning	g the Property at	3618 Vacanti Dr Richmond, TX 77406	
	The Property is located in	a propane gas system service area owned by a p	propane distribution system
	retailer.	ty that is located in a groundwater conservation	district or a subsidence
	district.		
If the answ	er to any of the items in Section	on 8 is yes, explain (attach additional sheets if necess	ary):
persons	who regularly provide in	rs, have you (Seller) received any written spections and who are either licensed as ns?yesno If yes, attach copies and comple	inspectors or otherwise
Inspection	Date Type	Name of Inspector	No. of Pages
11/5/202	P. I	tral Hamed Nahavi	6
Ho Wil	Check any tax exemption(mestead dlife Management ner:	(s) which you (Seller) currently claim for the Prope Senior Citizen Agricultural Disabled Unknown filed a claim for damage, other than flood of	rty: Veteran
Section 1 example, to make t Section 1 detector	nsurance provider?yes 2. Have you (Seller) ever an insurance claim or a she repairs for which the clair 3. Does the Property hav requirements of Chapter 7		predance with the smoke
*Ch			

(TXR-1406) 07-10-23

Initialed by: Buyer:

and Seller: (KW),

Page 5 of 7

Kandace Kesler

C	oncerning the Property at	iona, ix ii 400			
in m	coller acknowledges that the statements in this notice are true to cluding the broker(s), has instructed or influenced Seller to aterial information.	provide inaccurate	e informat	6	no person, omit any
Pi	rinted Name: Kandace K. Kesler Printed N	lame: LANG	TRU	DONG	
	DDITIONAL NOTICES TO BUYER:				
) The Texas Department of Public Safety maintains a databate determine if registered sex offenders are located in certain https://publicsite.dps.texas.gov . For information concerning neighborhoods, contact the local police department.	past criminal a	ro search	certain	areas or
(2	feet of the mean high tide bordering the Gulf of Mexico, the Act or the Dune Protection Act (Chapter 61 or 63, Natural construction certificate or dune protection permit may be re local government with ordinance authority over construinformation.	Property may be Resources Code, quired for repairs	respective or improv	o the Ope ly) and a /ements. (beachfront Contact the
(3	B) If the Property is located in a seacoast territory of this so Commissioner of the Texas Department of Insurance, requirements to obtain or continue windstorm and hail is required for repairs or improvements to the Property. For Regarding Windstorm and Hail Insurance for Certain Propertment of Insurance or the Texas Windstorm Insurance Associated	nsurance. A certion more information of the control	ficate of on, pleas	compliance review	e may be
(4	This Property may be located near a military installation and compatible use zones or other operations. Information relat available in the most recent Air Installation Compatible Use for a military installation and may be accessed on the Inter- county and any municipality in which the military installation is loc	ing to high noise Zone Study or J net website of the	and com oint Land	Use Stud	dy prepared
(!	 If you are basing your offers on square footage, measur items independently measured to verify any reported information. 	rements, or bound	laries, you	u should	have those
(6) The following providers currently provide service to the Property:		226	0.00	7.02
	Electric: Stream Energy	_ phone #:	888	685	7693
	Sewer: Aqua America	phone #:	377	981	2 18.7
	Water: Agua America	phone #:	877	981	2782
	Cable: Xfrity	_ phone #: _	800	934	6484
	Trash: M&M Disposal	_ phone #: _	979	627	0063
	Natural Gas: <u>Centerpoint</u>	phone #:	713	659	2111
	Phone Company:	phone #:			
	Propane: NA	phone #:			0.180
	Internet: Xfinity	phone #:	800	934	6484
,	TXR-1406) 07-10-23 Initialed by: Buyer: , a	and Seller:	4		Page 6 of 7
(1/1/1-1-100/ 01-10-20 Illination by Dayon	Phone: 8175010622	Fax: 81	75779003	Kandace Kesler

Concerning the Property at		3618 Vacanti Dr Richmond, TX 77406	
(7) This Seller's Disclosure Notice was comple this notice as true and correct and have ENCOURAGED TO HAVE AN INSPECTOR O	no rea	Seller as of the date signed. The brokers have relason to believe it to be false or inaccurate. YOU CHOICE INSPECT THE PROPERTY.	ied on J ARE
The undersigned Buyer acknowledges receipt of the	ne foregoi	ng notice.	
Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	

(TXR-1406) 07-10-23

Initialed by: Buyer:

and Seller:

Fax: 8175779003

Page 7 of 7

HAMED NABAVI

INVOICE

150 WEST SAM HOUSTON PKWY N APT #2230

HOUSTON TX 77024

Phone: (832) 805-5556

Email: Nabavi.hamed@gmail.com

INVOICE #	DATE
1110-1	11/5/2020

CUSTOMER ID TERMS ---- HA-1110-1

BILL TO

Kandace Kesler

3618 Vacanti Dr Richmond, TX 77406

T: 214-577-3059

Email Address: kandacekesler@yahoo.com

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
Full payment in order to commencement of work for Foundation and structure inspection of the residential building	1	\$ 450.00	\$ 450.00
			∀ ∺
Thank you for your business!	SUBT	OTAL	450.00
	TAX R	RATE	0.000%
	TAX		
	TOTA	AL	\$ 450.00

If you have any questions about this invoice, please contact HAMED NABAVI, (832) 805-5556, nabavi.hamed@gmail.com

Inspection Report

Reference No.: HA1110

Date: 11/27/2020

Structural Inspection of the residence located at:

3618 Vacanti Dr Richmond, TX 77406

REMARKS:

Please note that these reports are outcome of visual inspection of the house and states the condition of house at the time of the inspection. The inspections do not cover wood rot, sidings, painting, windows, inspections not ordered, and items that cannot be visually inspected. This property was not inspected for health-related molds, fungi or environmental concerns. We are not qualified, authorized or licensed to inspect for molds, fungi or environmental concerns. These inspection reports do not guarantee the state of the house in the future. All items may not be noted in the report, only those sufficient to describe the general condition of the house at the time of the inspection. Inspector's total liability due to errors and omissions is limited and is not to exceed the inspection fee.

JOB SUMMARY:

On Thursday, Nov 04, 2020, I made an engineering inspection of the residence at the above location per owner's request. The purpose of the inspection was to detect any defects that might exist, discuss apparent causes of the damage, and make recommendations for repair, as necessary. Please note that all observations and recommendations are strictly my professional opinion and may differ from those of other professionals.

KAYSTONE BUILDING GROUP LLC, Building Structural and Inspection Services



150 WEST SAM HOUSTON PKWY N UNIT 2230








FOUNDATION INSPECTION:

Foundation problems are usually identified by some signs in houses, and below are observation results of those signs for the subject property:

- 1- **Cracks on walls**: There are minor thermal cracks observed on the exterior wall corners which is not due to foundation settlement and can be filled with proper material match with existing fillers.
- 2- Cracks around window frames or exterior doors: There is not any crack around entrance door and window of the house.
- 3- **Sticking doors or windows**: All other doors and windows open and close properly and gaps between doors and frames have not deformed.
- 4- **Foundation cracks**: There is a crack observed on the garage foundation concrete and couple of cracks at ceramic of the house which shown on the below picture in red. Location of the cracks is sign of the foundation settlement at the south east of the main building and north west of car garage building.



KAYSTONE BUILDING GROUP LLC, Building Structural and Inspection Services



150 WEST SAM HOUSTON PKWY N UNIT 2230 HOUSTON TX 77024







5- **Uneven floor**: Floor is not even over the whole house and south part of the house has more un-even surface.

6- Drainage: NA

7- Miscellaneous: There is a foundation crack at exterior south east of the garage building which is sign of lack of vibration during concrete pour or rebar placement. This is not a structural issue and can be fixed with proper grout.

OTHER OBSERVATIONS:

There are few minor thermal cracks on exterior walls which is normal cracks and need to be filed with proper fillers matched with existing materials.

CONCLUSIONS:

Based on my observations, building has experienced foundation local movement which caused cracks. However, the foundation and structural integrity condition is normal at the time of inspection. Since all the foundation movement sign is limited to small portion (As shown above) of the building and may occur due to underground water level change or lack of concrete piers, these are the most probable reasons for the structure and foundation problems on that area.

RECOMMENDATIONS:

The cracks on the brick walls are to be sealed to prevent water intrusion and potential damage due to rain.

Foundation contractor shall fix the foundation level by adding proper piles. At least once a year, the client should carefully inspect the foundation (interior elements and exterior elements) for signs of cracking, insect intrusion, moisture intrusion, or changes of any type (such as the appearance of cracks, or the widening or lengthening of existing cracks).

If you have any questions, please do not hesitate to contact me.

Sincerely,

S. Hamed Nabavi Razavi, PE

KAYSTONE BUILDING GROUP LLC, Building Structural and Inspection Services



HOUSTON TX 77024













West elevation of the building



Foundation concrte crack at garage

KAYSTONE BUILDING GROUP LLC, Building Structural and Inspection Services



150 WEST SAM HOUSTON **PKWY N UNIT 2230 HOUSTON TX 77024**






832-805-5556



Foundation concrte at exterior south west of the garage



Crack at exterior wall corner

KAYSTONE BUILDING GROUP LLC, Building Structural and Inspection Services



150 WEST SAM HOUSTON PKWY N UNIT 2230 HOUSTON TX 77024



832-805-5556









Cracks at cermaics in side of the main building

KAYSTONE BUILDING GROUP LLC, Building Structural and Inspection Services



150 WEST SAM HOUSTON PKWY N UNIT 2230 HOUSTON TX 77024



832-805-5556

