29019 ZACATE CREEK LANE FULSHEAR, TX 77441

PROPERTY REPRESENTS \$46,482 IN UPGRADES and REMODELING, as follows:

UPGRADES:

UPGRADED FLOORING

Upgrade from standard tile and carpeting to uniform grey concrete tile flooring throughout. NO CARPETING.

WATER SOFTENER

Equipment and Installation - whole house system installed in garage and under-sink equipment in kitchen

UPGRADED FIXTURES IN TWO SHOWERS

VIDEO SECURITY EQUIPMENT

Video camera installed, rear entry. Video doorbell added

SECURITY SYSTEM

CODED ENTRIES

Digital coded locks added to all entries

WOOD BLINDS

Wood blinds on all windows throughout property

TOTAL UPGRADES VALUE

\$10,000 - \$11,000 value

REMODELING AND IMPROVEMENTS

INTERIOR PAINT	\$	5,625
Original black cabinets in kitchen and bathrooms repainted in top grade enamel white paint, inside and out, two coats		
EXTERIOR PAINT	\$	1,145
Original dark brown ceiling of patio repainted white, two coats		
REAR FENCE PAINT	\$	2,080
Power wash fence; paint fence in UV resistant grey paint, two coats, including neighbor fence at gate		
WINDOWS AND DRIVEWAY	\$	346
Total House window washing Front walks and driveway power washed		
ENTRY REMODELING	\$	2,124
Relocate rear gate; design and construct concrete stepping pads with steel edging and gravel surround; irrigation modifications to the area; install new container and provide new irrigation line to container; install new planting Relocate Backflow Preventer	g \$	470
NEW CONTAINER FOR PLANTING AT ENTRY	\$	178

\$15,000 REAR GARDEN Total Landscaping of Rear Garden as follows: Remove and haul existing sod to a depth of 6 inches; dump fees; provide and install new organic landscape soil; provide and install plant materials incl. 7 Little Gem Magnolia Trees, 7 Eagleston Holly Trees, 4 Judge Solomon Azaleas, 10 Japanese Yew, 2 Multi-trunk River Birch, 55 flats Asian Jasmine ground cover, 6 Baby Gem Boxwood, 1 Pyramid Boxwood and seasonal color \$ 1,100 **TREES** Pruning and treatment of Live Oak in Front Garden and. new irrigation to area **IRRIGATION MODIFICATIONS** \$ 2,036 Front and Rear Gardens: Modification of system incl. installation of new lines, heads and fittings AIR CONDITIONING 460 Relocate thermostat from mid-wall location of hallway; repair and paint sheetrock; clean and service unit **ELECTRICAL AND LIGHTING** \$ 715 Remove dated chandeliers in entry and dining area, replace with recessed fixtures. Replace mismatched recessed ceiling fixtures,

TOTAL REMODELING	\$31,279.00
DESIGN AND CONTRACTING 15%	\$ 4,691.85
TAX	<u>\$ 511.98</u>
TOTAL REMODELING	\$36,482.83

add rheostats in kitchen and dining areas.

RECAP:

REMODELING COSTS \$36,482.83 UPGRADES VALUE (\$10,000 - \$11,000) \$10,000.00

TOTAL VALUE UPGRADES AND REMODELING \$46,482.83