

APPROVED BY THE TEXAS REAL ESTATE COMMISSION (TREC)



SELLER'S DISCLOSURE NOTICE

CONCERNING THE PROPERTY AT	3 Sausalito Drive, Galveston, Texas, 775 (Street A	654-6907 Galveston County Address and City)				
	LER'S KNOWLEDGE OF THE CONDITION OF THE CONDITIONS OR WARRANTIES T	ON OF THE PROPERTY AS OF THE DATE SIGNED BY THE PURCHASER MAY WISH TO OBTAIN. IT IS NOT A				
Seller is is not occupying the P 1. The Property has the items checked						
<u>y</u> Range	<u>y</u> Oven	<u>y</u> Microwave				
<u>y</u> Dishwasher	nTrash Compactor	yDisposal				
<u>y</u> Washer/Dryer Hookups	<u>y</u> Window Screens	nRain Gutters				
<u>y</u> Security System	<u>y</u> Fire Detection Equipment	nIntercom System				
	y Smoke Detector					
	nSmoke Detector-Hearing Imp	aired				
	nCarbon Monoxide Alarm					
	<u>y</u> Emergency Escape Ladder(s)					
nTV Antenna	<u>y</u> Cable TV Wiring	<u>n</u> Satellite Dish				
<u>y</u> Ceiling Fan(s)	nAttic Fan(s)	yExhaust Fan(s)				
yCentral A/C	<u>y</u> Central Heating	nNall/Window Air Conditioning				
yJlumbing System	<u>n</u> Septic System	youblic Sewer System				
<u>y</u> Patio/Decking	<u>y</u> Outdoor Grill	<u>y</u> Fences				
<u>n</u> Pool	<u>n</u> Sauna	<u>n</u> Spa <u>n</u> Hot Tub				
n Pool Equipment Fireplace(s) & Chimney n (Wood burning)	nPool Heater	yAutomatic Lawn Sprinkler System Fireplace(s) & Chimney y (Mock)				
n Natural Gas Lines		n Gas Fixtures				
nLiquid Propane Gas: n	LP Community (Captive) <u>n</u> _P on	Property				
		s Steel TubingCopper				
Garage: <u>y</u> Attached	nNot Attached y	Carport				
Garage Door Opener(s): n Ele	ectronic n Control(s)	_				
Water Heater: n Ga	as y Electric					
Water Supply: <u>y</u> Ci	ity <u>n</u> Well	<u>n</u> MUD <u>n</u> Co-op				
Roof Type: shingle	Ag	e: 8 yrs (approx.)				
	e above items that are not in working on the seribe. (Attained)	condition, that have known defects, or that are in ach additional sheets if necessary):				
-						

09-01-2023

766, Health and Safety Code?*						
Chapter 766 of the Health and Safety Code requires one-family or two-family dwellings to have working smoke detect installed in accordance with the requirements of the building code in effect in the area in which the dwelling is local including performance, location, and power source requirements. If you do not know the building code requirement effect in your area, you may check unknown above or contact your local building official for more information. A buyer require a seller to install smoke detectors for the hearing impaired if: (1) the buyer or a member of the buyer's family will reside in the dwelling is hearing impaired; (2) the buyer gives the seller written evidence of the hearing impairment fra licensed physician; and (3) within 10 days after the effective date, the buyer makes a written request for the seller to install smoke detectors for the hearing impaired and specifies the locations for the installation. The parties may agree who will be the cost of installing the smoke detectors and which brand of smoke detectors to install.						
n Interior Walls	nCeilings		n Floors			
Exterior Walls	n Doors		<u>n</u> Windows			
nRoof		ion/Slab(s)	<u>n</u> Sidewalks			
<u>n</u> Walls/Fences	<u>n</u> Driveway		n Intercom System			
<u>n</u> Plumbing/Sewers/Septics <u>n</u> Electrical Systems <u>n</u> Lighting Fixtures						
<u>y</u> Other Structural Compon	ents (beschbe).		living area ceiling 7/2023.			
Other Structural Compon	e is yes, explain. (Attach ad	ditional sheets if n	necessary): Once mold was noticed, had			
Other Structural Compon	e is yes, explain. (Attach ad areas as well as all A/C unit	ditional sheets if n	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to			
Other Structural Compon If the answer to any of the above it remediated including ceiling control condensation. Added in	e is yes, explain. (Attach ad areas as well as all A/C unit	ditional sheets if n s, ductwork and v cover to attic acces	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to ss door. No further issues.			
Other Structural Compon If the answer to any of the above it remediated including ceiling control condensation. Added in Are you (Seller) aware of any of	e is yes, explain. (Attach ad areas as well as all A/C unit assulation to 14" and hatch of the following conditions? V	ditional sheets if ness, ductwork and vector to attic access	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to so door. No further issues. are aware, write No (N) if you are not aware.			
Other Structural Compon If the answer to any of the above it remediated including ceiling control condensation. Added in Are you (Seller) aware of any of a Active Termites (includes	e is yes, explain. (Attach ad areas as well as all A/C unit as all and hatch of the following conditions? Volume wood destroying insects)	ditional sheets if nes, ductwork and vector to attic access Write Yes (Y) if you n Previou	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to ss door. No further issues. are aware, write No (N) if you are not aware. as Structural or Roof Repair			
Other Structural Compon If the answer to any of the above it remediated including ceiling control condensation. Added in Are you (Seller) aware of any of any Active Termites (includes a Termite or Wood Rot Dan	e is yes, explain. (Attach ad areas as well as all A/C unit asulation to 14" and hatch of the following conditions? Wood destroying insects) mage Needing Repair	ditional sheets if notes, ductwork and vector to attic access Write Yes (Y) if you n Previou n Hazardo	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to ss door. No further issues. are aware, write No (N) if you are not aware. Its Structural or Roof Repair ous or Toxic Waste			
Other Structural Compone If the answer to any of the above it remediated including ceiling control condensation. Added in Are you (Seller) aware of any of an Active Termites (includes Termite or Wood Rot Dan Previous Termite Damage	e is yes, explain. (Attach ad areas as well as all A/C unit asulation to 14" and hatch of the following conditions? We wood destroying insects) hage Needing Repair	ditional sheets if notes, ductwork and vectors to attic accession. Write Yes (Y) if you n Previou n Hazardo n Asbesto	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to as door. No further issues. are aware, write No (N) if you are not aware. as Structural or Roof Repair ous or Toxic Waste os Components			
Other Structural Compone it remediated including ceiling control condensation. Added in Are you (Seller) aware of any of Active Termites (includes Termite or Wood Rot Dan Previous Termite Damage Previous Termite Treatments)	e is yes, explain. (Attach ad areas as well as all A/C unit asulation to 14" and hatch of the following conditions? We wood destroying insects) hage Needing Repair	ditional sheets if notes, ductwork and vectors attic access. Write Yes (Y) if you n Previou n Hazardo n Asbesto n Urea-fo	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to as door. No further issues. are aware, write No (N) if you are not aware. as Structural or Roof Repair ous or Toxic Waste as Components rmaldehyde Insulation			
Other Structural Compon If the answer to any of the above it remediated including ceiling control condensation. Added in Are you (Seller) aware of any of a Active Termites (includes a Previous Termite Damage a Previous Termite Treatmen Improper Drainage	e is yes, explain. (Attach ad areas as well as all A/C unit insulation to 14" and hatch of the following conditions? We wood destroying insects) in age Needing Repair	ditional sheets if notes, ductwork and vector to attic access. Write Yes (Y) if you n Previou n Hazardo n Asbesto n Urea-fo n Radon (eccessary): Once mold was noticed, had ents. Placed box fan near attic air handler to so door. No further issues. are aware, write No (N) if you are not aware. It is Structural or Roof Repair ous or Toxic Waste os Components rmaldehyde Insulation			
Jother Structural Componed in the answer to any of the above it remediated including ceiling control condensation. Added in the Are you (Seller) aware of any of an Active Termites (includes an Termite or Wood Rot Dan Previous Termite Damage an Previous Termite Treatment Improper Drainage you water Damage Not Due to the Active Termite Componed in the Improper Drainage you water Damage Not Due to the Active Termite Treatment Improper Drainage you water Damage Not Due to the Active Termite Treatment Improper Drainage you water Damage Not Due to the Active Termite Treatment Improper Drainage you water Damage Not Due to the Active Termite Treatment Improper Drainage you water Damage Not Due to the Active Termites Treatment Improper Drainage you water Damage Not Due to the Active Termites Treatment Improper Drainage you water Damage Not Due to the Active Termites Treatment Improper Drainage you water Damage Not Due to the Active Termites Treatment Improper Drainage you water Damage Not Due to the Active Termites Treatment Improper Drainage you water Damage Not Due to the Active Termites Treatment Improper Drainage you water Damage Not Due to the Active Termites Termites Treatment Improper Drainage you water Damage Not Due to the Active Termites Term	e is yes, explain. (Attach ad areas as well as all A/C unit insulation to 14" and hatch of the following conditions? We wood destroying insects) in age Needing Repair ent	ditional sheets if notes, ductwork and vectors to attic accessions. Write Yes (Y) if you n	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to ss door. No further issues. are aware, write No (N) if you are not aware. Its Structural or Roof Repair ous or Toxic Waste os Components rmaldehyde Insulation Gas ased Paint			
Other Structural Componed in the answer to any of the above it remediated including ceiling control condensation. Added in the Are you (Seller) aware of any of the Active Termites (includes the Active Termites (includes the Active Termite Damage the Active Termite Treatment the Active Termite Treatment the Active Termites Termites Treatment the Active Termites Termites Treatment the Active Termites	e is yes, explain. (Attach ad areas as well as all A/C unit asulation to 14" and hatch of the following conditions? We wood destroying insects) mage Needing Repair ent	ditional sheets if notes, ductwork and vectors to attic accessions. Write Yes (Y) if you n	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to se door. No further issues. are aware, write No (N) if you are not aware. It is Structural or Roof Repair ous or Toxic Waste os Components rmaldehyde Insulation Gas ased Paint um Wiring			
Jother Structural Componer If the answer to any of the above it remediated including ceiling control condensation. Added in the Are you (Seller) aware of any of the Active Termites (includes the Active Termites (includes the Active Termite or Wood Rot Dan the Previous Termite Damage the Active Termite Treatment the Improper Drainage the Mater Damage Not Due to the Active Termite, Soil Movement of the Previous Termite Treatment the Active Termites Term	e is yes, explain. (Attach ad areas as well as all A/C unit asulation to 14" and hatch of the following conditions? We wood destroying insects) mage Needing Repair ent	ditional sheets if notes, ductwork and vectors attic access. Write Yes (Y) if you note Previou notes. Hazardon notes. Asbesto notes. Previou notes.	necessary): Once mold was noticed, had ents. Placed box fan near attic air handler to as door. No further issues. are aware, write No (N) if you are not aware. as Structural or Roof Repair ous or Toxic Waste os Components rmaldehyde Insulation Gas as ased Paint tum Wiring as Fires			
Other Structural Componed in the answer to any of the above it remediated including ceiling control condensation. Added in the Are you (Seller) aware of any of the Active Termites (includes the Active Termites (includes the Active Termite Damage the Active Termite Treatment the Active Termites Termites Treatment the Active Termites Termites Termites Termites Termites Treatment the Active Termites Te	e is yes, explain. (Attach ad areas as well as all A/C unit asulation to 14" and hatch of the following conditions? We wood destroying insects) mage Needing Repair ent	ditional sheets if notes, ductwork and vector to attic access. Write Yes (Y) if you note Previou notes. Asbesto notes. Asbesto notes. Aluming notes. Previou notes. Previou notes. Previou notes. Subsurface Previou notes.	pecessary): Once mold was noticed, had ents. Placed box fan near attic air handler to ss door. No further issues. are aware, write No (N) if you are not aware. It is structural or Roof Repair ous or Toxic Waste os Components rmaldehyde Insulation Gas assed Paint tum Wiring its Fires ared Easements face Structure or Pits is Use of Premises for Manufacture of			
Other Structural Componing If the answer to any of the above it remediated including ceiling control condensation. Added in Are you (Seller) aware of any of an Active Termites (includes an Active Termites (includes an Active Termite or Wood Rot Dan Previous Termite Damage an Previous Termite Treatmen Improper Drainage an Active Damage Not Due to Landfill, Settling, Soil Move an Single Blockable Main Drain	e is yes, explain. (Attach ad areas as well as all A/C unit insulation to 14" and hatch of the following conditions? Wood destroying insects) mage Needing Repair ent. ent. o a Flood Event vement, Fault Lines ain in Pool/Hot Tub/Spa*	ditional sheets if notes, ductwork and vectors attic access. Write Yes (Y) if you note Previou	eccessary): Once mold was noticed, had ents. Placed box fan near attic air handler to so door. No further issues. are aware, write No (N) if you are not aware. It is structural or Roof Repair ous or Toxic Waste os Components rmaldehyde Insulation Gas as ased Paint the wiring is Fires are Easements Face Structure or Pits			

Seller's Disclosure Notice Concerning the Property at Street Address and City Page 3
(Street Address and City) Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need of repair? Yes (if you are aware) No (if you are not aware). If yes, explain (attach additional sheets if necessary).
Are you (Seller) aware of any of the following conditions?* Write Yes (Y) if you are aware, write No (N) if you are not aware.
Present flood insurance coverage
Previous flooding due to a failure or breach of a reservoir or a controlled or emergency release of water from a reservoir
Previous water penetration into a structure on the property due to a natural flood event
Write Yes (Y) if you are aware, and check wholly or partly as applicable, write No (N) if you are not aware.
Located wholly partly in a 100-year floodplain (Special Flood Hazard Area-Zone A, V, A99, AE, AO, AH, VE, or AR)
Located wholly partly in a 500-year floodplain (Moderate Flood Hazard Area-Zone X (shaded))
Located
nLocated
Located wholly partly in a reservoir
If the answer to any of the above is yes, explain (attach additional sheets if necessary): located in coastal flood zone VE
"500-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a moderate flood hazard area, which is designated on the map as Zone X (shaded); and (B) has a two-tenths of one percent annual chance of flooding, which is considered to be a moderate risk of flooding. "Flood pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that is subject to controlled inundation under the management of the United States Army Corps of
Engineers. "Flood insurance rate map" means the most recent flood hazard map published by the Federal Emergency
Management Agency under the National Flood Insurance Act of 1968 (42 U.S.C. Section 4001 et seq.). "Floodway" means an area that is identified on the flood insurance rate map as a regulatory floodway, which includes the channel of a river or other watercourse and the adjacent land areas that must be reserved for the discharge of a base flood, also referred to as a 100-year flood, without cumulatively increasing the water surface elevation of more than a designated height.
"Reservoir" means a water impoundment project operated by the United States Army Corps of Engineers that is intended to retain water or delay the runoff of water in a designated surface area of land.
Have you (Seller) ever filed a claim for flood damage to the property with any insurance provider, including the National Flood Insurance Program (NFIP)?* ☐ Yes ☑ No. If yes, explain (attach additional sheets as necessary):
*Homes in high risk flood zones with mortgages from federally regulated or insured lenders are required to have flood insurance. Even when not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate risk, and low risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the structure(s).
Have you (Seller) ever received assistance from FEMA or the U.S. Small Business Administration (SBA) for flood damage to the property? Yes No. If yes, explain (attach additional sheets as necessary):

					09-01-2023					
	Seller's Disclosure Notice Concerning the Prop	perty at <u>25043 Saus</u>	alito Drive, Galveston, Texas, 77554- (Street Address and Cit	<u>3907 Galveston County</u> Pag y)	je 4					
9.	Are you (Seller) aware of any of the following? Write Yes (Y) if you are aware, write No (N) if you are not aware.									
			rations or repairs made witho	ut necessary permits or	not in					
	Homeowners' Association or maintenance fees or assessments.									
	Any "common area" (facilities such as pools, tennis courts, walkways, or other areas) co-owned in undivided interest with others.									
	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the new-roperty .									
	$\underline{\underline{n}}$ Any lawsuits directly or indirectly affect	cting the Propert	y.							
	Any condition on the Property which materially affects the physical health or safety of an individual.									
	Any rainwater harvesting system located on the property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.									
	Any portion of the property that is loc	ated in a ground	water conservation district o	a subsidence district.						
	If the answer to any of the above is yes, expl Mandatory HOA dues	ain. (Attach addi	tional sheets if necessary): $\underline{\hspace{1cm}}$							
	Community pool									
 adjacent to public beaches for more information. 11. This property may be located near a military installation and may be affected by high noise or air installation compate zones or other operations. Information relating to high noise and compatible use zones is available in the most resultance Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accepted the Internet website of the military installation and of the county and any municipality in which the military installation located. 										
	dotloop verified	٦		dotloop verified	1					
70	mmy Lee 05/19/24 6:15 PM CDT CLIB-DNEO-UP6B-UAMH	05/19/2024	Joy Lee	05/19/24 6:14 PM CDT RFUU-KNDR-LELU-6XLJ	05/19/2024					
Sign	ature of Seller	Date	Signature of Seller		Date					
The	e undersigned purchaser hereby acknowledg	es receipt of the t	oregoing notice.							
Sign	ature of Purchaser	Date	Signature of Purchaser		Date					
	<u> </u>									



This form was prepared by the Texas Real Estate Commission in accordance with Texas Property Code § 5.008(b) and is to be used in conjunction with a contract for the sale of real property entered into on or after September 1, 2023. Texas Real Estate Commission, P.O. Box 12188, Austin, TX 78711-2188, 512-936-3000 (http://www.trec.texas.gov) TREC NO. 55-0. This form replaces OP-H.