



735 N. Water Street, Suite 175 Milwaukee, WI 53202

October 10, 2022

Ms. Linda Tsacalides, Portfolio Supervisor Creative Management Company 8323 Southwest Freeway, Suite 330 Houston, TX 77074

RE: River Oaks Townhomes

Dear Ms. Tsacalides:

We are pleased to submit the following Insurance Appraisal report. Congratulations! By authorizing this service, the Board of Directors has fulfilled its fiduciary responsibility, and now has expert advice to establish accurate insurance replacement values to help protect the community association's future property values.

Reserve Advisors, LLC has developed an exclusive affiliation with Specialty Property Appraisals LLC to provide its clients with the most authoritative Insurance Appraisals for community associations. Mr. William Jaeger, President of Specialty Property Appraisals, has over 30 years of experience conducting property Insurance Appraisals. Mr. Jaeger has conducted Insurance Appraisals for more than 300 community associations.

It has been a privilege to serve you. Your community can benefit from an economical Annual Review of its Insurance Appraisal. Accurate replacement costs ensure your members' investment in their units and might save your community association insurance premiums. We'll contact you when it's time to consider an economical update of your Insurance Appraisal.

The enclosed Insurance Appraisal Report contains the following:

- Transmittal Letter
- Insurance Summary
- Insurance Detail Report
- Credentials

Sincerely,

Alan M. Ebert, R.S., PRA Director of Quality Assurance

INSURANCE APPRAISAL RIVER OAKS TOWNHOMES



As Of: October 9, 2022





October 9, 2022

River Oaks Townhomes 4040 San Felipe Road Houston, TX 77027

RE: <u>Insurance Appraisal – River Oaks Townhomes</u>

To Whom it May Concern:

We have made an appraisal of certain designated property of interest to the River Oaks Townhomes, and submit our findings in this report.

The purpose of our appraisal investigation was to express our opinion of the cost of reproduction new and the insurance exclusion for insurance purposes.

Cost of Reproduction New, an appraisal term synonymous with "new replacement cost" in the insurance industry, and Insurance Exclusion are defined as follows:

Cost of Reproduction New is the amount required to reproduce property in like kind and materials at one time in accordance with current market prices for materials, labor and manufactured equipment, contractor's overhead, profit, and fees, but without provisions for overtime or bonuses for labor and premiums for materials.

Insurance Exclusion is a provision in an insurance contract describing property, or types of property, that are not covered by the contract. The insurance exclusion amount is deducted from the new replacement cost to arrive at an insurable value. Insurance Exclusions include basement excavation, foundation below ground, and piping below ground.

In estimating the cost of reproduction new, we did not consider costs associated with conforming with local ordinances or other legal restrictions, the cost of demolition in connection with reconstruction, or the cost to remove destroyed property.

In the event of partial loss, the amount of loss may be based upon the repair cost, which is usually proportionately higher than the cost of reproduction new for the entire property as defined and included in this report.

Exclusions have been calculated according to our experience with property that is typically excluded for insurance purposes. We accept no responsibility of liability for the excluded property. It is our recommendation that you consult with your insurance agents so that these figures may be compared to those in your current coverage.



River Oaks Townhomes October 9, 2022 Page 2

Natural Disaster Disclaimer

Recovery and reconstruction from widespread natural disasters such as hurricane or flood will create abnormal shortages of labor and materials which, in turn, will cause price increases as much as 50 percent or more above normal costs prior to the event. These increases, while temporary, may last for a year or more before returning to normal market conditions.

The values as reported herein are estimated based on normal market conditions and are considered appropriate for various purposes including insurance coverage. Some or all of the estimated values as reported herein may be inadequate for reconstruction or repair in periods after a widespread natural disaster.

Also excluded were assets of an intangible nature, records and drawings, inventory items, personal property of employees and leased property.

The appraisal report includes the following:

This letter, which summarizes the appraisal procedures applied in the appraisal process;

The following appraisal reports:

Insurance Summary
Insurance Detail Report with Color Photographs
Building Valuation Worksheets

Our appraisal investigation included the following:

Buildings and their related service systems

Excluded from our consideration were the following:

Land
Land Improvements
Contents
Infrastructure
Licensed Vehicles



River Oaks Townhomes October 9, 2022 Page 3

Based upon our appraisal investigation and analysis, and the premises outlined above, it is our opinion of value that as of October 9, 2022, the Cost of Reproduction New is:

Cost of Reproduction New: \$20,786,900

Exclusions: \$872,800

Cost of Reproduction New Less Exclusions: \$19,914,100

Respectfully submitted:

William N. Jaeger, ASA

Accredited Senior Appraiser (ASA), American Society of Appraisers



William M. Jaeger



Assumptions and Limiting Conditions

This appraisal report has been made with the following general assumptions:

It is assumed that the utilization of the improvements is within the boundaries or property lines of the property described and that there is no encroachment or trespass unless noted in the report. No survey has been offered or ordered in connection with the service.

- Building areas discussed have been calculated in accord with standards developed by the American Standards Association as included in Real Estate Appraisal Terminology.
- It is assumed that there are no hidden or unapparent conditions of the property, subsoil, or structures that render them more or less valuable. No responsibility is assumed for such conditions or for arranging for engineering studies that may be required to discover them.
- All engineering and architecture is assumed to be correct.
- We have assumed that the property is free from insect infestations, dry rot, and fungus growth. The mechanical systems, heating system, piping, plumbing, and other building service equipment have not been specifically tested, but are assumed to be in good working order and adequate for the buildings, unless specifically cited otherwise.
- It is assumed that all required licenses, certificates of occupancy, consents, or other legislative or administrative authority from any local, state, or national government or private entity or organization have been or can be obtained or renewed for any use on which the value estimate contained in this report is based.
- It is assumed that there is full compliance with all applicable federal, state, and local environmental regulations and laws unless noncompliance is stated, defined, and considered in the appraisal report.
- It is assumed that there are no hazardous substances on the subject property or on surrounding properties that
 would potentially adversely affect the value of the subject property. The analyses and value conclusions in this
 appraisal report are null and void should any such hazardous materials be discovered. We possess no expertise or
 qualifications for identifying hazardous materials. We assume no responsibility for investigating or arranging for
 competent engineering studies of the property to identify such hazardous materials.
- The information furnished by others is believed to be reliable and has been confirmed with public records or a knowledgeable party when possible. However, no warranty is given for its accuracy.
- Our appraisal is valid only for the function, which is stated herein. Any other use of, or reliance upon, this report by you or third parties is invalid.



- Liability of for errors and omissions, if any, in this work is limited to the amount of its compensation for the work performed in this assignment.
- All services provided are performed in accordance with the Uniform Standards of Professional Appraisal Practice.
 We have acted as an independent contractor and have no personal interest, either present or contemplated, in the subject property. We certify that no fee received, or to be received, or the employment of our services, is in any way contingent upon the opinion reported. All files, work papers or documents developed during the course of the assignment shall be our property. We will retain these data for at least five years.

INSURANCE SUMMARY REPORT



Building	Address	Cost of Reproduction New	Exclusions	Cost of Reproduction New Less Exclusions
CONDOMINIUM #1 - 33 UNITS	4040 SAN FELIPE ROAD	\$4,344,800	\$195,900	\$4,148,900
CONDOMINIUM #2 - 83 UNITS	4040 SAN FELIPE ROAD	\$12,353,100	\$519,200	\$11,833,900
CONDOMINIUM #3 - 27 UNITS	4040 SAN FELIPE ROAD	\$3,435,000	\$157,700	\$3,277,300
ENTRANCE MONUMENT (2)		\$20,000	0\$	\$20,000
PERIMETER FENCE		\$50,000	0\$	\$50,000
SWIMMING POOL		\$70,000	0\$	\$70,000
GUARD HOUSE		\$20,000	0\$	\$20,000
SECURITY GATE		000′9\$	0\$	000′9\$
GAZEBO		\$18,000	0\$	\$18,000
CARPORT #1		\$15,000	0\$	\$15,000
CARPORT #2		\$20,000	0\$	\$20,000
CARPORT #3		\$30,000	0\$	\$30,000
CARPORT #4		000′09\$	0\$	000'09\$
CARPORT #5		\$120,000	\$0	\$120,000
CARPORT #6		\$40,000	\$0	\$40,000
SWIMMING POOL #2		\$110,000	0\$	\$110,000
WOOD PERIMETER WALL		\$75,000	\$0	\$75,000
TOTALS:	S:	\$20,786,900	\$872,800	\$19,914,100



INSURANCE DETAIL REPORT



INSURANCE DETAIL REPORT

RIVER OAKS TOWNHOMES Owner: CONDOMINIUM #1 - 33 UNITS **Building:**

4040 SAN FELIPE ROAD Address:

HOUSTON, TX 77027 City / State / Zip Code:

HARRIS County:

1956 No. Of Stories: Year Built:

Sq. Ft. Area Building Area: 27,932

FRAME

Framing:

(1) FRAME ISO Class (1-6): REINFORCED CONCRETE FOOTINGS, FOUNDATIONS WALLS, SLAB. Foundation: BRICK ON BRICK, GLASS AND METAL WINDOWS, PATIO / BALCONY DOORS, METAL ENTRANCE DOOR. **Exterior Walls:**

SHINGLE ROOFING ON WOOD DECK AND TRUSSES (PITCHED).

WOOD DECK AND JOISTS. Structural Floor:

Roofing:

CONCRETE, WOOD, TILE. Flooring:

DRYWALL. Ceiling: DRYWALL ON STUDS. Partitions:

FIRE EXTINGUISHERS, SMOKE DETECTORS.

Fire Safety:

ELECTRICAL, PLUMBING, HEATING, AIR CONDITIONING (SPLIT SYSTEM). **Building Service Systems:** COVERED WALKWAYS AND PASSAGEWAYS, GUTTERS AND DOWNSPOUTS, PATIOS (WOOD ENCLOSURE), BALCONIES, STAIRS. Additional Features:

S	ı
~	
$\overline{\circ}$	
_	
\sim	
\neg	
_	Γ
$\overline{}$	
U	
÷,	
_	
$\overline{}$	
U	
(
_	
_	
_	
$\overline{}$	
${}^{\circ}$	
_	
Ĕ	
◁	Γ
	Γ
_)	Γ
_	
7	Γ
\$	
>	Γ
	٠.

\$4,344,800 COST OF REPRODUCTION NEW:

EXCLUSIONS:

\$195,900

\$4,148,900 COST OF REPRODUCTION NEW LESS EXCLUSIONS:



Long-term thinking. Everyday commitment.



FRONT



SIDE





BALCONIES

COURTYARD



STAIRS





Property Express

10/10/2022

VALUATION

Value Basis:

Valuation Number: ESTIMATE-0006864

Effective Date: 10/09/2022

Reconstruction Expiration Date: 10/09/2023

Estimate Expiration Date: 01/07/2023

Cost as of: 06/2022

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 1 - Condominium - 33 Units

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium Story Height: 9 ft.

Construction Type: 100% Frame (ISO 1) Number of Stories: 2

Gross Floor Area: 27,932 sq.ft. Irregular None

Adjustment:

Construction Quality: 1.5 - Economy/Average

Year Built: 1956

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

Overhead and Profit: 20% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.

©CoreLogic. All rights reserved. CORELOGIC, the CoreLogic Logo, Commercial Express, and Commercial ExpressLync are the property of CoreLogic, Inc.



Property Express

Policy Number: ESTIMATE-0006864 10/10/2022

SUMMARY OF COSTS		Recons	struction Ex	clusion
SUPERSTRUCTURE				
Site Preparation				\$3,897
Foundations			\$99,580	\$63,236
Foundation Wall, Interior Foundations,	Slab On Ground			
Exterior		Ş	\$908,203	
Framing, Exterior Wall, Exterior Wall, S	tructural Floor, Roof			
Interior		\$1	,004,490	
Floor Finish, Ceiling Finish, Partitions				
Mechanicals		\$1	,647,926	\$128,796
Heating, Cooling, Fire Protection, Plum	bing, Electrical, Elevators			
Built-ins		Ç	\$346,006	
SUBTOTAL RC		\$	4,006,206	\$195,92
ADDITIONS				
Building Items			\$142,6	692
Total Additions			\$142,692	
TOTAL RC Section 1		\$	4,148,898	\$195,92
OTAL RC BUILDING 1 Condominium - 3	3 Units	\$	4,148,898	\$195,92
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
ATION TOTAL, Location 1	\$4,148,898	27,932	\$149	
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
JATION GRAND TOTAL	\$4,148,898	27,932	\$149	

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Property Express
EQUIPMENT REPORT

Policy Number: ESTIMATE-0006864 10/10/2022

VALUATION

Valuation Number:ESTIMATE-0006864Effective Date:10/09/2022Value Basis:ReconstructionExpiration Date:10/09/2023

Estimate Expiration Date: 01/07/2023 Cost as of: 06/2022

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

Equipment: Building items and site improvements

acement D	epreciated
5142,692	\$142,692
6142,692	\$142,692
6142,692	\$142,692
	\$142,692 \$142,692 \$142,692

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Property Express
SUMMARY REPORT

Policy Number: ESTIMATE-0006864 10/10/2022

VALUATION

Valuation Number:ESTIMATE-0006864Effective Date:10/09/2022Value Basis:ReconstructionExpiration Date:10/09/2023Estimate Expiration Date:01/07/2023

Cost as of: 06/2022

Sa.Ft.

\$/Sa.Ft.

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

River Oaks Townhomes Owners Association

BUILDING 1: SUPERSTRUCTURE

4040 San Felipe Street

Houston, TX 77027 USA

VALUATION GRAND TOTAL	\$4,148,898	27,932	\$149	
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
LOCATION TOTAL, Location 1	\$4,148,898	27,932	\$149	
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
-100% Variance	(\$4,148,898)			
100% Co-insurance Requirement	\$4,148,898			\$4,148,898
Percent of Insurance to Value	0%			
Total Insured Amount	\$0			
BUILDING INSURANCE SUMMARY				
BUILDING TOTAL , Building 1	\$4,148,898	27,932	\$149	
Total Additions:	\$142,692			
Section 1 100% Condominium	\$4,006,206	27,932	\$143	
Section Totals	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
Section 1 100% Condominium	\$4,006,206	27,932	\$143	
BUILDING 1. SUPERSTRUCTURE	Reconstruction	34.i t.	φ/3q.Ft.	

Reconstruction

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.

INSURANCE DETAIL REPORT

RIVER OAKS TOWNHOMES Owner: CONDOMINIUM #2 - 83 UNITS **Building:**

4040 SAN FELIPE ROAD Address:

HOUSTON, TX 77027 City / State / Zip Code:

HARRIS County:

1956 No. Of Stories: Year Built:

Sq. Ft. Area Building Area: 83,980

FRAME Framing:

REINFORCED CONCRETE FOOTINGS, FOUNDATIONS WALLS, SLAB. (1) FRAME ISO Class (1-6): Foundation: BRICK ON BRICK, GLASS AND METAL WINDOWS, PATIO / BALCONY DOORS, METAL ENTRANCE DOOR. **Exterior Walls:**

SHINGLE ROOFING ON WOOD DECK AND TRUSSES (PITCHED). Roofing:

WOOD DECK AND JOISTS. Structural Floor:

CONCRETE, WOOD, TILE. Flooring:

DRYWALL. Ceiling: DRYWALL ON STUDS. Partitions:

Fire Safety:

ELECTRICAL, PLUMBING, HEATING, AIR CONDITIONING (SPLIT SYSTEM). **Building Service Systems:**

FIRE EXTINGUISHERS, SMOKE DETECTORS.

COVERED WALKWAYS AND PASSAGEWAYS, GUTTERS AND DOWNSPOUTS, PATIOS (WOOD ENCLOSURE), BALCONIES, STAIRS. Additional Features:

VALUATION CONCLUSIONS

\$12,353,100 COST OF REPRODUCTION NEW:

EXCLUSIONS:

\$519,200

\$11,833,900 COST OF REPRODUCTION NEW LESS EXCLUSIONS:



Long-term thinking. Everyday commitment.



FRONT



SIDE



BACK



PATIOS / BALCONIES

COURTYARD



COVERED WALKWAY / STAIRS



Long-term thinking. Everyday commitment.



Property Express

10/10/2022

VALUATION

Value Basis:

Valuation Number: ESTIMATE-0006864

Effective Date: 10/09/2022

Expiration Date: 10/09/2023

Estimate Expiration Date: 01/07/2023

Cost as of: 06/2022

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

Reconstruction

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 2 - Condominium - 83 Units

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium Story Height: 9 ft.

Construction Type: 100% Frame (ISO 1) Number of Stories: 2

Gross Floor Area: 83,980 sq.ft. Irregular None

Adjustment:

Construction Quality: 1.5 - Economy/Average

Year Built: 1956

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

Overhead and Profit: 20% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.

©CoreLogic. All rights reserved. CORELOGIC, the CoreLogic Logo, Commercial Express, and Commercial ExpressLync are the property of CoreLogic, Inc.



Property Express

Policy Number: ESTIMATE-0006864 10/10/2022

SUMMARY OF COSTS		Recons	struction Ex	clusion
SUPERSTRUCTURE				
Site Preparation				\$11,717
Foundations		Ş	\$299,397	\$121,802
Foundation Wall, Interior Foundations, Sl	ab On Ground			
Exterior		\$2	,218,952	
Framing, Exterior Wall, Exterior Wall, Stru	uctural Floor, Roof			
Interior		\$2	,972,982	
Floor Finish, Ceiling Finish, Partitions				
Mechanicals		\$4	,943,361	\$385,700
Heating, Cooling, Fire Protection, Plumbin	ng, Electrical, Elevators			
Built-ins		\$1	,040,298	
SUBTOTAL RC		\$1	1,474,990	\$519,2°
ADDITIONS				
Building Items			\$358,8	392
Total Additions			\$358,892	
TOTAL RC Section 1		\$1	1,833,882	\$519,2
OTAL RC BUILDING 2 Condominium - 83	Units	\$1	1,833,882	\$519,2°
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
ATION TOTAL, Location 1	\$11,833,882	83,980	\$141	
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
UATION GRAND TOTAL	\$11,833,882	83,980	\$141	

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Property Express
EQUIPMENT REPORT

Policy Number: ESTIMATE-0006864 10/10/2022

VALUATION

Valuation Number:ESTIMATE-0006864Effective Date:10/09/2022Value Basis:ReconstructionExpiration Date:10/09/2023

Estimate Expiration Date: 01/07/2023 Cost as of: 06/2022

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

Equipment: Building items and site improvements

Equipment: Building items and site improvements		
	Replacement	Depreciated
Building 2, Section 1		
Building Items		
Balconies		
(1) Balconies, Wood frame	\$358,892	\$358,892
LOCATION 1 - River Oaks Townhomes Owners Association TOTAL	\$358,892	\$358,892
TOTAL		£250.002
TOTAL	\$358,892	\$358,892

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Property Express
SUMMARY REPORT

Policy Number: ESTIMATE-0006864 10/10/2022

VALUATION

Valuation Number:ESTIMATE-0006864Effective Date:10/09/2022Value Basis:ReconstructionExpiration Date:10/09/2023

Estimate Expiration Date: 01/07/2023 Cost as of: 06/2022

Sa Ft

\$/Sa Et

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

River Oaks Townhomes Owners Association

BUILDING 2: SUPERSTRUCTURE

4040 San Felipe Street

Houston, TX 77027 USA

BUILDING 2. SUPERSTRUCTURE	Reconstruction	oq.rι.	ə/əq.Fι.	
Section 1 100% Condominium	\$11,474,990	83,980	\$137	
Section Totals	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
Section 1 100% Condominium	\$11,474,990	83,980	\$137	
Total Additions:	\$358,892			
BUILDING TOTAL, Building 2	\$11,833,882	83,980	\$141	
BUILDING INSURANCE SUMMARY				
Total Insured Amount	\$0			
Percent of Insurance to Value	0%			
100% Co-insurance Requirement	\$11,833,882			\$11,833,882
-100% Variance	(\$11,833,882)			
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
LOCATION TOTAL, Location 1	\$11,833,882	83,980	\$141	
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
VALUATION GRAND TOTAL	\$11,833,882	83,980	\$141	
	End of Donort			

Reconstruction

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.

INSURANCE DETAIL REPORT

Owner: RIVER OAKS TOWNHOMES

Building: CONDOMINIUM #3 - 27 UNITS

Address: 4040 SAN FELIPE ROAD

City / State / Zip Code: HOUSTON, TX 77027

County: HARRIS
Vear Built: 1956

No. Of Stories: 2

Framing: FRAME

ISO Class (1-6): (1) FRAME

Foundation: REINFORCED CONCRETE FOOTINGS, FOUNDATIONS WALLS, SLAB.

BRICK ON BRICK, GLASS AND METAL WINDOWS, PATIO / BALCONY DOORS, METAL ENTRANCE DOOR. **Exterior Walls:**

SHINGLE ROOFING ON WOOD DECK AND TRUSSES (PITCHED).

TOTAL MANAGEMENT

Structural Floor: WOOD DECK AND JOISTS.

Roofing:

Flooring: CONCRETE, WOOD, TILE.

Ceiling: DRYWALL.

Fire Safety: FIRE EXTINGUISHERS, SMOKE DETECTORS.

DRYWALL ON STUDS.

Partitions:

ELECTRICAL, PLUMBING, HEATING, AIR CONDITIONING (SPLIT SYSTEM). **Building Service Systems:** COVERED WALKWAYS AND PASSAGEWAYS, GUTTERS AND DOWNSPOUTS, PATIOS (WOOD ENCLOSURE), BALCONIES, STAIRS. Additional Features:

VALUATION CONCLUSIONS

COST OF REPRODUCTION NEW: \$3,435,000

EXCLUSIONS:

\$157,700

COST OF REPRODUCTION NEW LESS EXCLUSIONS: \$3,277,300



Long-term thinking. Everyday commitment.



FRONT



SIDE



BACK



PATIOS / BALCONIES

COURTYARD







Property Express

10/10/2022

VALUATION

Value Basis:

Valuation Number: ESTIMATE-0006864

Effective Date: 10/09/2022

Expiration Date: 10/09/2023

Estimate Expiration Date: 01/07/2023

Cost as of: 06/2022

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

Reconstruction

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 3 - Condominium - 27 Units

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium Story Height: 9 ft.

Construction Type: 100% Frame (ISO 1) Number of Stories: 2

Gross Floor Area: 21,736 sq.ft. Irregular None

Adjustment:

Construction Quality: 1.5 - Economy/Average

Year Built: 1956

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

Overhead and Profit: 20% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.

©CoreLogic. All rights reserved. CORELOGIC, the CoreLogic Logo, Commercial Express, and Commercial ExpressLync are the property of CoreLogic, Inc.



Property Express

Policy Number: ESTIMATE-0006864 10/10/2022

SUMMARY OF COSTS		Recons	struction Exc	lusion
SUPERSTRUCTURE				
Site Preparation				\$3,033
Foundations			\$77,491	\$54,790
Foundation Wall, Interior Foundations,	Slab On Ground			
Exterior		Ş	\$748,540	
Framing, Exterior Wall, Exterior Wall, S	Structural Floor, Roof			
Interior		Ş	\$785,540	
Floor Finish, Ceiling Finish, Partitions				
Mechanicals		\$1	,279,755	\$99,869
Heating, Cooling, Fire Protection, Plum	bing, Electrical, Elevators			
Built-ins		Ş	\$269,253	
SUBTOTAL RC		\$	3,160,580	\$157,69
ADDITIONS				
Building Items			\$116,7	48
Total Additions			\$116,748	
TOTAL RC Section 1		\$	33,277,328	\$157,6
OTAL RC BUILDING 3 Condominium - 2	?7 Units	\$	3,277,328	\$157,69
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
ATION TOTAL, Location 1	\$3,277,328	21,736	\$151	
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
UATION GRAND TOTAL	\$3,277,328	21,736	\$151	

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Property Express
EQUIPMENT REPORT

Policy Number: ESTIMATE-0006864 10/10/2022

VALUATION

Valuation Number:ESTIMATE-0006864Effective Date:10/09/2022Value Basis:ReconstructionExpiration Date:10/09/2023

Estimate Expiration Date: 01/07/2023 Cost as of: 06/2022

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

Equipment: Building items and site improvements

	Replacement	Depreciated
Building 3, Section 1		
Building Items		
Balconies		
(1) Balconies, Wood frame	\$116,748	\$116,748
LOCATION 1 - River Oaks Townhomes Owners Association TOTAL	\$116,748	\$116,748
TOTAL	\$116,748	\$116,748

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Property Express SUMMARY REPORT

Policy Number: ESTIMATE-0006864 10/10/2022

VALUATION

Valuation Number: ESTIMATE-0006864 Effective Date: 10/09/2022 Value Basis: Reconstruction **Expiration Date:** 10/09/2023 Estimate Expiration Date: 01/07/2023

> Cost as of: 06/2022

BUSINESS

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

LOCATION 1 - River Oaks Townhomes Owners Association

River Oaks Townhomes Owners Association

4040 San Felipe Street

Houston, TX 77027 USA

BUILDING 3: SUPERSTRUCTURE	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
Section 1 100% Condominium	\$3,160,580	21,736	\$145	
Section Totals	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
Section 1 100% Condominium	\$3,160,580	21,736	\$145	
Total Additions:	\$116,748			
BUILDING TOTAL, Building 3	\$3,277,328	21,736	\$151	
BUILDING INSURANCE SUMMARY				
Total Insured Amount	\$0			
Percent of Insurance to Value	0%			
100% Co-insurance Requirement	\$3,277,328			\$3,277,328
-100% Variance	(\$3,277,328)			
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
LOCATION TOTAL, Location 1	\$3,277,328	21,736	\$151	
	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
VALUATION GRAND TOTAL	\$3,277,328	21,736	\$151	

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.

	OTHER INSURABLE STRUCTURES	COST OF REPRODUCTION NEW
STRUCTURE:	ENTRANCE MONUMENT (2)	\$20,000
DESCRIPTION:	METAL WITH LETTERING AND LIGHTS.	
STRUCTURE:	PERIMETER FENCE	\$50,000
DESCRIPTION:	BRICK COLUMNS WITH METAL FENCE.	

\$70,000

800 SQ. FT., MASONRY WITH CERAMIC TILE TRIM, LADDER, STAIRS AND FILTER EQUIPMENT.

SWIMMING POOL

STRUCTURE: DESCRIPTION:







ENTRANCE MONUMENT

	OTHER INSURABLE STRUCTURES	COST OF REPRODUCTION NEW
STRUCTURE:	GUARD HOUSE	\$20,000
DESCRIPTION:	ONE (1) STORY, 8 X 14, BRICK ON FRAME WITH SHINGLE ROOF, GLASS AND METAL DOORS, TILE FLOOR, ELECTRICAL, PLUMBING, AND WALL UNIT AIR CONDITIONING SERVICES.	
STRUCTURE:	SECURITY GATE	\$6,000

SINGLE ARM WITH CONTROLLER.

DESCRIPTION:

WOOD FRAME, SHINGLE ROOF.

DESCRIPTION: STRUCTURE:

GAZEBO

\$18,000



GUARD HOUSE / SECURITY GATE



GAZEBO



STRIICH IRE.	OTHER INSURABLE STRUCTURES	COST OF REPRODUCTION NEW
DESCRIPTION:	4 CAR, METAL FRAME, METAL ROOF.	ברים היים היים היים היים היים היים היים ה
STRUCTURE:	CARPORT #2	\$20,000
DESCRIPTION:	5 CAR, METAL FRAME, METAL ROOF.	
STRUCTURE:	CARPORT #3	\$30,000

8 CAR, METAL FRAME, METAL ROOF.

DESCRIPTION:





CARPORT #3



CARPORT #1

	OTHER INSURABLE STRUCTURES	COST OF REPRODUCTION NEW
STRUCTURE:	CARPORT #4	\$60,000
DESCRIPTION:	15 CAR, METAL FRAME, METAL ROOF.	
STRUCTURE:	CARPORT #5	\$120,000
DESCRIPTION:	23 CAR WITH CENTER STORAGE BUILDING / TRASH. METAL FRAME. METAL ROOF.	

\$40,000

10 CAR, METAL FRAME, METAL ROOF.

DESCRIPTION: STRUCTURE:

CARPORT #6







CARPORT #1

COST OF REPRODUCTION NEW	\$110,000	
OTHER INSURABLE STRUCTURES	SWIMMING POOL #2	1,512 SQ. FT., MASONRY CONSTRUCTION WITH CERAMIC TILE TRIM, LADDER, STAIRS, FILTER EQUIPMENT.
	STRUCTURE:	DESCRIPTION:

WOOD PERIMETER WALL

STRUCTURE:

\$75,000



WOOD PERIMETER WALL

SWIMMING POOL #2



OTHER INSURABLE STRUCTURES

COST OF REPRODUCTION NEW

\$675,000


CARPORT / STORAGE / LAUNDRY / MAINTENANCE STRUCTURE: TWO (2) STORY WITH LOWER LEVEL CARPORT, WITH BLOCK BACK WALL, UPPER LEVEL STORAGE BUILDING WITH WOOD

WALLS AND FLOORS, SHINGLE ROOFING WITH ELECTRICAL SERVICE. 18 X 956 CARETAKER'S END UNIT - 2 STORY 760 SQ. FT.

TOTAL 17,968 SQ. FT.

DESCRIPTION:





CARPORT





Long-term thinking. Everyday commitment.

OTHER INSURABLE STRUCTURES

CARPORT / STORAGE / LAUNDRY / MAINTENANCE - ADDITIONAL PICTURES

STRUCTURE:



STORAGE

