

4015 Brynmawr Drive, Richmond, TX 77406

Updates and Features

Exterior

- French Drains installed to the right side of the property 2022
- Gutter guards & Screens installed 2022
- Lightning Rod system on the roof replaced 2023
- Property features 2.5 car garage; additional bay can be used for storage, golf cart/mower parking
- Wrought iron fencing around pool repaired 2022
- Gutters and decking on upper balcony replaced 2021
- Siding on back of home replaced with Hardie board 2021

Interior

- Replaced kitchen electric cooktop 2024
- New faucet installed in half bath near primary bedroom 2024
- Chimney inspections and cleanings were performed 2024
- Both bathrooms downstairs fully remodeled 2023
- New carpet installed downstairs 2023
- New paint in guest bedroom
- New ceiling fan installed in guest bedroom
- French patio doors installed downstairs 2024
- HALO Security System installed
- (2) Spacious Laundry Rooms Featured In Home; (1) Upstairs, (1) Downstairs with Gas & Electric options

- Bonus/Secret Storage Room located in downstairs laundry room
- Wine Room located on first floor
- (3) Living Areas: Den Space Downstairs; Formal Living & Family Room Upstairs
- (2) Wet Bars: (1) Upstairs, (1) Downstairs
- Windows/Exterior doors replaced in laundry, kitchen, and master bedroom
 2021
- Installed (3) WiFi thermostats 2022

Pool/Backyard

- Pool pump replacement 2024
- New Pool vacuum 2024
- Pool Spa Heater replaced 2021

Gardening & Landscaping

- Fruit Trees Peach, Banana, Apple
- Vegetable Garden
- Herb Garden

Mechanicals

- 40-gallon gas hot water heater replaced 2021
- Trane Furnace installed 2022
- Water Softener replaced 2022
- Replaced master and sub-panel fuse boxes 2021