

# Property Disclosure

Case Number: 512-036782

Insurability: Uninsurable (UI)

Property Address: 705 W Norris St  
El Campo, TX 77437

## MPR Property Repairs

Repair / Replace Roof

Repair / Replace Drywall and Ceilings

Repair / Replace Cracked Slab

Repair / Replace Electrical System

Repair / Replace Exterior Trim, Soffit and Fascia

Repair / Replace HVAC System ( Missing Components )

Repair / Replace Plumbing System (Missing Components)

Repair / Replace Water Heater

Repair / Replace Flooring - Exposed Sub-floor

## Property Disclosures

Property does not have a Homeowners Association (HOA).

Property built before 1978 - Lead Based Paint addendum required

Property has a Shed/ Storage Building

Water can NOT be activated for Purchaser Inspection per HUD Field Service Manager

Electricity can NOT be activated for Purchaser Inspection per HUD Field Service Manager

Property is listed as Uninsurable: Estimated MPR Repairs Exceed \$10,000

## General Disclosures

**All HUD Homes are sold in their AS-IS condition:** HUD will not make any repairs nor allow the purchaser to complete any repairs prior to closing. **FOR YOUR PROTECTION GET A HOME INSPECTION**

Permission to activate utilities for purposes of the home inspection may be requested from the HUD Field Service Manager after the HUD-9548 sales contract is executed by the seller. Fees for activation may apply.

Properties being purchased with FHA insured financing will require a termite inspection and possible treatment. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or treatment has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection and treatment prior to closing.

Properties built prior to 1978 and being purchased with FHA insured financing will require a lead-based paint inspection and possible stabilization. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or stabilization has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection ,stabilization and clearance letter prior to closing.

*This information is accurate based on the data available at the time of listing, and is deemed reliable but not guaranteed. All information should be independently verified.*