This property <u>IS NOT</u> located in LEGEND LEGEND

I.E.—UILITY EASEMENT

A.E.—AERIAL EASEMENT

B.L.—BUILDING LINE

W.L.E.—WATER LINE EASEMENT

S.S.E.—SANITARY SEWER EASEMENT

SIM. SEW. ESMIT.—STORM SEWER EASEMENT

D.E.—DRAINAGE EASEMENT

— // — WOOD FENCE

— 0 — CHAIN LINK FENCE

— X — BARBED WIRE FENCE

— II — IRON FENCE the 100 year flood plain & is SCALE: 1"= 30' in insurance rate map zone X, as per map __48201C/0245K dated _____4-20-00 ROADWAY EASEMENT FND 1/2" I.R. 90.00 N21°52'00"W 16 FND 1/2" I.R. HILDEBRANDT, DORIS LOT 563 TAX ID NO. 0420860000307 LOT 562 CONC ONE STORY BRICK & FRAME HOUSE \$86.00'06"W STORY 67.92 1/2 1.R · 53'25"E 3 U.E. LOT 564 L=47.00 R=75.00 Poul Frank R.] Maralyn & Reid SURREYWEST LANE 5 0' R. O. W. I, MICHAEL D. MORTON, A REGISTERED PROFESSIONAL LAND I, MICHAEL D. MORTION, A REDISTRED PROFESSIONAL LAND SURVEYOR IN THE STATE OF TEMAS, DO HEREBY CERTIFY THAT THE PLAT HEREON CORRECTLY REPRESENTS THE RESULTS OF AN ACTUAL SURVEY MADE ON THE GROUND UNDER MY DIRECTION AND THAT THERE ARE NO ENCROACHMENTS EXCEPT AS SHOWN. NOTES: MICHAEL D. MORTON 1. BASIS FOR BEARINGS: ASSUMED AS PLATTED 2. DISTANCES SHOWN ARE GROUND DISTANCES 3. ALL ABSTRACTING DONE BY TITLE COMPANY 4. 35' BUILDING LINE IN FRONT (SOUTH) OF SUBJECT PROPERTY, 7' U.E. BACK (NORTH) SIDE OF SUBJECT PROPERTY, 3' U.E. AND 4' OVERHEAD EASEMENT ON BOTH SIDES (EAST AND WEST) OF SUBJECT PROPERTY IN BACK (NORTH) SIDE OF PROPERTY MICHAEL D. MORTON - R.P.L.S NO.3686 SUBDIVISION LOT(S) 16 563 TERRANDVA WEST 3 RECORDATION STATE VOL. 311 PG. 143 H.C.M.R HARRIS LENDER ZIP CODE CLARITY MORTGAGE SERVICES 17835 SURREYWEST LANE SPRING 77092 PURCHASER TILE COMPANY G.F. NO. DEIN AND KIM B. DEIN NETCO H0U49394 FIELDED BY: JOB NO. BUD 01-29-02 ARROW SURVEYING 02-01-149 DRAWN BY: LR/CG 01-30-02 P.O. BOX 410 PEARLAND, TEXAS 77588 CHECKED BY: (281) 412-2294 FAX(281) 412-2314 REVISION: MM 02-04-02