

### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS





### 2020

## KITCHEN UPDATED W/

- GRANITE COUNTERTOPS
- BREAKFAST BAR
- SUBWAY TILE BACKSPLASH
- GAS COOKTOP & NEW GAS LINE
- KITCHENAID STAINLESS STEEL APPLIANCE SUITE:
  - REFRIGERATOR
  - DOUBLE-OVENS
  - GAS COOKTOP
  - WINE FRIDGE
- STAINLESS STEEL UNDERMOUNT SINK
- STAINLESS STEEL FAUCET
- DESIGNER BATHTUB IN PRIMARY BATHROOM

# 2018

- HARDI PLANK CEMENT-BOARD SIDING
- ENERGY-EFFICIENT DOUBLE-PANE WINDOWS

## 2016

• ELECTRICAL PANEL UPGRADE TO 220



- ELECTRICAL WIRING AND OUTLETS
- PLUMBING TO PRIMARY BATHROOM
- HARDWOOD FLOORING
- CARPET
- BLOWN CELLULOSE INSULATION AS FOLLOWS:
  - -Cellulose does not shrink over time or hold moisture which allows the original thickness and R value to be preserved, wich is R38.
  - -The same Cellulose material is blown in the downstairs walls and was shaved off at the studs before new sheetrock, so walls are insulated above average.
  - -Attic walls for the upstairs are cotton batts, not fiberglass, with an R value of R19.
  - -Upstairs Gables are standard Fiberglass batts, installed from exterior when siding was replaced.
- POOL EQUIPMENT EXCEPT PUMP
- CONCRETE SIDEWALK TO MUDROOM/UTILITY ROOM
- CONCRETE EXPANSION JOINTS
- SPACEMAN CUSTOM CLOSETS IN PRIMARY BEDROOM
- LANDSCAPE BORDERS

