

MBG
 2 hrs 4:00
 11/12
 7/12
 506 12/12
 8:00

ATLAS

FOUNDATION REPAIR

713.641.4844

DATE: 11-08-03 KEY MAP# 539 X

NAME: Mary Kavan

ADDRESS: 5121 Valley View

PH: 1-471 3739 WK PH: 1 334 9721

OTHER: 77571


STRUCTURE DESCRIPTION

Siding: Front B+F Back B Sides B+F

Stories: 1 1/2 2 Other _____

Foundation: Slab PT B&B P/B

Beam Depth _____ Lot Type _____



- Price includes:
1. Mud pumping voids under slab after leveling
 2. Hydro static sewer line + str
 3. Insurance assistance
 4. Permits
 5. Financing
 6. Re-mortar exposed re-bar on front of garage

4345⁰⁰

TOTAL NUMBER OF PILINGS

INTERIOR _____ EXTERIOR //

LEGEND:	
EXTERIOR PILINGS	⊙
INTERIOR PILINGS	●
EXISTING PIERS/PILINGS	□
EXISTING BELL BOTTOM PIERS	●
FENCES	_____
DECKS	_____
PEAGRAVEL	_____
1 INCH = 10 FEET	